GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/SZ/2018/ 2530

Dated: 14/11/18

FIRE SAFETY CERTIFICATE

Certified that M/s. Red Apple Banquet located at A- 21/19, Naraina Industrial Area, Phase-II, New Delhi- 110028, comprised of basement, ground plus three upper floors, using basement as storage, ground as banquet hall, first & second floor as personal use as hall, third floor use as kitchen & office owned & occupied by the management of M/s Red Apple Banquet, was granted FSC by this department vide letter No. F.6/DFS/MS/BNQT/2015/SZ/105 dated 21.01.2015 for **ground floor only**. The Building was re-inspected by the officer concerned of this department on 22.10.2018 in the presence of Mr. A. Kapoor, authorized signatory of M/s Red Apple Banquet and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises (**Ground Floor Only**) is fit for occupancy class Assembly (Group- D) with effect from ________ | 1 1 1 1 2 | ________ for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued -- 1-4-1-18--- at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to: -

1. The manager, M/s. Red Apple Banquet located at A- 21/19, Naraina Industrial Area, Phase- II, New Delhi- 110028.

Following Fire Safety Directives Must Be Adhered To:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT : Red Apple Banquets, A-21/19, Naraina Phase- II, New 1. Name & address of the building Delhi- 110028. 2. Type of Occupancy : Assembly 3. Type of Case : Renewal 4. Details of previous NOC : F.6/DFS/MS/BNQ/2015/SZ/105 dated 21.01.2015 5. Fire Safety directives letter No : N/A : 22.10.2018 6. Date of inspection : M.K. Chattopadhyay, DO(South West), 7. Name of the Inspecting Officers 8. Name and designation of officers : Sh. Gopal Buttan, Authorized Signatory from the building side : 1977-78 9. Year of Construction : Form 'J' dated 06.09.2018 10. Applicant's letter No. The said banquet hall is running on ground floor of a building comprised of basement, ground plus three upper floors.

Sr. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per directives letter dt. 21.01.2015	Provided at site	Remarks MR/NMR		
1	Access to building					
).	Road width	06 mts	Provided	MR		
	Gate width	4.5 mts	Directly accessible from the road	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	-	-	-		
	Upper Floors	02 nos.	02 nos.	B. hall at GF only		
	 Basements 	N/A	N/A	B. hall at GF only		
	b. Width of staircases			-		
	Upper Floors		1.25, 1.35 mts.	B. hall at GF only		
	• Basements		1.30, 1.50 mts.	B. hall at GF only		
	c. Protection of exits	-	-	-		
	• Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	e. No of continuous staircases to terrace		01	B. hall at GF only		
	g. Width of Corridor	N/A	N/A	B. hall at GF only		
	h. Door Size	2.0 mts	2.35, 2.35, 0.95 mts.	MR		
3	Compartmentation.			e e		
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	• Basements	30 a/c per hour	Exhaust fan provided	MR		
	Upper floors	12 a/c per hour	Natural ventilation	MR		

)	FIFE EXUNGUISHERS			The state of the s				
	Total numbers	12	Provided	MR				
	• Types	ABC & CO ₂ type	ABC & CO ₂ type	MR				
	IS marking	ISI marked	Provided	MR				
6	First-Aid Hose Reels.							
	Total numbers on each floor	01	Provided	MR				
	 Length of hose reel hose 	30 m	Provided	MR				
	Nozzle diameter	5 mm	Provided	MR				
		4						
7	Automatic fire detection and alarmin	N/A	Smoke					
	Type of detectors	N/A	Provided at GF					
	Location of Main Panel	N/A	N/A	N/A				
	Location of Repeater Panel	Required	D.G set 180 KVA	MR				
	Alternate source of powerHooters' Location	N/A	N/A	N/A				
8		Required	Provided	MR				
	MOEFA	Required	Provided	MR				
9	Public Address System.	Required		17110				
10	Automatic Sprinkler System.	Dagwingd	Provided	MR				
	Basement	Required	Flovided					
	Upper Floor / Ground Floor	N/A	N/A	N/A				
	Sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants							
	Size of riser/down-comer	100 mm	Provided	MR				
	Number of hydrants per floor	01 No.	Provided	MR				
	Hose Box	01 No.		MD				
		01110.	Provided	MR				
12	Yard Hydrants.							
	Total number of hydrants	01 No.	Provided	MR				
	Hose Box	01 No.	Provided	MR				
13	Pumping Arrangements.							
	Ground Level							
	Discharge of main Pump	N/A	N/A	N/A				
	> Head of Main pump	N/A		N/A				
	Number of main pumps	N/A		N/A				
	> Jockey Pump out put	N/A		N/A N/A				
	Jockey pump head	N/A N/A		N/A N/A				
	Standby Pump out putStandby Pump Head	N/A N/A		N/A				
	Auto Starting/ Manual stop			N/A				
	Pump House Access	N/A		N/A				
	Terrace level							
	> Discharge of pump	900 LI	PM Provided	MR				
	➤ Head of the pump	30 m	ts Provided	MR				
	> Power Supply	N/A	N/A	N/A				
	Auto Starting of pump	N/A	N/A	N/A				

	•	Underground tank capacity	N/A	N/A	N/A			
-	>	Draw-off connection	N/A	N/A	N/A			
	. >	Fire service inlet	N/A	Provided				
	>	Access to tank	N/A	N/A	N/A			
	•	Overhead Tank capacity	15000 lts	15000 lts	MR			
15	Exit S	ignage.	Required	Provided	MR			
16	6 Provision of Lifts. Provided but not commissioned							
	•	Pressurization of Lift Shaft	N/A	N/A	N/A			
	•	Pressurization of Lift lobby	N/A	N/A	N/A			
	•	Communication In lift Car	Required	Provided	MR			
	•	Fireman's Grounding Switch	Required	Provided	MR			
	•	Lift Signage	Required	Provided	MR			
17	Stand	by power supply	Required	Provided D.G set	MR			
18	Refuge Area.							
	>	Total Area	N/A	N/A	N/A			
	>	Location	N/A	N/A	N/A			
19	Fire Control Room							
		Detector System Panel	N/A	N/A	N/A			
		Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Batter backup	N/A	N/A	N/A			
		Building Floor Plans	N/A	N/A	N/A			
20	1	al Fire Protection Systems for etion of special Risks, if any:	Required	02 ABC type fire extinguishers found Provided near elect. panel	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/BNQ/2015/SZ/105 dated 21.01.2015, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please

DCFO (SZ)

(M.K. CHATTOPADHYAY)
Divisional Officer, (South West)

25/10/18 S

derif of p

FTD