GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2019/SZ

Dated:

18/01/19

FIRE SAFETY CERTIFICATE

Certified that the **Laxmi Model School,** 12 Block, Santoshi Mata Mandir (Near Community Hall), Tilak Nagar, New Delhi-110018, owned/occupied by Laxmi Devi Educational & Charitable Society was issued FSC for Ground floor only by this department vide letter no. F.6/DFS/MS/2012/School/266 dated 30.01.2012. The school was re-inspected by the officer concerned of this department on 26.12.2018 in the presence of Sh. Sunil Kumar (Manager) and found that Laxmi Model School comprised of ground floor only of a two storied building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (**Ground floor only**) is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on 18/01/19 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager, Laxmi Model School, 12 Block, Santoshi Mata Mandir (Near Community Hall), Tilak Nagar, New Delhi-110018
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

1. Name & address of the building: Laxmi Model School, 12 Block, Santoshi Mata Mandir (Near Community Hall), Tilak Nagar, New Delhi-110018 2. Type of Occupancy Educational Type of Case 3. Renewal 4. Details of Previous NOC F.6/DFS/MS/2012/School/266 dated 30.01.2012 (For GF only) 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 26.12.2018 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side : Sh. Sunil Kumar (Manager) 9. Year of Construction Before 2000 (GF) & Before 2018 (FF) 10. Applicant's letter No. : Form "J" dated 06.12.2018 S. No. Minimum Standards on fire prevention and Requirements as Provided at Remarks per FSC dt. fire safety U/R 33 site MR/NMR 30.01.2012 1. Access to building Road width Accessible 06 mtrs 09 mtrs MR 4.5 mtrs Directly accessible Gate width MR N/A from road Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors N/A N/A N/A **Basements** N/A N/A N/A b. Width of staircases Upper Floor N/A N/A N/A Basements N/A N/A N/A c. Protection of exits Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace Width of Corridor N/A N/A N/A 100 cms 83/105 cms on GF MR, being old Class Room Door Size case 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. **Basements** N/A N/A N/A Natural ventilation Upper floors Required M/R provided 5. Fire Extinguishers Total numbers 02 no's Provided MR ABC/CO₂ type **Types** Provided MR IS marking Provided MR ISI marked 6. First-Aid Hose Reels Total numbers on each floor N/A N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter N/A N/A

comprised of ground plus one upper moor our sensor is fulfilling at ground moor only.

INSPECTION REPORT

. A	Automatic fire detection and alarming system	president de la companya della companya de la companya de la companya della compa	The second second	
13	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
. N	MOEFA	N/A	N/A	N/A
	Public Address System	N/A	N/A	N/A
	Automatic Sprinkler System			27/4
0. 1	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
1. I	Internal Hydrants	1		21/4
-	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants			
.20	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2	Pumping Arrangements		< 2	ti .
3.	1 Y 1			
	Ground LevelDischarge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps		N/A	N/A
	> Jockey Pump out put	N/A		N/A
	Jockey pump head	N/A	N/A	CONTROL OF THE PARTY OF THE PAR
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	- N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	IVA	10.11	
	Terrace level	77/4	N/A	N/A
	Discharge of pump	N/A		N/A
	Head of the pump	N/A	N/A N/A	N/A
	Power Supply	N/A	2	N/A
	Auto Starting of pump	N/A	N/A	14/71
		•	1 1	
	0 0 0 1 1			
14.	Captive Water Storage for fire fighting	N/A	N/A	N/A
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connectionFire service inlet		N/A	N/A
	> Access to tank	N/A		N/A
	Overhead Tank capacity	N/A	N/A	
	Overneau Tank capacity	N/A	N/A	N/A N/A
		N/A	N/A	N/A
15.	Exit Signage.			
				No Lift
16.	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft	,		N/A
	Pressurization of Lift lobby	N/A	N/A	N/A N/A
	Communication In lift Car	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
			N/A	N/A
		N/A	IN/A	14/11
17.	Standby power supply			
10	Defense Avec			
18.	Refuge Area. > Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A

الم الم

9.	Fire Control Room					
	Q Paral	N/A	N/A	N/A		
	Detector System Panel Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
	D. A. Gar System for Protection of	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:		•			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/2012/School/266 dated 30.01.2012 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the undertaking submitted by the Manager (placed at C-18) that we use only ten rooms on ground floor and we do not use the two rooms situated on first floor. So please issue Fire Safety Certificate.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Mille

309 20 KW 2 11 12015 4/c A ST

4

Last

cto de miscel

FIN.

F.T. letter is putup for signature of

CIEX