FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/MS/DFS/2020/ 21

Dated: 15/01/2020

FIRE SAFETY CERTIFICATE

Certified that the M/s Fiery Grills (A unit of WOW Hotels Pvt Ltd) located at 306, 3rd Floor,

D mall, Netaji Subash Place, Pitampura New Delhi-110034 in a building comprised of Three

Basement +Ground + 12 Upper Floor owned/ occupied by M/s Fiery Grills (A unit of WOW Hotels

Pvt Ltd) have complied with the fire prevention and fire safety requirements in accordance with rule

33 of the Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on

28/11/2019 in the presence of Sh. Deepak (Manger) and found that the said building that the

premises is fit for occupancy class "Assembly" Group D (3rd Floor Only) with effect from

15/01/2020 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the

Delhi Fire Service Rules, 2010.

Issued on ... 15. at New Delhi by.

Atul Garg)
Director

Delhi Fire Service

Copy to:

1. The Addl. Commissioner of Police, Licensing unit First Floor, Police Station, Defence Colony, New Delhi.

2. M/s Fiery Grills (A unit of WOW Hotels Pvt Ltd) located at 306, 3rd Floor, D mall, Netaji Subash Place, Pitampura New Delhi-110034.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in...

INSPECTION REPORT

1. Name & address of the building: M/s Fiery Grills (A unit of WOW Hotels Pvt Ltd) located at 306, 3rd Floor, D mall, Netaji Subash Place, Pitampura New Delhi-110034

2. Type of Occupancy

: Assembly

3. Type of Case

: New

4. Details of previous NOC: F6/DFS/MS/WZ/2018/2575 Dated -29/11/2018 (Issued to mall)

5. Fire Safety directives Letter No.: nill

6. Date of inspection

: 28/11/2019

7. Name of the Inspecting Officer: ADO (WP)

8. Name and designation of Officer

from the building side : Sh. Deepak (Manager)

9. Year of Construction

: 2010

10. Applicant's letter No. : Nil Dated 13/11/2019

	S	M: · · · · · · ·	3	v						
		Minimum standards on fire	BBI			Provided at	Ren	Remarks		
	No	prevention and fire safety U/R 33	Req	Requirements		site	MR/NMR			
	1.						0.0			
	1.	Access of building								
				NA NA		rovided		MR .		
	2					4		NA		
				NA		per controlled	1	NA		
		N. 1 111 m	driwing							
-	2.	2. Number, width, Type & Arrangements of exits								
		a. Number of staircasesUpper floorsBasements			1					
				2		04 Provided	MR			
				NA		NA	NA			
		b. Width of staircases								
		 Upper floors Basements Protection of exits Fire check door 		1.5m		4x1.5m		MR		
				NA	NA		NA			
				NA Provi		Provided	The Control of the Co	NA		
		 Pressurization 				Provided		NA		
		d. No of continuous staircase		o NA		NA		NA		
		terrace	1421							
		e. Width Of Corridor f. Door Size		2m		Provided		MR		
				2m & 1m		Provided		MR		
	3.	Compartmentation		*			11111			
		• Fire check door		NA		NA		NA		
		 Sealing of electrical shafts 	NA		NA		NA			
		 Fire Rating of shaft door 		NA		NA		NA		
		Water Curtain	NA		NA		NA NA			
		• Fire Dampers	NA		NA		NA NA			
						1 12 1		INA		

4.	Smoke managements System		12					
	Basements	NA		NA		NA		
	 Upper floors 		12 a/c per		Provided		MR	
	<u> </u>		hour			T =	3,0	
5.	Fire Extinguishers			у.				
	 Total numbers 		02 nos. each		Provided		MR	
	• Types		type		Provided		MR	
	 IS marking 	8	DCP, CO2 & WCO2 ISI marked					
					Provided		MR	
6.	First – Aid Hose Reels		common with the mall					
					D 111		1.00	
	• Total numbers on each floor		1		Provided		MR	
	 Length of hose reel hose 		30 m		Provided		MR	
	Nozzle diameter		5 mm		Provided		MR	
7.	Automatic fire detection and alar	ming					10	
	 Type of detectors 			Provided		MR		
	 Location of Main Panel 	. :-:	Required		Provided (3F	MR	
	 Location of Repeater Pane 	el	el NA		NA	2	NA	
, ,	 Alternate source of power 	Required			Provided		MR	
	Hooters' Location	Required		08 55	Provided		MR	
8.	MOEFA		Required		Provided		MR	
9.	Public Address System		NA		Provided		MR	
10.	Automatic Sprinkler System							
	Basements		8	N	ΙA	NA	19	
	Upper Floor	Req	uired P		Provided MR			
					Provided MR		v 3	
	ceiling							
11.	Internal Hydrants: common with	the r	nall		×.	1		
	Size of riser/down- comer				Provided	MR		
	Number of hydrants per flo		oor 1		Provided MR		v	
	Hose Box		Required 1		Provided MR		5	
12.	Yard Hydrants	0.						
			NA NA		NA NA			
	Hose Box	NA		NA	NA			
13.	Pumping Arrangements: Commo	n wit	ith the mall					
15.	Ground Level							
	Discharge of main pump	NA		285		NA		
	➤ Head of main pump	NA	110			NA		
	Number of main pumps	NA			vided	NA		
	> Jockey pump out put	NA			lpm	NA		
	> Jockey pump head	NA	110			NA		
	> Standby Pump out put	NA	8		0 lpm	NA		
	Standby Pump Head	NA				NA		
	Auto Staring/Manual stopping	NA			vided NA			
	> Pump House Access NA		Desc		vided NIA			
	Terrace level		Prov		vided NA			
			1 5		111			
	0 1 1		10 m Prov		ovided MR ovided MR			
	> Head of the pump						18 N	
	> Power supply	Req	Distributed the second		vided		MR	
	11 3	-	uired Prov		ovided MI			
	> Auto starting of pump	Req	uired	Pro	vided	IVIIC		
		Req	uired	Pro	vided	IVIIC		
		Req	uired	Pro	vided	IVIK		

1 1.	captive water storage for the righting. Common with the man								
	•	Under ground tank capa	acity	NA	2,50,000 litr	es	NA		
	>	Draw off connection		NA	Provided		NA		
	>	Fire service inlet		NA	Provided		NA		
	Access to tank		NA	Provided		NA			
	•	Overhead Tank capacity		10,000	50, 000 Litres Prov		vided MR		
				litres					
15	Exit S	Signage		Required	Provided		MR		
16.	Provis	Provision of Lifts							
	>	Pressurization of Lift Sh	naft	NA	NA		NA		
	>	Pressurization of lift lob	urization of lift lobby		NA		NA		
	>	Communication in lift C	Car	NA	NA		NA		
	>	Fireman's Grounding SwitchLift Signage		NA	NA		NA .		
	>			NA	NA		NA		
17.	Standl	by power supply	supply		Provided MI		MR		
18.	Refug	e Area							
	>	Total area		NA	NA	NA	NA		
	>	Location		NA	NA	NA			
19.	Fire control room								
	>	Detector system panel	NA		NA	NA	NA		
	>	Flow Switch Panel	NA NA		NA	NA	A		
	>	PA System Panel			NA	NA	4		
	~	Battery backup	NA		NA	NA	A		
	>	Building Floor Plans	NA		NA	NA			
20.	Special Fire Protection NA Systems for Protection of			NA	NA				
				*	2.				
	special Risks, if any;			_				_ ^	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue noted serial numbers shortcomingsNil.....

- 1. M/s Fiery Grills (A unit of WOW Hotels Pvt Ltd) running at 306, 3rd Floor, D mall, Netaji Subash Place, Pitampura New Delhi-110034
- 2. The total covered area 197.43 m² (Approx)
- 3. As per part IV, NBC-2016, table no 4.3 under clause 4.4.2.1 the occupant load for dining area and restaurant is 1.8. Accordingly the number of seats come out to be 109.68 (197.43/1.8=109.68 say 110) for whole restaurant.
- 4. The total seating capacity comes out be 110

Note ;-As the restaurant is running since 2010 accordingly two exits of 2m & 1m width are required and the same has been provided.

Signature of the Inspecting Officer
Name Volume
Designation ADO(wp)

Signature of the Inspecting Officer

Name

Designation