GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2020/ 64

Dated: 12/03/2020

FIRE SAFETY CERTIFICATE

Certified that the M/s. Kadhai Tadka Restaurant (A unit of Bharat Fortune Resorts Pvt. Ltd.) running at Ground and First Floor of a building comprised of basement, ground plus three upper floors at R-549, Shankar Road, New Rajinder Nagar, New Delhi-110060, was granted FSC vide letter No. F.6/DFS/MS/EH/2016/SZ/1191 dated 22.07.2016. The restaurant was re-inspected by the officer concerned of this department on 24/01/2020 in presence of Sh. Prakash, (Manager) and found that the owners have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class assembly (restaurant) at Ground and First Floor only with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 12/03/200 at New Delhi by.

(S.S. Tuli)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. Mrs. Saroj Uppal (Director), Kadai Tadka Restaurant, R-549, Shankar Road, New Rajinder Nagar, New Delhi- 110060.
- 2. The Deputy Health Officer, North Delhi Municipal Corporation, Karol Bagh Zone, Anand Parbat, New Delhi- 110005.
- 3. The Addl. Commissioner of Police (Lic), 1st Floor, Police Station Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing department shall always be permitted and
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

Name & address of the building

: M/s Kadhai Tadka Restaurant (A unit of Bharat Fortune Resorts Pvt. Ltd.), R-549, Shankar Road, New Rajinder

Nagar, New Delhi- 110060.

2. Type of Occupancy

: Assembly (Restaurant)

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/EH/2016/SZ/1191 dated 22.07.2016

5. Fire Safety directives letter No

: N/A

6. Date of inspection

: 24.01.2020

7. Name of the Inspecting Officers: Shri Rajbir Kharb, ADO(SRD)

8. Name and designation of officers

from the building side

: Sh. Prakash, (manager)

9. Year of Construction

: Before 2009

10. Applicant's letter No.

: nil dated nil

The said restaurant is running at ground and first floor of a building comprised of basement, ground plus three upper floors.

S. No.	Mir preve	nimum Standards on fire ntion and fire safety U/R 33	Requirement as per NBC/BBL/ Addl. Sect. (Home) Directives for Restaurants	Provided at site	Remarks MR/NMR
1	Access	to building			MD
1	•	Road width	06 mts	Provided	MR
	•	Gate width	4.5 mts	Directly accessible from the road	MR
	•	Width of internal road	N/A	N/A	N/A
?	Numh	er, Width, Type & Arrangem	ent of Exits		
2		nber of staircases	-	-	·
	a. Null	Upper Floors	02 Nos.	Provided	MR
		Basements	02 Nos.	Provided	MR
		Ith of staircases	_	_	7
	b. W10		02 Exits	1.30, 0.94 mts	MR being old case
	•	Upper Floors	02 Exits	1.21, 0.92 mts	MR being old case
	•	Basements	-	-	-
	c. Pro	tection of exits	N/A	N/A	N/A
	•	Fire check door	N/A	N/A	N/A
	•	Pressurization	01	01	MR
		of continuous staircases to terrace		1.26 mts	MR being old case
	_	dth of Corridor	Old case		MR being old case
	h. Do	or Size	Old case	1.12, 0.88 mts	Wile being old east
3	Com	partmentation.			77/4
	•	Fire check door	N/A	N/A	N/A
		Sealing of electrical shafts	N/A	N/A	N/A
		Ein Dating of shoft door	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
	•	E' D	N/A	N/A	N/A
4	Smo	ke Management System.			1.1
7	Sino	The sale managery	30 a/c per hour	Exhaust fan provid	
		TI Garage Pagtourent GF		Exhaust fan provid	ded MR
		- PP	C		

5	Fire Extinguishers			**			
	Total numbers	12	Provided	MR			
	• Types	CO ₂ , ABC type	Provided	MT			
	IS marking	ISI marked	Provided	MR			
6	First-Aid Hose Reels.						
	Total numbers on G. floor (Rest.)	01	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7	140zzie diameter						
7	Automatic fire detection and alarming	N/A	N/A	N/A			
	Type of detectorsLocation of Main Panel			N/A			
74	Location of Nam Fane Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
		N/A	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Tiovided	IVIK			
10	Automatic Sprinkler System.		Provided	MD			
	Basement	Required	Provided	MR			
-	• Entire Restaurant	Required		MR N/A			
	Sprinkler above false ceiling	N/A	N/A	IN/A			
11	Internal Hydrants	100	D : -: 1- 1	MR			
	Size of riser/down-comer Note that a floor floor Note that a flore Note that a floor Not	100 mm	Provided	MR			
	Number of hydrants per floorHose Box	01 No.	Provided Provided	MR			
10		01 100.	Tiovided	IVIIC			
12	Yard Hydrants.	N/A	N/A	N/A			
	 Total number of hydrants 	NECT 1001 (2004)		N/A			
	Hose Box	N/A	N/A	IV/A			
13	Pumping Arrangements.						
	Ground Level			N/A			
	Discharge of main Pump	N/A	N/A				
	➤ Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	> Auto Starting/ Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
1	Terrace level			, 00			
-		450 LPM	Provided	MR			
	Discharge of pump	30 mts	Provided	MR			
	> Head of the pump	Required	Provided	MR			
388	> Power Supply	N/A	N/A	N/A			

	7		N/22					
.14	Captive Water Storage for fire fighting.							
9	•	Underground tank capacity	N/A	N/A	N/A			
	>	Draw-off connection	N/A	N/A	N/A			
	>	Fire service inlet	N/A	N/A	N/A			
V	>	Access to tank	N/A	N/A	N/A			
	•	Overhead Tank capacity	5000 lts	6,000 lts	MR being old case			
15	Exit S	Signage.	Required	Provided	MR			
16 Provision of Lifts.								
	•	Pressurization of Lift Shaft	N/A	N/A	N/A			
	•	Pressurization of Lift lobby	N/A	N/A	N/A			
	•	Communication In lift Car	N/A	N/A	N/A			
	•	Fireman's Grounding Switch	N/A	N/A	N/A			
	•	Lift Signage	N/A	N/A	N/A			
17	Stand	by power supply	Required	Provided	MR			
18	Refug	efuge Area.						
	>	Total Area	N/A	N/A	N/A			
	>	Location	N/A	N/A	N/A			
19	Fire Control Room							
		Detector System Panel	N/A	N/A	N/A			
		Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Battery backup	Required	Provided	MR			
		Building Floor Plans	N/A	N/A	N/A			
20	_	Il Fire Protection Systems for tion of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/EH/2016/SZ/1191 dated 22.07.2016, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

shortcomings pointed out by this department vide letter no. F.6/DFS/MS/EH/SZ/2019/4536 dated 26.07.2019 have been complied with by the restaurant management.

DFA is put up for approval & signature please.

Rajbir Kharb

Asstt. Div. Officer (S.Rd)

D.O. (SW)

Ish for form I & K as required andu valus.