GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2020 / W2/SCHOOL / 418

Dated: /2 //o /2020

FIRE SAFETY CERTIFICATE

Certified that the Joseph & Mary Public School located at Nathu Pura, Road, Burari, Delhi110084 comprised of Basement + Ground +02 upper floor owned/ occupied by the Joseph &
Mary Public School was granted FSC by this department vide letter F6/DFS/MS/2017/WZ/1402
dated 22.09.2017. The premises was re-inspected by the officer concerned of this department on
28.09.2020 in presence of Sh. Manoj Kr. Shrivastava and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class Group B Educational with effect from 12.10.2020 for a period of three years, subject to compliance of the conditions mentioned below:

(Dharampal Bhardwaj)
Dy.Chief Fire Officer
Ph:-011-23414250

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

2. The Principal, Joseph & Mary Public School, Nathu Pura, Road, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1 All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

: Joseph & Mary Public School, Nathu Pura, Road, Burari, Delhi-110084.

2. Type of Occupancy

:Educational

3. Type of Case

: Renewal (B+G+02 upper floors)

4. Details of previous NOC

:F6/DFS/MS/2017/WZ/1402 Dated: 22.09.2017

5. Fire Safety directives letter No

: Director of Education Circular letter no 262-362 dated 17.01.2005.

6. Date of inspection

: 28.09.2020

7. Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Sh. Manoj Kr. Shrivastava

9. Year of Construction

: 1997-2013

10. Applicant's letter No.

: Online E-Mail I.D dated:11/09/2020

Plot Area-	12140 sqm Covered Area- 9330 sqm,	Class rooms		lents2800 nos		
1 lot / freu	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part 4	Provided at site	Remarks MR/NMR		
1 A	access to building			s.		
	Road width	Accessible	Accessible	MR		
	Gate width	4.5m	04m	MR(old case)		
	Width of internal road	NA	NA	NA		
2 N	Number, Width, Type & Arrangement of Exits					
a	. Number of staircases			s*		
	Upper Floors	04	04	MR		
	Basements	02	02	MR		
b	. Width of staircases			1/0		
	Upper Floors	1.50m each	1.5m each	MR		
		1.50m	1.50m	MR		
	Basements			1		
*		NA	NA	NA .		
С	e. Protection of exits	NA	NA	NA		
	Fire check door	NA	NA	NA		
-	Pressurization	Required	Provided	MR		
c	d. No. of continuous staircases to terrace	1 m	1 m	MR		
e	e. Width of Corridor					
3	Compartmentation.					
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA •	NA	NA		

	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA NA	NA	
	Fire Dampers				
4	Smoke Management System.	NA	NA	NA	
	Basements	30 a/c per hour	Exhaust Fan	MR	
				MIK	
	Upper floors	12 a/c per hour	Natural Ventilated	MR	
5	Fire Extinguishers				
	Total numbers	32 nos	40nos	MR	
	• Types	ABC/CO2	ABC-40	MR	
	ISI marking	ISI Marked	Yes	MR	
6	First-Aid Hose Reels.	107,7141.104	1 03	IVIIC	
	Total numbers on each floor	03	03	MR	
	Length of hose reel hose	30m	-		
	Nozzle diameter		30m	MR	
7	Automatic fire detection and alarming syst	5mm	5mm	MR	
,	Type of detectors	em.	NA	NI A:	
	Location of Main Panel	NA	NA NA	NA NA	
		NA			
	Location of Repeater Panel		NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	NA	NA	NA	
9	Public Address System.	NA	NA	NA	
10	Automatic Sprinkler System.				
	Basement	Required	Provided	MR	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants				
	Size of riser/down-comer	NA	NA	NA	
	Number of hydrants per floor	NA	NA	NA	
	Hose Box	NA	NA	NA	
12	Yard Hydrants.				
	Total number of hydrants	NA	NA	NA	
	Hose Box				
	- 11036 DUA	NA	NA	NA	
13	Pumping Arrangements.				



	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump			
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual stopping Pump House Access	N/A	N/A	N/A
	Pump House AccessTerrace level	N/A	N/A	N/A
		900 lpm	000.1	
	Discharge of pump	•	900 lpm	MR
	► Head of the pump	40m	40m	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
4	Captive Water Storage for fire fighting.		· ·	
	Underground tank capacity	NA	NA	NA
	Draw-off connection	NA	NA	NA.
	Fire service inlet	NA	NA	NA NA
	Access to tank	NA	NA	NA NA
	 Overhead Tank capacity 	15000 ltrs		
5	Exit Signage.		15000 ltrs	MR
,	Provision of Lifts.	Required	Provided	MR
	Pressurization of Lift Shaft	N/A		
		N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A		
	Standby power supply	N/A N/A	N/A	N/A
	Refuge Area.	IN/A	N/A	N/A
	Total Area	N/A	Nich	
	Location		N/A	N/A
	Fire Control Room	N/A	N/A	N/A
	THE CONTROLL		4	
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
			0 co 4 8	11/7



	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 1402 dated 22.09.2017

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation: - ADO/RN

Change A' of DFA in conformity with point No.5 above the impection table at N/20.

ADO

(RN) Necessary change done in OFA Pl

(My)

Dycholws I light on

paroj Ry for your signature p1. My 36/16/20

Dyefo(w2