

228

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No.F6/DFS/MS/SZ/ 2021/05

Date: 05/01/2021

To,

The Principal,
Govt. Co-Ed. Sr. Sec. School,
SPS Block, Jaffarpur Kalan,
New Delhi-110073

Subject: : Regarding Issuance of Fire Safety Certificate in respect of Govt. Co-Ed. Sr. Sec. School, SPS Block, Jaffarpur Kalan, New Delhi-110073.

Sir,


Please refer to your letter no-. JPK/2020/331 dated 12/11/2020 on the subject captioned above. In this connection it is to inform you that the premises was visited by officers concerned of this department on 15/12/2020 and observed that the shortcomings communicated vide this office letter no. F6/DFS/MS/School/2020/SZ/606 dated 01/09/2020 (Copy enclosed) are still not complied.

You are requested to comply the shortcomings under intimation to this department for further consideration in the matter

In view of the above FSC from fire safety point of view cannot be considered at this stage.


Yours faithfully,

Enclose :- As above


(Sunil Choudhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:

1. Directorate of Education Old Secretariat Delhi – 110054


3/2/2020

C/22

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ/606

Dated: 01/09/2020

To,

The Principal,
Govt. Co-Ed. Sr. Sec. School,
SPS Block, Jaffarpur Kalan, New Delhi-110073

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Co-Ed. Sr. Sec. School, SPS Block, Jaffarpur Kalan, New Delhi-110073.

Sir,

This has reference to your Letter No. JPK/2020/106 dated 16.07.2020 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 14.08.2020 to see the compliance of the requisite fire safety measures. Sh. R.N. Shah (Estate Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of three blocks namely Block-A, Block-B & MP hall block. Block-A & Block-B having ground plus three upper floors and MP hall block is having ground floor only. The upper floors of Block-A are served by two staircases having width 173 cms each and the upper floors of Block-B are served by single staircase having width 173 cms. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The main gate having width 4.5 mtrs is provided but way to school building is obstructed, therefore either obstruction from the main gate is to be cleared or width of adjoining gate to school building is to be increased upto 4.5 mtrs.
2. Door width is 170 cms (07 no.'s) against required 200 cms (04 no.'s) in MP Hall.
3. First aid hose reel provided but not functional in Block-A & Block-B.
4. Hose reel system not provided in MP Hall.
5. Fire pumps having capacity 450 LPM are provided in each block but not functional on automatic mode.
6. Fire pump of 450 LPM not provided in MP Hall.
7. Overhead water storage tank of 5,000 ltrs. capacity not provided in MP Hall.
8. Illuminated exit signs are not provided in MP Hall.

You are advised to rectify the above-mentioned shortcomings and apply in Form "J" & Form "K" for Block-A & Block-B and apply in Form "I" (for MP Hall) for taking further action as necessary for renewal of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054
2. The Assistant Engineer (E),
Education (Maint.), Sub-Divn. M-I-I,
PWD, ITI Campus, Pusa, New Delhi-110012

de
E