GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2021/ND2/72

Dated: 05 02 2021

FIRE SAFETY CERTIFICATE

Certified that the King Palace Guest House located at 1955/41, Naiwalan, S.K. Dass Road, Karol Bagh, New Delhi comprised of Ground floor (01 office+ reception), 1st floor to 3rd floor (05 guest rooms at each floor) and terrace floor (staff rooms), total 15 guest earlier granted **FSC** by this department No.F6/DFS/MS/GH/2017/NDZ/286 dated 23.02.18. The premises was re-inspected by the officer concerned of this department on 01/02/21 in the presence of Sh. Mahander (Manager) and found that the said guest house building comprises of basement(other property), ground & three upper and ½ terrace floor having staff rooms not in use as per affidavit submitted by applicant dated 07.03.2020. The said guest house has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (01 office+ reception), 1st floor to 3rd floor (05 guest rooms at each floor) total -15 guest rooms only with effect from -05-02-202-1. for period of three years in accordance with rule 36 unless renewed under rule 37' or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 05 02 2021 at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

0×10mm

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. :- ID. No. 2020123009282 dated 30.12.2020
- The Manager,
 King Palace Guest House at 1955/41, Naiwalan, S.K. Dass Road, Karol Bagh,
 New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other condition mentioned in the gazette notification dated 27.05.2019 & clarification issued dated on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. The owner shall not use any floor above third floor for any purpose and same shall remain closed/locked

1. Name & address of the building King Palace Guest House at 1955/41, Naiwalan, S.K. Dass Road, Karol Bagh, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1 Gr. + 03 Upper floors (total 15 Guest rooms) Ground floor (Reception + 01 office), 1st floor to 3rd floor (05 guest rooms at each floor) and Terrace floor having (staff rooms) not in use as per affidavit dated 07.03.2020 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/2018/NDZ/286 dated 23/03/18 5. Fire safety directives No.-N/A 6. Date of inspection:-01/02/21 7. Name of the inspecting officer:-Sh. Ravinder Singh ADO/CC) 8. Name & designation of officer From the building side:-Sh. Mahander (Manager) 9. Year of construction:-1998-99 10. Applicant's letter No:-ID. No. 2020123009282 dated 30.12.2020 Building is comprised of basement, ground and three upper floor and 1/2 terrace floor which is not in use as per affidavit submitted by applicant dated 07.03.2020. Basement is other property and having separate entry/exit. Old Case S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Existing fire Prevention and fire safety MR/NMR safety U/R 33 arrangements 1. Access to Building 1) Road width 09 mtr. Approx N/A MR 2) Gate width N/A N/A N/A N/A N/A 3) Width of internal road N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 0.80 mtr. 0.80 to 0.98 mtr. MR N/A 2. Basements N/A N/A C. Protection of exits N/A N/A N/A 1. Fire check door 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace MR 1.25 mtr. E. Width of corridor 01 mtr. MR 01 mtr. 01 mtr. F. Door size 3. Compartmentation N/A N/A N/A 1) Fire check door N/A 2) Sealing of electrical shafts N/A N/A N/A N/A N/A 3) Fire rating of shaft door N/A N/AN/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. 30 ACPH N/A N/A 1) Basements MR Natural 12 a/c per 2) Upper floors hour Fire Extinguishers 5. MR 12 Nos. 10 Nos. 1) Total numbers ABC & CO2 MR ABC & CO2 2) Types Provided MR Required 3) ISI marking First-Aid Hose Reel 6. MR 01 1) Total number of eachfloor 01

	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	Required	TTOVICC	IVIIC
10.	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	14/11	1 4/ 7 4	10/21
11.	Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	14/11	1 4/ 7 4	11111
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	IN/ II	14/11	11 4/2 1
12.		N/A	N/A	N/A
	1) Total number of hydrants 2) Hose box	N/A	N/A	N/A
12		1 1/ / 1	1 1/ / 1	1 1// 1
13.	Pumping Arrangement	N/A	N/A	N/A
	1) Ground level		N/A N/A	N/A N/A
	a) Discharge of main	N/A	1N/ A	1N/ FA
	pump	N/A	N/A	N/A
	b) Head of main pump		N/A N/A	N/A
	c) Number of main pump	N/A		N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level	450 L DN 4	450 I DM	MR
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Provided	Provided	MR
	d) Auto starting of pump	Provided	Provided	IVIK
			T	
14.	Captive Water Storage for F	ire Fighting	NI/A	N/A
	1) Under ground tank	N/A	N/A	IN/A
	capacity	21/4	NI/A	N/A
	a) Draw-off connection	N/A	N/A	N/A N/A
	b) Fire service inlet	N/A	N/A	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank	5000 ltr.	5000 ltr.	IVIIC
	capacity	D : 1	Duanidad	MR
15.	Exit Signage.	Required	Provided	IVIIX
16.	Provision of Lifts.	2		
	a) Pressurization of lift	N/A	N/A	N/A
	shaft			
	b) Pressurization of lift	N/A	N/A	N/A
	lobby			
	c) Communication in	N/A	N/A	N/A
	lift car			
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
10.	110105	27/4	NI/A	N/A

,

M/22

19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: ABC & Co2			MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/286 dated 23/02/18, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Dychicarps

(K) WIZIZ

Mskeu uphowalid