GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2021/ 96

Dated: |8/2/21

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Royal Palace located at 1056-59, Pai Walan, Jama Masjid, Delhi, comprised of Ground + 03 upper floors: Ground floor- reception, 1st floor to 3rd floor - 06 guest rooms at each floor level & 02 temporary store room at terrace floor, total 18 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/2017/377 dated 08.03.2018. The building/premises was reinspected by Assistant Divisional Officer (SPM) from this department on 12.02.2021 in presence of Manager, and found that now the building is comprised on ground + mezzanine + 04 upper floors: ground floor- reception, Mezzanine - office (sealed), 1st floor to 3rd floor -06 guest rooms at each floor, terrace/4th floor -02 rooms- vacant and not in use. The owner has submitted an affidavit stating that they have sealed the mezzanine floor and shall not use any floor above third floor for any purpose in accordance with Gazette Notification dated 27.05.2019 and its subsequent clarification dated 25.09.2019 and 17.12.2021. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 18 guest rooms (Ground floor - reception, 1st floor to 3rd floor -06 guest rooms at each floor) only, with effect from for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued onat New Delhi by

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Tel: 011-23412025

ofc 86

Copy to:-

1. The Joint Commissioner of police (Licensing),
1st Floor, Police Station Defence Colony, New Delhi

2. The Licensee, M/s Hotel Royal Palace located at 1056-59, Pai Walan, Jama Masjid, Delhi

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

	INS	PECTION REPORT		•	
1	Name & address of the building	M/s Royal Palace Guest House located at 1056-59, Pai Walan, Jama Masjid, Delhi			
2	Building is comprised of	Ground + mezzanine + 04 upper floor			
	building is comprised of	Ground floor – reception			
		Mezzanine – single office room + toilet (Sealed)			
		1 st floor to 3 rd floor - 06 guest rooms at each floor			
	9	Terrace floor/4 th floor- 02 rooms (vacant).			
2	T (0				
3	Type of Occupancy	Residential Group A-1			
4	Type of Case	Renewal			
5	Details of Previous FSC		017/377 dated 08.03.2018		
6	Fire Safety direction letter No	Nil			
7	Date of Inspection	12.02.2021			
8	Name of the Inspecting Officers	Rajesh Kumar Shukla ADO (SPM)			
9	Name of the designation of Officer	Manager			
	from the building side				
10	Year of Construction	Prior to 1990			
		Online I.D No. 2021010609440 dated 05.01.2021			
11	Applicant's letter No	10- Hallest and State Continues to the State of the State			
S.No		Requirement/ Existing	Provided at Site	Remarks	
	Prevention and fire safety	fire safety	z 7 ^a	MR/NMI	
	requirements U/R 33	arrangements			
1	Access to building				
	Road width	NA	06 m	NA	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type and Arrai	ngement of Exits	8		
	A. Number of Staircases	8	8		
	Upper Floor	01 no.	01 no.	MR	
	Basement	NA	NA	NA	
	B. Width of Staircases				
	Upper Floor	80 cms	1 m	MR	
	Basement	NA	NA	NA	
	C. Protection of exits	11/1			
	Fire check door	(required as per point no. x	Not Provided	Last date o	
	The check door	of GN dated 27.05.2019)		compliance	
				extended	
	a a	· , , , , , ,	8 7.4	till	
	2			31.03.2021 vide order	
				dated	
				17.12.2020	
	Pressurization	NA	NA	NA	
	D. No. of continuous staircases to	NA	NA	NA	
	terrace				
	E. Width of Corridor	NA	NA	NA	
	G. Door size	1 m	1 m	MR	
3	Compartmentation	1 3 2	1 2 2 2		
_	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire rating of shaft door	NA	NA	NA	
		NA	NA	NA	
	Water curtain		NA NA	NA NA	
4	Fire Dampers	NA	INA	INA	
4	Smoke Management System.		NIA	NIA	
	Basement	30a/cper hour	NA	NA	
	Upper floor	(required as per point no. ix of GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021	

5.	Fire Extinguisher					
	Total numbers	10 no.	10 no.	MR		
	types	CO ₂ & ABC	CO ₂ & ABC	MR		
	IS marking	ISI marked	ISI marked	MR		
6	First-aid-Hose Reels.					
	Total numbers of each floor	l no.	1 no.	MR		
	Length of hose reel hose	30 m	30 m	MR		
	Nozzle diameter	5 mm	5 mm	MR		
7	Automatic fire detection and alarming					
	Type of detectors	CO detectors (required as per point no. viii of GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 31.03.2021 vide order dated 17.12.2020		
	Location of main panel	NA	NA	NA		
	Location of repeater panel	NA ·	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters	NA	NA	NA		
8	MOEFA	NA	NA	NA		
9	Public address System.	Required	Provided	MR		
10	Automatic Sprinkler System.		Tab.	1224		
	basement	NA	NA	NA		
	upper floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants					
	size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.					
	Total number of hydrants	NA .	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.		TI W			
15	Ground Level					
	Discharge of main Pump	NA	NA	NA		
	➤ Head of Main Pump	NA ·	NA	NA		
	> Number of main pumps	NA	NA	NA		
	> Jockey pump out put	NA NA	NA	NA NA		
		NA NA	NA	NA NA		
	Jockey pump headStandby pump out put	NA NA	NA	NA NA		
	> Standby pump Head	NA	NA	NA		
	> Auto Starting /Manual stopping	NA	NA	NA		
	> Pump House Access	NA	NA	NA		
	Terrace Level		a ·	* 8		
	Discharge of pump	450 LPM	450 LPM	MR		
	> Head of the Pump	40 m	40 m	MR		
	> Power supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		

14	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	NA	NA	NA	
	Draw-off connection	NA	NA	NA	
	Fire service inlet	NA	NA	NA	
	Access to tank	NA	NA	NA	
	Overhead Tank capacity	5000 ltrs	5000 ltrs	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby	NA	NA	NA	
	Communication in lift car	NA	NA	NA	
	Firemen's grounding switch	NA	NA	NA	
	Lift Signage	NA	NA	NA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	Total area	N.A	N.A	N.A	
	Location	N.A	N.A	N.A	
19	Fire Control Room				
	Detector system panel	NA	NA	NA	
	Flow switch panel	NA	NA	NA	
	PA system panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection systems for prot	tection of special	NA	NA	
	Risks, if any:		a a		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued by this department vide letter no. F6/DFS/MS/GZH/NDZ/2021/98 dated 27.01.2021 has been rectified by the management of the guest house and the owner has submitted an affidavit stating that the mezzanine floor has been sealed and any floor above third floor shall not be used for any purpose in accordance with Gazette Notification dated 27.05.2019 and its subsequent clarification dated 25.09.2019 and 17.12.2021.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/2017/377 dated 08.03.2018 is recommended to be renewed for ground 1st, 2nd and 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation ADO (SPM)

DO (CD)

16/2

9470m

Er is put up pla