## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2021/WZ/EH/ 4 8

Dated: 01 03 202

## FIRE SAFETY CERTIFICATE

Issued on O.A. 0.3. 2.1. at New Delhi by

DIRECTOR Ph:011-23414000

Ph:011-23414000

Copy to:-

1. The Dy. Health Officer, North MCD, Sec-5, Rohini Zone, Delhi-110085.

2. Randhir Kumar Arora, Spicy Affair Restaurant (Sanvi agencies Pvt Ltd) at Shop No.115, 119, FF, W Mall Pearls, Corporate, Manglam Palace, Sec-3, Rohini, Delhi-110085. Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.
- 9. The FSC will be automatically be null and void in absence of electrical and water supply to fire protection system if disconnected for mall building.

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

## **INSPECTION REPORT** 1. Name & address of the building: Spicy Affair Restaurant (Sanvi agencies Pvt Ltd) at Shop No.115, 119, FF, W Mall Pearls, Corporate, Manglam Palace, Sec-3, Rohini, Delhi-110085 Type of Occupancy : Group D Assembly Building (at first floor) 3. Type of Case : New Case (Eating House) 4. Details of Previous NOC : Nil 5. Fire Safety directives letter No : Nil 6. Date of inspection : 22.01.2021 7. Name of Inspecting Officer : ADO (Rohini) & DO (NW) 8. Name and designation of officers From the building side : Randhir Kumar Arora 9. Year of Construction 10. Applicant's letter No. : Online Application No.20201204135217 dated 04.12.2020 S. No. Minimum Standards on fire prevention UBBL/NBC Provided at site Remarks Requirement and fire safety U/R 33 MR/NMR Access to building 1. Provided Road width 6m MR Gate width Provided 4.5m MR Width of internal road NA NA NA 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 02 MR Basements NA NA NA b. Width of staircases Upper Floor Required Within Mall MR Basements NA NA NA c. Protection of exits NA NA NA Fire check door NA NA NA Pressurization NA NA NA d. No. of continuous staircases toterrace NA NA NA e. Width of Corridor NA NA NA Door Size 02 exit MR 3. Compartmentation Fire check door NA NA NA NA NA NA Sealing of electrical shafts Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA 4. Smoke Management System Basements NA NA NA Required MR Upper floors Exhaust Fan Fire Extinguishers 5. Total numbers 04nos 4nos MR Types ABC/CO2 **ABC** MR IS marking ISI Marked YES MR First-Aid Hose Reels 6. 01 Total numbers on each floor 01 MR Length of hose reel hose 30m Provided MR Nozzle diameter 5mm Provided MR 7. Automatic fire detection and alarming system

	Type of detectors	NA	NA	NA			
	<ul> <li>Location of Main Panel</li> </ul>	NA	NA	NA			
	<ul> <li>Location of Repeater Panel</li> </ul>	NA	NA	NA			
	<ul> <li>Alternate source of power</li> </ul>	NA	NA	NA			
	<ul> <li>Hooters' Location</li> </ul>	NA	NA	NA			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	NA	NA	NA			
10.	Automatic Sprinkler System			100,000			
	Basement	NA	NA	NA			
	<ul> <li>Ground &amp; Upper Floors</li> </ul>	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11.	Internal Hydrants						
	Size of riser/down-comer	NA	NA	NA			
	<ul> <li>Number of hydrants per floor</li> </ul>	NA	NA	NA			
	Hose Box	NA	NA	NA			
12.	Yard Hydrants						
	<ul> <li>Total number of hydrants</li> </ul>	NA	NA	NA			
	Hose Box	NA	NA	NA			
13.	<b>Pumping Arrangements</b>						
	Ground Level	NA	NA	NA			
	<ul><li>Discharge of main Pump</li></ul>	NA	NA	NA			
	Head of Main pump	NA	NA	NA			
	Number of main pumps	NA	NA	NA			
	Jockey Pump out put	NA	NA	NA			
	Jockey pump head	NA	NA	NA			
	Standby Pump out put	NA	NA	NA			
	Standby Pump Head	NA	NA	NA			
	Auto Starting/Manual Stopping	NA	NA	NA			
	Pump House Access	NA	NA	NA			
	Terrace level						
	Discharge of pump	450lpm	450lpm	MR			
	Head of the pump	40m	40m	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	<ul> <li>Underground tank capacity</li> </ul>	NA	NA	NA			
	Draw-off connection	NA	NA	NA			
	Fire service inlet	NA	NA	NA			
	Access to tank	NA	NA	NA			
	Overhead Tank capacity	10,000ltr	Provided	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.	-					
	Pressurization of Lift Shaft	NA	NA	NA			
	Pressurization of Lift lobby	NA	NA	NA			
	Communication In lift Car	NA	NA	NA			
	• Fireman's Grounding Switch	NA	NA	NA NA			
	Lift Signage	NA	NA	NA NA			
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area.	-toquitou	Tiovided	IVIK			

	4	Location	NA	NA	NA		
19.	Fire Control Room						
	•	Detector System Panel	NA	NA	NA		
		Flow Switch Panel	NA	NA	NA		
	•	PA System Panel	NA	NA	NA		
	<ul><li>Battery backup</li><li>Building Floor Plans</li></ul>	NA	NA	NA			
		NA	NA	NA			
20.	Specia	Fire Protection System for	NA	NA	NA		
	Protec	tion of special Risks, if any:					

The fire protection systems provided in the restaurant were tested, checked at random and found in working competition.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note: The mall is not having valid FSC, but this restaurant owner has provided all fire safety measure as required under law, separately, as approved by competent authority vide note on pre page 6/N. FSC is recommended subject to condition that is will be null & void in absence of electrical and water supply to dedicated fire protection system of restaurant if same is disconnected for mall building.

Signature of the Inspecting Office

Name: - D.B Mukherjee Designation:- DOWW

Signature of the Inspecting Officer

Name: - Ajay Kumar Sharma Designation: - ADO/Rohini