GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2021/ 137

Dated: 12 03 2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Delhi Muslim Guest House located at 2274, Gali Oasim Jan, Ballimaran, Delhi-06, comprised of Ground + 02 upper floors: Ground floor - commercial use, 1st floor - 10 guest rooms, 2nd floor -10 guest rooms + 03 staff rooms, total 20 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/2017/NDZ/1447 dated 06.10.2017. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 03.03.2021 in presence of manager and found that the building is now comprised of ground + 3 upper floors: ground - commercial, 1st floor -10 guest rooms +01 store +01 staff room, 2^{nd} floor -01 store +01 staff room). The owner has submitted property tax receipt from 2004-05 to 2020-21 as proof of existence of third floor since 2004. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 20 guest rooms (1st floor - 10 guest rooms, 2nd floor - 10 guest rooms) only, with effect from 12 03 2021. for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 12 03 202 at New Delhi by

(Dr. S.K. Tomar)

Dy. Chief Fire Officer

Tel: 011-23412025 ole Ales

Copy to:-

1. The Commissioner, North DMC, Shama Prashad Mukherjee Civic Centre, Delhi – 02.

- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New
- 3. The Licensee, M/s Delhi Muslim Guest House located at 2274, Gali Qasim Jan, Ballimaran, Delhi-06

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 31.03.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

N 2.7

		,			
1	INSP	ECTION REPORT			
1	Name & address of the building	M/s Delhi Muslim Guest House located at 2274, Gali Qasim Jan, Ballimaran, Delhi-06			
2	Building is comprised of	Ground + 03 upper floors			
		Ground floor - commercial use			
		1 st floor - 10 guest rooms + 01 store + 01 staff room			
		2^{nd} floor -10 guest rooms + 01 store + 01 staff rooms.			
		3 rd floor - Owner's residen	nce		
3	Type of Occupancy	Residential Group A-1			
4	Type of Case	Renewal			
5	Details of Previous FSC	F6/DFS/MS/GH/2017/NDZ/1447 dated 06.10.2017.			
6	Fire Safety direction letter No	NA			
7	Date of Inspection	03.03.2021			
	Name of the Inspecting Officers	Rajesh Kumar Shukla, ADO (SPM)			
8		Md. Iqbal (Manager)			
9	Name of the designation of Officer	Mu. Iquai (Mailagei)			
	from the building side	1982			
10	Year of Construction		21020210994 dated	02 02 2021	
11	Applicant's letter No	Online application I.D. 20		Remarks	
S.N		Requirement/ Existing	Provided at Site		
	Prevention and fire safety	fire safety		MR/NMR	
	requirements U/R 33	arrangements		2 /	
1	Access to building				
	Road width	05 m	05 m	MR	
	Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type and Arran	gement of Exits			
	A. Number of Staircases		· · · · · · · · · · · · · · · · · · ·	3.50	
	Upper Floor	02 no.	02 no.	MR	
	Basement	NA	NA	NA	
	B. Width of Staircases	0.7.0.7.	05.0.75	MD	
	Upper Floor	95 & 75 cms	95 & 75 cms NA	MR NA	
	Basement	NA	NA	IVA	
	C. Protection of exits	(Required as per GN dated	Not Provided	Last date o	
	Fire check door	27.05.2019)	8 8	compliance extended till 31.03.2021 vide order dated 17.12.2020	
	Pressurization	NA	NA	NA	
	D. No. of continuous staircases to terrace	01 no.	01 no.	MR	
	E. Width of Corridor	NA	NA	NA	
	G. Door size	1 m	1 m	MR	
3	Compartmentation	8	11 0	T	
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire rating of shaft door	NA	NA	NA	
	Water curtain	NA	NA	NA	
	Fire Dampers	NA	NA	NA	
4	Smoke Management System.			1	
	Basement	NA	NA	NA	
	Upper floor	Required natural/	Natural ventilation	MR	
1		mechanical	provided		

5.	Fire Extinguisher					
	Total numbers	06 no.	08 no.	MR		
	Types	CO ₂ & ABC	CO ₂ & ABC	MR		
	IS marking	Required	ISI marked	MR		
6	First-aid-Hose Reels.					
-	Total numbers of each floor	01	01 no.	MR		
	Length of hose reel hose	30 m	30 m	MR		
	Nozzle diameter	5 mm	5 mm	MR		
7			3 mm	IVIR		
	Automatic fire detection and alarming system. Type of detectors					
	Type of detectors	(required as per GN dated 27.05.2019)	Not Provided	compliance extended till 31.03.2021 vide order dated 17.12.2020		
	Location of main panel	NA	NA	NA		
	Location of repeater panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
0	Hooters	NA	NA	NA		
8	MOEFA	NA	NA	NA		
9	Public address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
	basement	NA	NA	NA		
	upper floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants	•				
	size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.	8		:		
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	NA	NA	NA		
	➤ Head of Main Pump	NA	NA	NA		
	> Number of main pumps	NA	NA	NA		
	Jockey pump out put	NA	NA	NA NA		
	> Jockey pump head	NA	NA	NA NA		
	> Standby pump out put	NA	NA	NA NA		
	> Standby pump Head	NA	NA	NA		
	> Auto Starting /Manual stopping	NA	NA	NA		
	> Pump House Access	NA	NA	NA		
	Terrace Level		•			
	Discharge of pump	225 LPM	225 LPM	MR		
	Head of the Pump	30 m	30 m	MR		
	Power supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		



N 2	2
for E' E'	
for Fire Fighting	•

Captive Water Storage for Fire Fighting. Underground tank capacity NA NA NA					
NA	NA				
NA					
NA	NA				
NA	NA				
ltrs 2 500 ltrs	NA				
red Provided	MR				
	MR				
NA					
NA NA	NA				
NA NA	NA				
NA NA	NA				
	NA				
ed Provided	NA				
ed Provided	MR				
Refuge Area. Total area N.A N.A N.A					
N.A	N.A				
N.A					
Fire Control Room Detector system panel N.A N.A N.A N.A					
NA					
NA NA	NA				
NA NA	NA				
NA NA	NA				
NA	NA				
ecial NA	NA				
IVA	NA				
	NA NA NA				

F6/DFS/MS/GH/2017/NDZ/1447 dated 06/10/2017 and the building comprised of ground + 2 upper issued floors. The guest house was running on 1st and 2nd floor of the building. However, in the inspection dated 03.03.2021 it was noticed that now the building comprised of ground + 3 upper floors wherein the third floor was being used as owner's residence while 1st and 2nd floor were being used as guest house. The owner has submitted a copy of property tax receipt from 2004-05 to 2020-21(placed at C/92) claiming that the residence of the owner was existing at third floor since 2004. The receipt copy has mention of 3rd floor and the tax has been paid under residential category. This supports the claim of the owner. The owner has also submitted the elevation plan of the building signed by a registered architect (placed at C/93-94) which shows that the building height upto 2nd floor is 12.08 meters. Guest houses above 12 meters are under the purview of this department as per DFS Act and Rules 2010 and this guest house is

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/2017/NDZ/1447 dated 06.10.2017 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: Rajesh Kumar Shukla

Designation ADO (SPM)

DØ (CD)