

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No F6/DFS/MS/EH/NDZ/2021/ 111

Dated: 27/4/21

FIRE SAFETY CERTIFICATE

Certified that **M/s Moti Mahal Restaurant** located at **3704, Netaji Subhash Marg, Daryaganj, Delhi – 02**, comprised of ground floor only, was granted FSC by this department vide letter no. F6/DFS/MS/EH/2017/739 dated 24.05.2017. The premises was inspected by the ADO (SPM) on 15.04.2021 in presence of Shri Vinod Chadha (prop.) and found that the said premises has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of **Group D “Assembly Building” (Restaurant)** with effect from ..27/4/21..... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under Rule 38 of Delhi Fire Service Rules, 2010 as mentioned below.

Issued on27/4/21..... at New Delhi by


23/4/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service
Tel: 011 - 23412025

Copy to:

1. The Joint Commissioner, Licensing, 1st floor, P. S. Defence Colony, New Delhi in r/o Online application I.D. 2021022710810 dated 08.03.2021.
2. The Health Officer, North DMC, SPM Civic Centre, JLN Marg, Delhi – 02.
3. The Licensee, M/s Moti Mahal Restaurant located at 3704, Netaji Subhash Marg, Daryaganj, New Delhi.

Condition for the validity of fire safety certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1.	Name & address of the building	M/s Moti Mahal Restaurant, Netaji Subhash Marg, Daryaganj, Delhi – 02.		
2.	Building is comprised of	Ground floor only		
3.	Type of Occupancy	Assembly (Restaurant)		
4.	Type of Case	Renewal		
5.	Details of Previous FSC	F6/DFS/MS/EH/2017/739 dated 24.05.2017		
6.	Fire Safety direction letter No	NA		
7.	Date of Inspection	15.04.2021		
8.	Name of the Inspecting Officers	Rajesh Kumar Shukla, ADO (SPM)		
9.	Name of the designation of Officer from the building side	Mr. Vinod Chadha (Prop.)		
10	Year of Construction	1947		
11.	Applicant's letter No	Online application I.D. 2021022710810 dated 08.03.2021		
S.No	Minimum Standards on fire prevention and fire safety U/R 33	Requirement/ NBC	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	06 m	24 m	MR
	Gate width	NA	NA	NA
	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits.			
	A. Number of Staircases			
	upper floor	NA	NA	NA
	Basement	NA	NA	NA
	B. Width of Staircases	NA	Na	NA
	Ground to mezzanine floor	NA	NA	NA
	Basement	NA	NA	NA
	C. Protection of exits			
	Fire check door	NA	NA	NA
	Pressurization	NA	NA	NA
	D. No. of continuous staircases to terrace	NA	NA	NA
	E. Width of Corridor	NA	NA	NA
	F. Door Size (Exits)	1.5 m	1.69 m, 0.90 m	MR
3	Compartmentation			
	Fire check door	NA	NA	NA
	Sealing of electrical shafts	N.A.	NA	NA
	Fire rating of shaft door	N.A.	N.A.	N.A.
	Water curtain	N.A.	N.A.	N.A.
	Fire Dampers	N.A.	N.A.	N.A.
4	Smoke Management System.			
	Basement	NA	NA	NA
	Ground floor	12 a/c per	Natural	MR

5.	Fire Extinguisher			
	Total numbers	02 no.	08 no.	MR
	types	ABC + CO ₂	ABC + CO ₂	MR
	IS marking	ISI marked	ISI marked	MR
6	First-aid-Hose Reels.			
	Total numbers of ground floor	01 no.	01 no.	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	Smoke/heat	Provided	MR
	Location of main panel	Required	Provided	MR
	Location of repeater panel	NA	NA	NA
	Alternate source of power	Required	Provided	MR
	Hooters	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public address System.	N.A.	NA	NA
10	Automatic Sprinkler System.			
	Kitchen	NA	NA	NA
	Upper floors	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	Internal/ External Hydrants			
	Size of Hydrant	100 mm	100 mm	MR
	Number of hydrants each floor	1 no.	1 no.	MR
	Hose box each floor	1 no.	1 no.	MR
12	Yard Hydrants.			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements.			
	• Ground Level			
	➤ Discharge of main Pump	450 LPM	450 LPM	MR
	➤ Head of Main Pump	40 m	40 m	MR
	➤ Number of main pumps	01 no.	01 no.	MR
	➤ Jockey pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby pump out put	NA	NA	NA
	➤ Standby pump Head	NA	NA	NA
	➤ Auto Starting /Manual stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	• Terrace Level	NA	NA	NA
	➤ Discharge of pump	NA	NA	NA
	➤ Head of the Pump	NA	NA	NA
	➤ Power supply	NA	NA	NA
	➤ Auto Starting of pump	NA	NA	NA

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	13,000 Liters	13,000 litres	MR
	Draw-off connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
	Overhead Tank capacity	NA	NA	NA
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.
	Pressurization of Lift lobby	N.A.	N.A.	N.A.
	Communication in lift car	N.A.	N.A.	N.A.
	Firemen's grounding switch	N.A.	N.A.	N.A.
	Lift Signage	N.A.	N.A.	N.A.
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total area	N.A.	N.A.	N.A.
	Location	N.A.	N.A.	N.A.
19	Fire Control Room			
	Detector system panel	N.A.	N.A.	N.A.
	Flow switch panel	N.A.	N.A.	N.A.
	PA system panel	N.A.	N.A.	N.A.
	Batter backup	N.A.	N.A.	N.A.
	Building Floor Plans	N.A.	N.A.	N.A.
20	Special Fire Protection systems for protection of special Risks, if any:	LPG bank near the kitchen: Protected by sprinklers		MR


MR – Meeting Requirement, NMR – Not Meeting Requirement, NA – Not Applicable

The shortcomings issued to the restaurant vide letter no. F6/DFS/MS/EH/NDZ/2021/140 dated 23.03.2021 have been rectified.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the Rule 33 of the Delhi Fire Service Rules 2010, it is recommended to renew the FSC issued vide letter no. F6/DFS/MS/EH/2017/739 dated 24.05.2017 under Rule 35 of DFS Rules 2010.


Accordingly, online application no. 2021022710810 may be cleared from fire safety point of view.


Signature of the Inspecting Officer

Name Rajesh Kumar Shukla

Designation ADO (SPM)

DO (CC)


19/4/21

Dy. C.F.S. (NDZ)

F. T. P. I.

