GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/GH/2021/SZ/ 2/9

FIRE SAFETY CERTIFICATE

Certified that the Guest House in the Name & Style of The Muse, Sarovar Portico, (A Unit of Palm Land Hospitality) A-1, Chirag Enclave, New Delhi 110048 comprised of Basement, Ground plus three upper floors (42 Guest Room) was already been issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/697 dated 13/04/2018. The premise was reinspected by the officer concerned of this department on 02/07/2021 in the presence of Mr. Piyush (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential & Lodging", Group-A" (Guest House) with effect from the date of issue 157 7 /2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 1577/2/ at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ)

Delhi Fire Service

Copy to: -

- py to:
 1. The Muse, Sarovar Portico, (A Unit of Palm Land Hospitality) A-1, Chirag Enclave, New Delhi 110048
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049.

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or before 30/09/2021 in compliance to the notification dated 27/05/2019 an as approved and now have been extended till 30.09 2021 vide Directorate of Local Bodies, UDD, GNCT of Delhi letter no. F5 (189)/AD/LB/2016/359-374 dated 29.06.2021.

	INSPECTIO	ON REPORT			
1	Name & Address of the Building	The Muse, Sarovar Portico, (A Unit of Palm			
		Delhi 110048	Land Hospitality) A-1, Chirag Enclave, New		
2	Type of Occupancy				
3	Building Comprised of	Residential (Guest House), "Group – A" Basement + Ground + 03 upper floors.			
4	Type of Case	Renewal	und + 03 upper 11001s.		
5	Details of Previous NOC		I/SZ/2018/697 dated 13	2/04/2019	
6	Fire Safety Directives Letter No	Nil 1	1/32/2016/09/ dated 13	0/04/2010	
7	Date of Inspection	02/07/2021			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers				
	from the building side	Mr. Piyush (Manager)			
10	Year of construction	2007 (03 guest rooms at GF, & 13 guest rooms, a			
10	Total of construction	each upper floors, total 42 guest rooms)			
11	Applicant letter No.	Gmail dated 30/06/2021			
S. No.	Minimum standards on Fire Prevention	BBL /NBC	Provided at Site	Remarks	
-1180	and Fire Safety U/R 33	Requirements		MR/NMR	
1	Access to Building.				
	Road width	Required	09 mtr	MR	
	Gate width	-NA-	About no road	-NA-	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.				
	g) Number of Staircase				
	> Upper floors.	02 Required	Provided	MR	
	Basement floor.	02 Required	Provided	MR	
	h) Width of Staircase				
	> Upper floors	1.25 & 1.2 Mtr	1.25 & 1.2 Mtr	MR	
	Basement floor	1.25 & 1.2 Mtr	1.25 & 1.06 Mtr	MR (old case)	
	i) Protection of exits		2.20 00 2.00 124	IVII (Old Case)	
	Fire check door	-NA-	-NA-	-NA-	
	> Pressurization	-NA-	-NA-	-NA-	
	j) No. of continuous staircase to terrace	Required	Two	MR	
	k) Width of corridor	-NA-	1.50 mtr	-NA-	
	1) Door size	1 mtr	1.0 mtr (Final exit)	MR	
3	Compartmentation.	1 IIII	1.0 Hiti (Thiai CAIL)	, IVIX	
	Fire check door.	-NA-	-NA-	-NA-	
	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4	Smoke Management system.	-1477-	-14/7-	-11/7-	
	Basement	30 ACPH	Exhaust fan provided	MR	
	• Upper floors	12 ACPH	-NA-		
5	Fire Extinguishers.	12 ACFII	~IVA~	-NA-	
3	Total numbers		15 Nos	MD	
			CO2- 05, w.co2-05 &	MR	
	• Types	ISI marked	ABC-05	MR	
	ISI Marking		Provided Provided	MR	
6	First Aid Hose Reels.		1 TOVIGEU	IVIIX	
	Total numbers on each floor.	Hose Reel	Provided	MR	
		30m			
	Length of hose-reel hose.		Provided	MR	
	Nozzle Diameter	05 mm	Provided	MR	

1	Automatic fire detection & alarming syst	em.		
		*		
	Type of detectors	Required	Provided	
	Education of Main Panel	-NA-		M
	Location of Repeater Panel	-NA-	-NA-	-NA
	riteriale source of nower	-NA-	-NA-	-NA
0	Trooter's location	-NA-	-NA-	-NA
8	THE PARTY OF THE P	Required	-NA-	-NA
10	Public Address System	Required	Provided	MR
10	Tatomatic Sprinkler System	required	Provided	MR
	Basement	Required	D. 11.1	
	• Upper floors	Required	Provided Provided	MR
11	Sprinkler above false ceiling	-NA-		MR
11	Internal Hydrants.	- 1. 2	-NA-	-NA
	Size of Riser/Down-comer	Required	100	
	 Number of Hydrant per floor 	Required	100 mm	MR
	Hose box.	Required	01	MR
12	Yard Hydrants.	Required	01	MR
	 Total number of hydrants. 			
	Hose box.	-NA-	-NA-	-NA-
13	And the second s	-NA-	-NA-	-NA-
	Pumping arrangements. • Ground Level			-INA-
	Discharge of main pump.Head of main pump.	-NA-	-NA-	77.4
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level	-NA-	-NA-	-NA-
	Discharge of pump.			-IVA-
	Head of pump.	840 & 600 LPM	Provided	MD
	Power supply.	36 & 23.5 m	Provided	MR MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	Required	Provided	MR
	Underground tank capacity.			IVII
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	 Overhead tank capacity 	-NA-	-NA-	-NA-
5	Exit Signage.	13,000 Ltrs	Provided	MR
6	Provision of Lifts.	Required	Provided	MR
	 Pressurization of lift shaft. 	NTA.		
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	 Communication in lift car 	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
	 Lift signage. 	-NA-	-NA-	-NA-
7 5	Standby Power Supply	-NA-	-NA-	-NA-
3]	Refuge Area	Required	Provided	MR
Similar Simila	Total area	AT A		
	• Location	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

ered please return to .

19	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
***************************************	Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 293 dated 05/04/2021.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/GH/SZ/2018/697 dated 13/04/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Rajesh Kumar

Design: ADO (BCP)

Defo

opproved, F.t. lettel es synature P).