

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No F 6/DFS/MS/2021/EH/WZ/ 149

Dated 23/7/21

FIRE SAFETY CERTIFICATE

Certified that the M/s **Bikanervala Foods Pvt. Ltd, located at 103-105, 1st floor, Ring Road Mall, Sector-3, Rohini, Delhi-110085** in the building comprised of basement, ground and 08 upper floor owned/ occupied by M/s **Bikanervala Foods Pvt. Ltd** was granted NOC by this department vide letter no. **F.6/DFS/MS/2017/EH/WZ/1223 dated 18.08.2017**. The premises was re-inspected by the officers concerned of this department on **06.04.2021** in the presence of **Sh. Nikesh Sharma (Manager)** and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. Hence the NOC is renewed and premises is fit for occupancy **Class (Assembly)** for first floor only with effect from **23/7/21** for a period of **03 (Three) years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on **23/7/21** at New Delhi by


(Dhrampal Bhardwaj)
Dy.Chief Fire Officer
Tel:-01123412050

54

Copy to:-

1. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054.
2. Sh. Pankaj Saroha (Manager), M/s Bikanervala Foods Pvt. Ltd, located at 103-105, 1st floor, Ring Road Mall, Sector-3, Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building : M/s Bikanervala Foods Pvt. Ltd, located at 103-105, 1st floor, Ring Road Mall, Sector-3, Rohini, Delhi-110085.
2. Type of Occupancy : Assembly (Upper floor) Shop No. 103 to 105
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/2017/EH/WZ/1223 dated 18.08.2017
5. Fire Safety directives letter No : (Mall NOC F6/DFS/MS/2014/WZ/486 dated 16.04.2014)
6. Date of inspection : 06.04.2021
7. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)
8. Name and designation of officers
From the building side : Sh. Nikesh Sharma (Manager)
9. Year of Construction : 2007
10. Applicant's letter No. : Online e-mail dated 23.03.2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building (Ring Road Mall issued FSC vide letter No. F6/DFS/MS/2014/WZ/486 dated 16.04.2014)			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible	Accessible	MR
		Accessible	Accessible	MR
		NA	NA	NA
2.	Number, Width, Type & Arrangement of Exits [Provided & Maintained by Mall management]			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
	c. Protection of exits			
	Fire check door [Provided &	Restaurant within Mall	As Above	NA
	<ul style="list-style-type: none"> • Pressurization 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
	d. No. of continuous staircases to terrace	Restaurant within Mall	As Above	NA
	e. Width of Corridor			
		02 Exit	1.80m & 1.70m	MR (Old case)
	f. Door Size			
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
4.	Smoke Management System [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> • Basements 	Restaurant within Mall	As Above	NA
	<ul style="list-style-type: none"> • Upper floors 	Restaurant within Mall	As Above	NA
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	04	04	MR
		ABC/Co2	ABC/Co2	MR
		ISI Marked	Yes	MR
6.	First-Aid Hose Reels. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	01	As Above	MR
		30m	As Above	MR
		5mm	As Above	MR
7.	Automatic fire detection and alarming system. [Provided & Maintained by Mall management]			

	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
8.	MOEFA	Required	Provided	MR
9.	Public Address System	NA	As Above	NA
10.	Automatic Sprinkler System [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Basement 	Restaurant within Mall	As Above	NA
	<ul style="list-style-type: none"> Ground & Upper Floors 	Restaurant within Mall	As Above	NA
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	Restaurant within Mall	As Above	NA
11.	Internal Hydrants [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Size of riser/down-comer 	100mm	As Above	MR
	<ul style="list-style-type: none"> Number of hydrants per floor 	One (near to Restaurant)	As Above	MR
	<ul style="list-style-type: none"> Hose Box 	One (near to Restaurant)	As Above	MR
12.	Yard Hydrants [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Total number of hydrants 	NA	NA	NA
	<ul style="list-style-type: none"> Hose Box 	NA	NA	NA
13.	Pumping Arrangements [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Ground Level 			
	<ul style="list-style-type: none"> ➤ Discharge of main Pump 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Head of Main pump 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Number of main pumps 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Jockey Pump out put 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Jockey pump head 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Standby Pump out put 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Standby Pump Head 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Auto Starting/Manual Stopping 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Pump House Access 	NA	NA	NA
		NA	NA	NA
	<ul style="list-style-type: none"> Terrace level 	[Provided & Maintained by Mall management]		
	<ul style="list-style-type: none"> ➤ Discharge of pump 	NA	As above	MR
	<ul style="list-style-type: none"> ➤ Head of the pump 	NA	As above	MR
	<ul style="list-style-type: none"> ➤ Power Supply 	Required	As above	MR
	<ul style="list-style-type: none"> ➤ Auto Starting of pump 	Required	As above	MR
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> Underground tank capacity 	NA	As above	NA
	<ul style="list-style-type: none"> ➤ Draw-off connection 	NA	As above	NA
	<ul style="list-style-type: none"> ➤ Fire service inlet 	NA	As above	NA
	<ul style="list-style-type: none"> ➤ Access to tank 	NA	As above	NA
	<ul style="list-style-type: none"> Overhead Tank capacity 	NA	As above	NA
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft 	NA	NA	NA
	<ul style="list-style-type: none"> Pressurization of Lift lobby 	NA	NA	NA
	<ul style="list-style-type: none"> Communication In lift Car 	NA	NA	NA
	<ul style="list-style-type: none"> Fireman's Grounding Switch 	NA	NA	NA
	<ul style="list-style-type: none"> Lift Signage 	NA	NA	NA
17.	Standby power supply	NA	NA	NA
18.	Refuge Area. [Provided & Maintained by Mall management]			

	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19.	Fire Control Room [Provided & Maintained by Mall management]			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Battery backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2017/EH/WZ/1223 dated 18.08.2017. Renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Note:- Request of applicant that shortcoming given to mall dose not belong to first floor are not affect fire & life safety of restaurant may be accepted.

Amr
7/4/21

Signature of the Inspecting Officer

Name Ajay Kumar Sharma

Designation ADO (Rohini)

DO(NW) - on leave

~~DCFO(W2)~~

Is it working its individual F.F. provisions.
8/4/2021

~~MS/2017~~
~~WZ/1223~~

Fire-fighting system is provided by the main occupancy and it is in working condition and shortcoming issued to main occupancy does it affect the fire safety of restaurant premises.

~~DO(NW)~~

~~DCFO(W2)~~

Amr
12/04/2021

Amr
9/4/21

FSC is not obtained by mall main building hence FSC for mall restaurant can not be