C-105

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2021/SZ/2 48

Dated: 26./07./2021

FIRE SAFETY CERTIFICATE

Certified that M/s Madhuban Inn Guest House located at B- 71, Greater Kailash-1, New Delhi 110048, comprised of Basement, Stilt, ground plus three upper floors with total 40 Guest rooms only was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2017/SZ/1717 dated 30/11/2017. The premise was re-inspected by the officer concerned of this department on 23/07/2021 in the presence of Mr. Kush Nanda and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential & lodging Group-A" (Guest House) with effect from the date of issue 36 / 7/2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions funder Rule 38 of the Delhi Fire Service Rules, 2010

Issued on $\frac{36}{7}$ at New Delhi by

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- The Manager that M/s Madhuban Inn Guest House located at B- 71, Greater Kailash-1, New Delhi 110048
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi–110049

Conditions for the validity of Fire Safety Certificate: -

- 1. Mezzanine floor in between basement and ground is sealed with Brick wall by the Owner/occupier of the building.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 8. The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or before 30/09/2021 in compliance to the notification dated 27/05/2019 an as approved and now have been extended till 30.09 2021 vide Directorate of Local Bodies, UDD, GNCT of Delhi letter no. F5 (189)/AD/LB/2016/359-374 dated 29.06.2021.

- M32-

		ON REPORT				
1	Name & Address of the Building	& Address of the Building M/s Madhuban Inn, Guest				
		Greater Kailash-I, New Delhi-110048				
2	Type of Occupancy	Residential, "Group-A" (Guest House)				
3	Building Comprised of	Basement, Stilt + Ground + 03 upper floors. (Mezzanine floor sealed by brick wall)				
4	Type of Case	Renewal				
5	Details of Previous NOC	F6/DFS/MS/GH/2017/SZ/1717 dated 30/11/2017 Basement, stilt, ground and 03 upper floors				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	23/07/2021				
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
9	Name & Designation of Officers	Mr. Kush Nanda				
	from the building side	2010 Basement storage & Office, Stilt (Parkin				
10	Year of construction	2010 Basement storage & Office, Stift (Page Reception), Ground Floor (Kitchen, dining hal GH room) 1st to 3rd floor (12 Guest room at Total 40 GH rooms			ning hall & 04	
11	Applicant letter No.	Gmail d	ated 16/0'			
S. No.	Minimum standards on Fire Prevention	Old NOC		Provided at Site	Remarks	
	and Fire Safety U/R 33	requirements			MR/NMR	
1	Access to Building.				7.50	
	Road width	Required		09 mtr	MR	
20	Gate width	-N		-NA-	-NA-	
	Width of internal road	-NA-		-NA-	-NA-	
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase				1.00	
4	Upper floors.	Required		· 02 Nos	MR	
	Basement floor.	Required		02 Nos	MR	
- 1	b) Width of Staircase					
	> Upper floors	Required		1.25m & 1.36 m	MR	
	Basement floor	Required		1.25m & 1.36 m	MR	
	c) Protection of exits			V 2 2		
	Fire check door	-NA-		-NA-	-NA-	
	> Pressurization	-NA-		-NA-	-NA-	
-	d) No. of continuous staircase to terrace	02		Provided	MR	
	e) Width of corridor	-NA-		-NA-	-NA-	
	f) Door size	1m		2 m (final exit)	MR	
3	Compartmentation.					
	Fire check door.	Required		Provided	MR	
	 Sealing of electrical shafts. 	NA		NA	NA	
	Fire rating of shaft door.	-NA-		-NA-	-NA-	
	Water curtain	-1	VA-	-NA-	-NA-	
	Fire dampers.	1-	VA-	-NA-	-NA-	
4	Smoke Management system.					
	Basement	30 /	ACPH	Exhaust fan provided	MR	
	Upper floors	-1	VA-	-NA-	-NA-	
5	Fire Extinguishers.					
	Total numbers	24	Nos	Provided	MR	
	• Types	ABC / CO2		ABC & CO2	MR	
	ISI Marking	ISI marked		Provided	MR	
6	First Aid Hose Reels.					
					MR	

- NJ33-

***************************************	Length of hose-reel hose.	30 mtr	Provided) (D	
	Nozzle Diameter			MR	
7		5 mm	Provided	MR	
/	Automatic fire detection & alarming system.	Circular dated 29/06/2021 amendment / modification in (UBBL-2016 till 30/09/2021)			
	Type of detectors	-NA-	-NA-	-NA-	
	 Location of Main Panel 	-NA-	-NA-	-NA-	
	 Location of Repeater Panel 	-NA-	-NA-	-NA-	
	 Alternate source of power 	-NA-	-NA-	-NA-	
	Hooter's location	-NA-	-NA-	-NA-	
8	MOEFA	Required	Provided	MR	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler System	1.00			
	Basement	Required	Provided	MR	
	Upper floors.	-NA-	-NA-	-NA-	
	Sprinkler above false ceiling	-NA-	-NA-	-NA-	
11	Internal Hydrants.		A 1 A B	1471	
Ballinda Sent sharenas	Size of Riser/Down-comer	-NA-	100 mm	-NA-	
	Number of Hydrant per floor	-NA-	-NA-	-NA-	
	Hose box	-NA-	-NA-	-NA-	
12	Yard Hydrants.	1111	-1 ALJ.	-1VA-	
	Total number of hydrants.	-NA-	-NA-	-NA-	
	Hose box.	-NA-	***************************************		
13	Pumping arrangements.	-IVA-	-NA-	-NA-	
10	Ground Level				
	Discharge of main pump.	ATA .	T A		
	Head of main pump.	-NA-	-NA-	-NA-	
	Number of main pumps.	-NA-	-NA-	-NA-	
	Jockey Pump output.	-NA-	-NA-	-NA-	
	Jockey Pump head.	-NA-	-NA-	-NA-	
	Standby Pump output.	-NA-	-NA-	-NA-	
	Standby Pump head.	-NA-	-NA-	-NA-	
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-	
	Pump house access.	-NA-	-NA-	-NA-	
		-NA-	-NA-	-NA-	
	Terrace Level Discharge of pump	OCCUPATION OF			
	Discharge of pump.Head of pump.	900 LPM	Provided	MR	
	Power supply.	40m	Provided	MR	
	Auto starting of pump.	Required	Provided	MR	
14		Required	Provided	MR	
4.4	Captive water storage for fire fighting.	20,000 1	20,000 1		
	 Underground tank capacity. Draw-off connection. 	30,000 ltrs	30,000 ltrs	MR	
	Fire Service Inlet.	-NA-	-NA-	-NA-	
	Access to tank.	-NA-	-NA-	-NA-	
	Overhead tank capacity.	-NA-	-NA-	-NA-	
		20,000 ltrs	20,000 Ltrs	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	 Pressurization of lift shaft. 	-NA-	-NA-	-NA-	
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-	
	 Communication in lift car. 	-NA-	-NA-	-NA-	
	Fireman's switch.	Required	Provided	MR	
	Lift signage.	Required	Provided	MR	
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area		11011000	TATIX	

- M34 -

- 6. 3.	Total area	-NA-	-NA-	-NA-		
0	• Location	-NA-	-NA-	-NA-		
19	Fire Control Room.					
	Detector system panel.	-NA-	-NA-	-NA-		
	Flow switch panel.	-NA-	-NA-	-NA-		
	PA system panel.	-NA-	-NA-	-NA-		
	Battery backup.	-NA-	-NA-	-NA-		
1	Building floor plan.	-NA-	-NA-	-NA-		
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-		

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 295 dated 06/05/2021. Mezzanine Floor is sealed with Brick wall by the Guest house management.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2017/SZ/1717 dated 30/11/2017, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Design: ADO (BCP)

Defo(sh)

A Defo(sh)

As approved, F.T. tetter in putup for your

synature PI

My

20/2