GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2021/EH/WZ/ 17 8
FIRE SAFETY CERTIFICATE

Dated 12/8/21

Certified that the M/s Pind Baluchi Restaurant at F A-9, 10, 11, Unitech Metro Walk, Sector-10, Rohini, Delhi-110085, restaurant is running at first floor of a building comprised of Ground + One floor owned/ occupied by Amusement Park was granted NOC by this department vide letter no. F.6/DFS/MS/2018/EH/WZ/1856 dated 08.08.2018. The premises was re-inspected by the officers concerned of this department on 06.07.2021 in the presence of Sh. Rajesh Thakur (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010, and premises is fit for occupancy Class (Assembly Restaurant) with effect from 12/8/2/ for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12/8/21. at New Delhi by

(Dhrampal Bhardwai) Dy.Chief Fire Officer Tel;-01123414250

Copy to:-

1. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054

2. Mr Suraj (Store Manager), M/s Pind Baluchi Restaurant at F A-9, 10, 11, Unitech Metro Walk, Sector-10, Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

		a water a second	INSPEC	CTION REPORT		
	2. Ty 3. Ty 4. De 5. Fin 6. Da 7. Na 8. Na fro 9. Year 10. App	tte of inspection me of the Inspecting Officers me and designation of officer m the building side of Construction blicant's letter No.	g: M/s Pi Walk, : Assemble: Renew : F.6/DF : NBC P : 06.07.2 : A.K.Shes : Mr. Ra :2007 :Online	bly (Restaurant running) al S/MS/2018/EH/WZ/18 art-4 2021 harma ADO/Rohini akesh Thakur, Manager	ng at 1 st floor, F A	-9, 10, 11) 018
1		mum Standards on fire preven fire safety U/R 33	iuon and	Rule 35 (6)	Provided at	Remarks
	F6/DF	ss to building (Amusement S/MS/WZ/2020/427 dated 22.10.20	Park of A	Adventure Island Metro P	ark issued FSC vi	de letter No
	•	Road width	020]	Restaurant within Ma		de letter 190.
	9	Gate width	*:	Restaurant within Mal		MR
	•	Width of internal road			1 As Above	MR
2	Numt			NA	NA	NA
	a Nur	oer, Width, Type & Arrange onber of staircases	ement of	Exits[Provided & Maintai	ned by Mall managem	nent]
0	(i. 1 ((i))	7.74				lentj
		Upper Floors Basements		Restaurant within Mall	As Above	NA
		th of staircases		Restaurant within Mall	As Above	
	Ø. ₩10	Upper Floors			213 1100VE	NA
		Basements		Restaurant within Mall	1. Gardagus m	MR Cod Can
	c. Prote	ection of exits		Restaurant within Mall	As Above	NA
	1	• Fire check door		D	e de la companya de l	
		Pressurization		Restaurant within Mall	As Above	NA
	d. No.	of continuous staircases to ter	_	Restaurant within Mall	As Above	NA
	e. Widt	h of Corridor	-	Restaurant within Mall	As Above	NA
	f. Door			Restaurant within Mall	As Above	NA
3				Two Exits	0.93 & 1.38	MR
,	Compa	rtmentation.				14117
	• I	Fire check door	1	Rectanged 'd'		
	9 5	Sealing of electrical shafts	-	Restaurant within Mall	As Above	NA
	L	Starring of ciccurical shafts	1 1	The state of the s	110010	
	• F	Fire Rating of shaft door		Restaurant within Mall	As Above	NA
	0 1	Fire Rating of shaft door Vater Curtain	F	Restaurant within Mall Restaurant within Mall		
	• F	Vater Curtain	F	Restaurant within Mall Restaurant within Mall Restaurant within Mall	As Above	NA
	• F	Vater Curtain Tire Dampers	R	Restaurant within Mall Restaurant within Mall Restaurant within Mall	As Above As Above As Above	NA NA
	• F Smoke N	Tire Rating of shaft door Vater Curtain Tire Dampers Management System. [Provided]	R R d & Mainta	Restaurant within Mall Lined by Mall management	As Above As Above As Above	NA NA
	• V • F Smoke N	Vater Curtain Tire Dampers Management System. [Provided assements	R R d & Mainta	Restaurant within Mall Restaurant within Mall Restaurant within Mall	As Above As Above As Above	NA NA NA
	• V • F Smoke N • B	Vater Curtain Tire Dampers Management System. [Provided assements pper floors	F R R d & Mainta	Restaurant within Mall Lined by Mall management	As Above As Above As Above As Above	NA NA NA NA
	• F • W • F • Smoke M • B • U Fire Exti	Vater Curtain Varier Dampers Vanagement System. [Provided assements In page 1	F R R d & Mainta	Restaurant within Mall Restaurant within Mall Restaurant within Mall Restaurant within Mall Lestaurant within Mall Lined by Mall management] estaurant within Mall	As Above As Above As Above As Above	NA NA NA
	• F • W • F • Smoke M • B • U Fire Exti	Vater Curtain Tire Dampers Management System. [Provided assements pper floors	F R R d & Mainta	Restaurant within Mall	As Above As Above As Above As Above As Above As Above	NA NA NA NA
	• F Smoke M • B • U Fire Exti	Vater Curtain Varier Dampers Vanagement System. [Provided assements In page 1	R R R	Restaurant within Mall Restaurant within Mall Restaurant within Mall Restaurant within Mall Lestaurant within Mall Lined by Mall management Lestaurant within Mall Lestaurant within Mall Lestaurant within Mall Lestaurant within Mall O4nos O/Co2	As Above As Above As Above As Above	NA NA NA NA

	 IS marking 	ISI marked	Yes	MR			
6	First-Aid Hose Reels. [Provided & Maintained by Mall management]						
	Total numbers on each floor	01	As Above	MI			
	 Length of hose reel hose 	30 m	As Above	1111			
	 Nozzle diameter 	5mm	As Above				
7	Automatic fire detection and alarming system. [Provided & Maintained by Mall management]						
	Type of detectors	Restaurant within Mall	As Above				
	 Location of Main Panel 	Restaurant within Mall	As Above	1 42			
		Restaurant within Mall					
	Education of Repeater Failer		As Above	. 12			
	Alternate source of power	Restaurant within Mall	As Above	NA			
	Hooters' Location	Restaurant within Mall	As Above	N/			
)	MOEFA	Required	Provided	MR			
	Public Address System.	NA	As Above	NA			
0	Automatic Sprinkler System[Provided & Maintained by Mall management]						
	• Basement	Restaurant within Mall	As Above	NA NA			
	 Upper Floor 	Restaurant within Mall	As Above	NA NA			
	 Sprinkler above false ceiling 	Restaurant within Mall	As Above				
1	Internal Hydrants [Provided & Maintained by Mall management]						
	Size of riser/down-comer	100mm	As Above	MR			
	 Number of hydrants per floor 	One (near to Restaurant)	As Above				
	 Hose Box 	One (near to Restaurant)	As Above	MR			
2	Yard Hydrants. [Provided & Maintained by Mall management]						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA					
			NA	NA			
	Pumping Arrangements. [Provided & Maintained by Mall management]						
	Oround Devel	NA					
	Discharge of main Pump	NA NA	NA	NA			
	Head of Main pumpNumber of main pumps	NA NA	NA	NA			
	Number of main pumps	NA NA	NA	NA			
				NA			
THE RESIDENCE STREET, AND ASSESSMENT OF THE PROPERTY OF THE PERSON OF TH	Jockey Pump out put		NA				
	Jockey Pump out putJockey pump head	NA	NA	NA			
	Jockey Pump out putJockey pump headStandby Pump out put	NA NA	NA NA				
	 Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head 	NA NA NA	NA NA NA	NA			
	 Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual 	NA NA	NA NA	NA NA			
	Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping	NA NA NA	NA NA NA	NA NA NA			
	 Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual 	NA NA NA NA	NA NA NA	NA NA NA NA			
	Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level	NA NA NA NA NA Provided & Mainta	NA NA NA NA	NA NA NA NA NA NA NA NA NA			
	Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level Discharge of pump	NA NA NA NA NA PA NA [Provided & Maintantantantantantantantantantantantantan	NA NA NA NA NA NA ained by Mall manager	NA NA NA NA			
	Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level	NA NA NA NA NA Provided & Mainta	NA NA NA NA NA NA A NA A A A A A A A A	NA NA NA NA NA MA MA MA MA MR			

-							
	0	Underground tank capacity	NA	As Above	NA		
	>	Draw-off connection	· NA	As Above	NA		
	a.	Fire service inlet	NA	As Above	NA		
		Access to tank	NA	As Above	NA		
	•	Overhead Tank capacity	NA	As Above	MR		
15	Exit S	ignage.	Required	Provided	MR		
16	Provision of Lifts.[Provided & Maintained by Mall management]						
		Pressurization of Lift Shaft	NA	· NA	NA		
	0	Pressurization of Lift lobby	NA	NA	NA		
	0	Communication In lift Car	NA	NA	NA		
	0	Fireman's Grounding Switch	n NA	NA	. NA		
	0	Lift Signage	NA	NA	NA		
17	Stand	by power supply	NA	NA	NA		
18	Refuge Area.[Provided & Maintained by Mall management]						
	>	Total Area	NA	NA	NA		
	>	Location	NA	NA NA	NA		
19	Fire Control Room [Provided & Maintained by Mall management]						
		Detector System Panel	NA	NA	NA		
		Flow Switch Panel	NA	NA ·	NA		
		PA System Panel	NA	NA	NA		
	•	Batter backup	NA	NA	NA		
	•	Building Floor Plans	NA	NA	NA		
20	Special for Proany:	Fire Protection Systems tection of special Risks, if	NA	NA	NA		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2018/EH/WZ/1856 dated 08.08.2018. Renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Ajay Kumar Sharma

Designation ADO (Rohini)

Joseph Designation AD Whyn So lote,

o (102)

PT letter is fruit up for Kind

Derycal and signature please.

DO (NW) Sylver)
Dol Rahme F