GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2021/SZ/ 309

Dated: 1.3./2021

FIRE SAFETY CERTIFICATE

Certified that M/s Golden leaf, (A unit of Golden Tulip Hotel) A-1/296, Safdarjung Enclave, New Delhi 110029 Comprised of Ground plus three upper floors was issued Fire Safety Certificate by this department vide letter No. F6/MS/DFS/GH/2018/SZ/945 dated 08-05-2018 for 14 Guest Rooms. The premise was re-inspected by the officer concerned of this department on 29/07/2021 in the presence of Sh. Lokesh Pahwa and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential & Lodging", Group-A" with effect from the date of issue 13 / 2/2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13 8 21 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. M/s Golden leaf, A-1/296, Safdarjung Enclave, New Delhi 110029.
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi–110049. (Ref. MHA Portal 2021060113610 dated 09.07.2021)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 7. The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or before 30/09/2021 in compliance to the notification dated 27/05/2019 an as approved and now have been extended till 30.09 2021 vide Directorate of Local Bodies, UDD, GNCT of Delhi letter no. F5 (189)/AD/LB/2016/359-374 dated 29.06.2021.

| | INSPECTION REPORT | | | | | |
|--------|---|--------------------------------------|-------------------------|-------------|--|--|
| 1 | Name & Address of the Building M/s Golden leaf, A-1/296, Safdarjung Enclave, | | | | | |
| | | New Delhi 11 | | g Liiciave, | | |
| 2 | Type of Occupancy | | | | | |
| 3 | Building Comprised of | Residential, "Group-A" (Guest House) | | | | |
| 4 | Type of Case | Ground + 03 upper floors. Renewal | | | | |
| 5 | Details of Previous NOC | | H/2018/SZ/945 dated 08- | 05 2019 | | |
| 6 | Fire Safety Directives Letter No | Nil | 1/2010/32/943 dated 08- | -03-2018 | | |
| 7 | Date of Inspection | 29-07-2021 | | | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | | | |
| 9 | Name & Designation of Officers | Sh. Lokesh Pahwa (Manager) | | | | |
| | from the building side | I mirra (irialiago) | | | | |
| 10 | Year of construction | 1994 (Total 14 Guest Room) | | | | |
| 11 | Applicant letter No. | | 21060113610 dated 09.0 | 7 2021 | | |
| S. No. | Minimum standards on Fire Prevention | Old NOC | Provided at Site | Remarks | | |
| | and Fire Safety U/R 33 | Requirements | | MR/NMR | | |
| 1 | Access to Building. | | | | | |
| | Road width | Required | 6 mtr | MR | | |
| | Gate width | -NA- | -NA- | -NA- | | |
| | Width of internal road | -NA- | -NA- | -NA- | | |
| 2 | Number, width, type & arrangement of exits. | 3 | | | | |
| | a) Number of Staircase | | | | | |
| | Upper floors. | Required | One | MR | | |
| | Basement floor. | -NA- | -NA- | -NA- | | |
| | b) Width of Staircase | | | | | |
| | Upper floors | 1.25 mtr | 1.25 mtr | MR | | |
| | Basement floor | -NA- | -NA- | -NA- | | |
| | c) Protection of exits | | | | | |
| | Fire check door | -NA- | -NA- | -NA- | | |
| | Pressurization | -NA- | -NA- | -NA- | | |
| | d) No. of continuous staircase to terrace | Required | One | MR | | |
| | e) Width of corridor | -NA- | -NA- | -NA- | | |
| | f) Door size | 1 m | 1 m (Final exit) | MR | | |
| 3 | Compartmentation. | | | 5 | | |
| | Fire check door. | -NA- | -NA- | -NA- | | |
| | Sealing of electrical shafts. | Required | Provided | MR | | |
| | Fire rating of shaft door. | -NA- | -NA- | -NA- | | |
| | Water curtain | -NA- | -NA- | -NA- | | |
| | Fire dampers. | -NA- | -NA- | -NA- | | |
| 4 | Smoke Management system. | | | | | |
| | Basement | 30 ACPH | -NA- | -NA- | | |
| - | • Upper floors | 12 ACPH | Exhaust fan provided | MR | | |
| 5 | Fire Extinguishers. | | | | | |
| | Total numbers | Required | 12 Nos | MR | | |
| | • Types | ABC / CO2 | CO2 & ABC | MR | | |
| | ISI Marking | ISI marked | Provided | MR | | |
| 6 | First Aid Hose Reels. | | | | | |
| | Total numbers on each floor. | -NA- | Provided | MR | | |
| | Length of hose-reel hose. | -NA- | Provided | MR | | |
| | | | | | | |

M/30

| 7 | Automatic fire detection & alarming system. | The state of the s | | |
|--|---|--|------------|-------|
| | Type of detectors | -NA- | Smoke type | -NA- |
| | Location of Main Panel | | | -NA- |
| | Location of Repeater Panel | -NA- | | -NA- |
| | | -NA- | | -NA- |
| | Hooter's location | -NA- | | -NA- |
| 8 | MOEFA | NA | | NA |
| 9 | Public Address System | | | MR |
| 10 | Automatic Sprinkler System | | 1101100 | IVIIC |
| | Basement | -NA- | -NA- | -NA- |
| | Upper floors | -NA- | -NA- | -NA- |
| | Sprinkler above false ceiling | In (UBBL-2016) till 30/09/2021 Type of detectors | -NA- | |
| 11 | Internal Hydrants. | P | | 1111 |
| | Size of Riser/Down-comer | -NA- | -NA- | -NA- |
| | Number of Hydrant per floor | -NA- | | -NA- |
| | | -NA- | | |
| 12 | Yard Hydrants. | 1477- | -11/1- | -NA- |
| 1.24 | | NTA | NT A | - |
| | · · | | 20 2 0 5/2 | -NA- |
| 12 | | -NA- | -NA- | -NA- |
| 13 | Pumping arrangements. | | | |
| | | | | |
| | | | | -NA- |
| and the second | | | | -NA- |
| The same of the sa | | | | -NA- |
| | | | | -NA- |
| | | | | -NA- |
| and the second second | Standby Pump head | | | -NA- |
| | | | | -NA- |
| | | | | -NA- |
| - | | -NA- | -NA- | -NA- |
| - | | 7.7.1 | | |
| | | | | -NA- |
| | | | | -NA- |
| | | | | -NA- |
| 14 | | -NA- | Provided | -NA- |
| 4.4 | | D.T.A | D.T.A. | |
| | | | | -NA- |
| | | | | -NA- |
| | | | | -NA- |
| and the second | | | | -NA- |
| 15 | Exit Signage. | | | -NA- |
| | Provision of Lifts. | Required | riovided | MR |
| | | -NA- | _N A | -NA- |
| | | | | -NA- |
| | | | | MR |
| | | | | MR |
| | | | | -NA- |
| 17 5 | Standby Power Supply | | | |
| | Refuge Area | rodanea | riovided | MR |
| - | Total area | -NA- | -NA- | NTA |
| | • Location | | | -NA- |
| 19 I | | -NA- | -NA- | -NA- |
| 17 1 | Fire Control Room. | | | |
| | Detector system panel. | -NA- | -NA- | -NA- |

| Til itali nomal | -NA- | -NA- | -NA- |
|--|----------------------|---|---|
| PA system panel.Battery backup. | -NA- | -NA- | -NA- |
| | -NA- | -NA- | -NA- |
| | -NA- | -NA- | -NA- |
| Special Fire Protection System for the Protection of special Risk, if any. | | | |
| | Building floor plan. | PA system panel. Battery backup. Building floor plan. NA- NA- | Flow switch panel. PA system panel. Battery backup. |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/GH/2018/SZ/945 dated 08-05-2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Design: ADO (BCP)

As approved, F.T. totter in pritup
Signature P)

6/8/204