GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ \ 89

Dated: 1 9 / 2 /2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Haldiram Restaurant located at Ground and First floor at R-11, Block –R, Plot No 11, Main Market, Green Park, New Delhi-110016, in the building comprised of Ground + 02 floors (owner/occupied by (A Unit of Haldiram Marketing Pvt Ltd) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 18/08/2021 in the presence of Mr. Arvind Kumar (Manager)and that the premise is fit for occupancy class Group–D Assembly (Restaurant at Ground and First floor only) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 19/2021 at New Delhi by

ATUL GARG) DIRECTOR

Copy to: -

- 1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049
- 2. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi–110016 (Ref. MHA Portal ID NO 2021081617836 dated 16/08/2021)
- 3. M/s Haldiram Restaurant located at R-11, Block R- Plot No 11, Main Market, Green Park, New Delhi-110016.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		INSP	ECTION REPORT				
1	Name	& Address of the Building	Haldiram Restaurant (A Unit of Haldiram Marketing				
			Pvt Ltd) located at R-11, Block- R, Plot No 11, Main				
2			Market, Green Park, New Delhi-110016 Assembly Building (Group-D)				
3	- 1	ng Comprised of	Ground + 02 upper flo				
3	Dullai	ing Comprised of	(Restaurant at Ground & First Floor only)				
4	Туре	of Case	New Case				
5	Detail	s of Previous NOC	Nil				
6	Fire Sa	afety Directives Letter No	Nil				
7	Date o	of Inspection	18/08/2021				
8	Name	of the Inspecting Officers	DO (South) & ADO (BCP)				
9		& Designation of Officers	Mr. Arvind Kumar (Manager)				
10		he building side	2019				
10		of construction	2018				
11		cant letter No.	MHA Portal ID NO 2021081617836 dated 16/08/2021				
S. No		num standards on Fire ntion and Fire Safety U/R 33	UBBL /NBC- 2016 Requirements	Provided at Site	Remarks NR/NMR		
1	Access to Building.						
	•	Road width	As per MPD-2021	06 m	MR		
	•	Gate width	4.5 m	About on road	MR		
	•	Width of internal road	-N/A-	-N/A-	-N/A-		
2	Numl	ber, width, type & arrangement	of exits.				
	a) Number of Staircase						
	>	Upper floors.	02 Nos	Provided	MR		
	>	Basement floor.	-N/A-	-N/A-	-N/A-		
	b) W	idth of Staircase					
	>	Upper floors	2 m & 1.50 m	2 m & 1.50 m	MR		
	>	Basement floor	-N/A-	-N/A-	-N/A-		
	c) Protection of exits						
	Fire check doorPressurization		Required	Provided	MR		
			-N/A-	-N/A-	-N/A-		
	d) No. of continuous staircase to terrace		02 nos.	02 nos.	MR		
	e) W	Vidth of corridor	-N/A-	-N/A-	-N/A-		
	f) D	oor size	2 exits, 1.50 m x 2	Provided	MR		
3	Compartmentation.						
		Fire check door.	Required	Provided	MR		
		 Sealing of electrical shafts. 	Required	Provided	MR		
		• Fire rating of shaft door.	Required	Provided	MR		
		Water curtain Fire damners	-N/A-	-N/A-	-N/A-		
		Fire dampers.	-N/A-	-N/A-	-N/A-		
4.	Smo	ke Management system.	L				
	•	Basement	-N/A-	-N/A-	-N/A-		
	•	Upper floors	12 ACPH	Exhaust fan provided	MR		
5.	Fire	Extinguishers.		1111	1.00		
	•	Total numbers	10 nos.	Provided	MR		
	•	Types	ABC / CO ₂	ABC & CO ₂	MR		
	•	ISI Marking	ISI marked	Provided	MR		

	 Length of hose-reel hose. 	30m	Provided	MR			
	Nozzle Diameter	5mm	Provided	MR			
7 Automatic fire detection & alarming system.							
	Type of detectors	-N/A-	Smoke type	-N/A-			
	Location of Main Panel	-N/A-	Ground Floor	-N/A-			
	Location of Repeater Panel	-N/A-	-N/A-	-N/A-			
	Alternate source of powerHooter's location	-N/A-	Provided	-N/A-			
	1100tel 3 location	-N/A-	Each floor	-N/A-			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	-N/A-	-N/A-	-N/A-			
10.	Automatic Sprinkler System						
	Basement.	-N/A-	-N/A-	-N/A-			
	Upper floors	-NA-	Provided	-NA-			
	Sprinkler above false ceiling	-NA-	-NA-	-NA-			
11.	Internal Hydrants.			0			
	Size of Riser / Down-comer	100 mm	Provided	MR			
	Number of Hydrant per floor	Required	01 no	MR			
	Hose box.	Required	01 no	MR			
12.	Yard Hydrants.						
	Total number of hydrants.	-N/A-	-N/A-	-N/A-			
	Hose box.	-N/A-	-N/A-	-N/A-			
13.	Pumping arrangements.						
	Ground Level						
	Discharge of main pump.	-N/A-	-N/A-	-N/A-			
	Head of main pump.	-N/A-	-N/A-	-N/A-			
	Number of main pumps.	-N/A-	-N/A-	-N/A-			
	Jockey Pump output.	-N/A-	-N/A-	-N/A-			
	Jockey Pump head.Standby Pump output.	-N/A-	-N/A-	-N/A-			
	Standby Pump output.Standby Pump head.	-N/A-	-N/A-	-N/A-			
	> Auto Starting/Manual	-N/A-	-N/A-	-N/A-			
	stopping.	-N/A-	-N/A-	-N/A-			
	Pump house access.	-N/A-	-N/A-	-N/A-			
-	Terrace Level						
	Discharge of pump.	450 LPM	2 x 450 LPM	MR			
	Head of pump.	40 m	40 & 30 m	MR			
	Power supply.	Required	Provided	MR			
	Auto starting of pump.	Required	Provided	MR			
14.	Captive water storage for firefighting.						
	Underground tank capacity.	-N/A-	-N/A-	-N/A-			
	Draw-off connection.	-N/A-	-N/A-	-N/A-			
	Fire Service Inlet.	-N/A-	-N/A-	-N/A-			
	Access to tank.	-N/A-	-N/A-	-N/A-			
	 Overhead tank capacity. 	20,000 ltrs	Provided	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						
V.	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-			
	 Pressurization of lift lobby. 	-N/A-	-N/A-	-N/A-			
	• Communication in lift car.	-N/A-	-N/A-	-N/A-			
	• Fireman's switch.	-N/A-	-N/A-	-N/A-			

	•	Lift signage.	-N/A-	-N/A-	-N/A-			
17	Stand	by Power Supply	Required	Provided	MR			
18.	Refuge Area							
	•	Total area	-N/A-	-N/A-	-N/A-			
	•	Location	-N/A-	-N/A-	-N/A-			
19.	19. Fire Control Room.							
	•	Detector System Panel.	-N/A-	-N/A-	-N/A-			
	•	Flow Switch Panel.	-N/A-	-N/A-	-N/A-			
	•	PA system Panel.	-N/A-	-N/A-	-N/A-			
	•	Battery backup	-N/A-	-N/A-	-N/A-			
	•	Building floor plan	-N/A-	-N/A-	-N/A-			
20.	_	Il Fire Protection System for the ction of special Risk, if any.	-N/A-	-N/A-	-N/A-			

It is to submit that the same was received earlier in this department vide MHA Portal application no 2021012109811 dated 10.04.2021 for consideration of FSC for eating house establishment/ restaurant at GF,FF & SF in the building comprised of ground and two upper floors. Accordingly, the inspection of the premise was conducted to verify the fire safety measures as recommended under UBBL-2016/ NBC Part IV and issued certain shortcomings/ observations vide letter of even no 346 dated 16.08.2021.

Now, the case is resubmitted by the applicant on MHA Portal no 2021081617836 dated 16.08.2021 for issuance of FSC for eating house establishment/ restaurant for Ground and First only in the building comprised of ground and two upper floors. The height up to the first floor of the restaurant occupancy is 8.50m as mentioned in the MHA Portal.

Accordingly, the Fire protection systems provided in the building were tested/ checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: - Sh. S.K Dua Designation: - DO (South) Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

Dy. CFO (SZ)

340 C. F.O.

2000