GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/ 6 3 7

Dated: 24 8 21

FIRE SAFETY CERTIFICATE

Certified that the Govt. Co-ed Sr. Sec. School, Bindapur Extn., New Delhi-110059 comprised of three blocks each block is having ground plus one upper floor, owned/occupied by Govt. Co-ed Sr. Sec. was issued Fire Safety Certificate by this department F.6/DFS/MS/School/2018/SZ/691 dated 13/04/2018. The school building was re- inspected by the officer concerned of this department on 09/08/2021 in the presence of Sh. Raj Kumar (Vice Principal) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 24/8/21 at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

KP4

Copy to:-

- The Principal,
 Govt. Co-ed Sr. Sec. School,
 Bindapur Extn., New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

School building is comprised of three blocks. Each block is having ground plus one upper floor. INSPECTION REPORT Name & address of the building: Govt. Co-ed Sr. Sec. School, Bindapur Extn., New Delhi-110059 Type of Occupancy Educational 3. Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2018/SZ/691 dated 13/04/2018 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 09/08/2021 7. Name of Inspecting Officer A.D.O. R.K. Yadav 8. Name and designation of officers From the building side Sh. Raj Kumar (Vice Principal) 9. Year of Construction 2004-2013 10. Applicant's letter No. G Co ED SSS Bindapur Extn/2021/82 dated 28/06/2021 S. No. Minimum Standards on fire prevention and Requirement Provided at Remarks fire safety U/R 33 site MR/NMR 1. Access to building Road width Accessible 06 m 10 m MR 4.5 m Directly accessible M/R Gate width N/A from road N/A Width of internal road N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 06 no.'s Provided MR Basements N/A N/A N/A b. Width of staircases Upper Floor 1.50, 1.50, 1.45, 150 m & .75 m MR Basements 1.41, 1.40 & 1.40 m N/A N/A N/A c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to N/A Four N/A terrace 1.77, 1.56 & 1.52 m 1.50 m MR Width of Corridor 1.0 to .95 m & 1.0 MR, being old case 1.0 m Door Size to 1.17 m 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System N/A N/A N/A Basements Natural Ventilation MR Upper floors Required provided 5. Fire Extinguishers Total numbers 25 No's Provided MR ABC/CO₂ type Types Provided MR ISI marked IS marking ISI marked MR First-Aid Hose Reels 6. Total numbers on each floor N/A N/A N/A N/A Length of hose reel hose N/A N/A

NT/A

7.	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A N/A	N/A		
	Hooters' Location	N/A	N/A N/A			
8.	MOEFA	N/A	N/A N/A	N/A N/A		
	THOUSE IN	IN/A	N/A	N/A		
9.	Public Address System	N/A	Provided	N/A		
10.	Automatic Sprinkler System					
	Basement	N/A	N/A	N/A		
	 Ground Floor 	N/A	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11.	Internal Hydrants			12		
	 Size of riser/down-comer 	N/A	N/A	N/A		
	 Number of hydrants per floor 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
-	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	The second secon				
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/Manual Stopping	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	Pump House Access	1377	1 1/1 1	14/14		
	• Terrace level	27/4				
	Discharge of pump	N/A	N/A	N/A		
	Head of the pump	N/A	N/A	14/11		
	Power SupplyAuto Starting of pump	N/A		N/A		
	Auto starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A N/A	N/A		
	 Overhead Tank capacity 					
5.	Evit Signage	N/A	N/A	N/A		
o.	Exit Signage.	N/A	N/A	N/A		
6.	Provision of Lifts. (No Lift)					
	 Pressurization of Lift Shaft 	N/A	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	 Fireman's Grounding Switch 	N/A	N/A	N/A		
	• Lift Signage					
7.	Standby noway awaly	N/A	N/A	N/A		
1.	Standby power supply	N/A	N/A	N/A		
8.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	Location	3. >				

19.	Fire Control Room	rol Room				
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2018/SZ/691</u> dated 13/04/2018 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Dy cio de la F. F.

FT hetter is put up to

Dycro(sz)

18 8 Zos