GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI**

0-66

No. F6/DFS/MS/EH/WZ/2021/ 241

Dated: 2 2/ 9 /2021

FIRE SAFETY CERTIFICATE

Certified that the Teo The Dineroom, Shop No- 37, Club Road, West Punjabi Bagh, New Delhi-110026 located at Second & Third Floor in a building comprised of Basement, Ground & Three Upper Floors, owned/Occupied by M/s.(A unit of TSRA Tradecorp LLP) fire safety Certificate was issued by this department Vide letter no. F6/DFS/MS/EH/2018/2035 dated 05/09/2018 (Earlier FSC was Issued in the name of Masabaa The Treasury A unit of VSR Foods India). The Premises was re-inspected by the officer concerned of this department on 14/09/2021 in the presence of Sh. Shaan Sarin (owner) found that the said restaurant have deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the said Floor is fit for occupancy class "Assembly" Group D (Second & Third Floor Only) with effect from 121 9/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Condition Mentioned below.

Issued on . 2.21.5.1.2........ at New Delhi by.

(Dharampal Bhardwaj) Dy. Chief Fire Officer

Delhi Fire Service

Copy to: -

- 1. M/s TSRA Tradecorp LLP Teo the Dineroom, Shop No- 37, Club Road, West Punjabi Bagh, New Delhi-110026. (Ref. Online ID. No. 2021070614728 dated 07/07/2021).
- 2. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi.
- 3. Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi -110027.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. This NOC is valid for Second & Third Floor only.

INSPECTION REPORT

1. Name & address of the building : Teo, The Dineroom, Shop No. 37,

Club Road, West Punjabi Bagh, New Delhi-110026.

(Earlier FSC was Issued in the name of Masabaa The **Treasury (A unit of VSR Foods India))**

2. Type of Occupancy : Assembly 3. Type of Case : Renewal

4. Details of previous NOC

: F6/DFS/MS/EH/2018/2035 dated 05/09/2018

5. Fire Safety directives letter No : Nil

6. Date of inspection : 14/09/2021

7. Name of the Inspecting Officers : Sarabjeet Singh ADO(MN)

8. Name and designation of officers

from the building side

: Sh Shaan sarin

9. Year of Construction

:2008-2009(As per previous Inspection report dtd.27/08/2018)

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement previous In report dtd.2	ent/ As per aspection	Provided at	site	Remarks MR/NMI
l .	Access to building	_		*		
	 Road width 	06 mts		Provided		MR
	Gate width	Required		Provided		MR
	Width of internal road	N/A		N/A		N/A
2	Number, Width, Type & Arrangemen	t of Exits				
	a. Number of staircases			a 160 m		
	 Upper Floors 	02		Provided		MR
	Basements	N/A		N/A		N/A
	b. Width of staircases					
	• Upper Floors	Old Case	1X106 cm	s,1X152 cms	MR	being old case
	Basements	Required	e:	Provided		MR
	c. Protection of exits					į.
	Fire check door	NR		NR		NR
	Pressurization	NR	7	NR		NR
	e. No. of continuous staircases to terrace					
	f. Width of Corridor	Required		Provided	,	MR
	g. Door Size	Old case	209cms,	1 m provided	MF	theing old cas
	Compartmentation.					
	Fire check door	NR		NR		NR
	 Sealing of electrical shafts 	Required		Provided		MR
	 Fire Rating of shaft door 	N/A		N/A		N/A
	Water Curtain	N/A		N/A		N/A
	• Fire Dampers	N/A		N/A		N/A
-	Smoke Management System.					
	Basements	30 a/c per h	our	N/A		N/A
	• Upper floors	12 a/c per hour		Provided		MR

5	Fire Extinguishers			-		
	Total numbers	08	12 Provided	MR		
	 Types 	CO ₂ , ABC type	Provided	MR		
7	IS marking	ISI Marked	Provided	MR		
5	First-Aid Hose Reels.					
	Total numbers on each floor	02	Provided	MR		
	 Length of hose reel hose 	30 m Required	Provided	MR		
	Nozzle diameter	5mm	Provided	MR		
C.	Automatic fire detection and alarming system.					
	Type of detectors	Smoke	Provided	MR		
	 Location of Main Panel 	Required	Provided	MR		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	• Alternate source of power	Required	Provided	MR		
	Hooters' Location	Each floor	Provided	MR		
	MOEFA	Required	Provided	MR		
	Public Address System.	NR	NR	NR		
0	Automatic Sprinkler System.					
*	Basement	N/A	N/A	N/A		
	Upper Floor	NR	NR	NR		
	Sprinkler above false ceiling	NR	NR	NR		
1	Internal Hydrants					
	Size of riser/down-comer	NR	NR	NR		
	Number of hydrants per floor	NR P	NR	NR		
	Hose Box	NR	NR	NR		
2	Yard Hydrants.	, a				
	Total number of hydrants	NR	NR	NR		
	Hose Box	NR	NR	NR		
3	Pumping Arrangements.	-10		s		
	Ground Level			s.		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level			21		
	Discharge of pump	450 LPM	Provided	MR		
	> Head of the pump	30 M	Provided	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump					

14	Captive Water Storage for fire figh	ting			
15	 Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. 	NR NR NR NR 10,000 ltrs Required	NR NR NR NR Provided Provided	NR NR NR NR MR	
16	Provision of Lifts.				
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A N/A N/A	N/A N/A N/A N/A	N/A N/A N/A	
17	Standby power supply	N/A	N/Λ	N/A	
18	Refuge Area.	Required	Provided	MR	
9	Total Area Location	N/A	N/A	N/A	
9	Fire Control Room		N/Λ	N/A	
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	N/A N/A N/A N/A	N/A N/A N/A	N/A N/A N/A	
) S	Special Fire Protection Systems for Protection of special Risks, if any:	N/A N/A	N/A N/A	N/A N/A	

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings issued by this department vide letter no. F6/DFS/MS/EH/WZ/2021/355 dated

Keeping in view the deemed compliance of the minimum standards of fire prevention & fire safety required under the rules, the NOC Vide letter no. F6/DFS/MS/EH/WZ/2018/2035 dated 05/09/2018 (Earlier FSC was Issued in the name of Masabaa The Treasury {A unit of VSR Foods India}) recommended to renewal of Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010.

D = (MESS/2)

16/9/2021

Signature of the Inspecting Officer

Name: Sarabject Singh Designation: ADO (MN)

DGG (uz)

J779/2021