GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2021/ 476

Dated, 3.0./.9../2021

FIRE SAFETY CERTIFICATE

Issued on 50/9/2021 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal ID No. 2021070614751 dated 06/07/2021)

2. M/s United Coffee House situated at R-03, Upper Ground Floor, Epicuria TDI Mall, Nehru Place Metro Station, New Delhi -110019

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010.

1	Name & Address of the Building M/s United Coffee House at P.03					
	Traine & Address of the Building	M/s United Coffee House, at R-03, Upp Ground Floor, Epicuria TDI Mall, Nehru pla				
2	TCO	Metro Statio	on, New Delhi 110019)		
3	Type of Occupancy	Group-D As	g house)			
3	Building Comprised of	Lower ground floor & upper ground floor				
-	TT 0.0	(PD area at Nehru Place Metro Station)				
4	Type of Case	Renewal				
5	Details of Previous NOC	F.6/DFS/MS/EH/2018/SZ/1732 dated 25/07/2018				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	24/07/2021				
8	Name of the Inspecting Officers	umar ADO (BCP)				
9	Name & Designation of Officers	Sh. Akash Kalra (owner)				
	from the building side	The state (Owner)				
10	Year of construction	2008-09				
11	Applicant letter No.	Online No. 2021070614751 dated 06/07/2021				
S. No.	Minimum standards on Fire Prevention	NBC / BBI	Provided at Site	D		
	and Fire Safety U/R 33	Requiremen	CITCLE SEE VIEW			
1	Access to Building.			MR/NMI		
		The same of the sa	F6/DFS/MS/2019/SZ/1712 dated 03/09/2019			
	1 Toda Widili	Restt. within	As above	MR		
	• Gate width	TDI Mall	As above	N/A		
	Width of internal road		A = -1-	IN/A		
2	Number, width, type & arrangement of e	xits.	As above	N/A		
	a) Name of the second					
	Upper floors.	Provided 8	Maintained by TDI M	intained by TDI Mall /DMRC		
	Basement floor.	NA N/A	Restt. at Upper GF	NA		
	b) Width of Staircase	N/A	As above	N/A		
	> Upper floors	Provided &	Maintained by TDI M	all /DMRC		
	Basement floor	NA	Restt. at Upper GF	NA		
			N/A As above			
	c) Protection of exits Fire check door	Provided & Maintained by TDI M		all /DMRC		
	THE CHECK GOOD	N/A	N/A	N/A		
	> Pressurization	N/A	N/A	N/A		
	d) No. of continuous staircase to terrace	Required	One	MR		
	e) Width of corridor	N/A	N/A	N/A		
	f) Door size	2 exits	The state of the s	MR (old case		
		(2m & 1 m)	Degradad			
3	Compartmentation.		Maintained by TDI Ma	II./DMDC		
	Fire check door.	N/A	Provided & Maintained by TDI Ma			
	 Sealing of electrical shafts. 	The same of the sa	N/A	N/A		
	or vivourous sitalis.	N/A	DI/A			
	• Fire rating of shaft door	NT/A	N/A	N/A		
	The fathing of shall door.	N/A	N/A	N/A		
	 Water curtain 	N/A	N/A N/A			
4	Water curtainFire dampers.	N/A N/A	N/A N/A N/A	N/A N/A N/A		
4	 Water curtain Fire dampers. Smoke Management system.	N/A N/A	N/A N/A	N/A N/A N/A		
4	 Water curtain Fire dampers. Smoke Management system. Basement 	N/A N/A	N/A N/A N/A	N/A N/A N/A MI/DMRC		
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors 	N/A N/A Provided &	N/A N/A N/A Maintained by TDI Ma	N/A N/A N/A II /DMRC		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers.	N/A N/A Provided & 30 ACPH	N/A N/A N/A N/A Maintained by TDI Ma	N/A N/A N/A N/A N/A N/A N/A		
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers 	N/A N/A Provided & 30 ACPH	N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provided	N/A N/A N/A II /DMRC		
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos	N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provided	N/A N/A N/A N/A N/A MI /DMRC N/A MR		
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂	N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide	N/A N/A N/A N/A N/A N/A MI /DMRC N/A MR		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided	N/A N/A N/A N/A N/A N/A MR MR		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels.	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided	N/A N/A N/A N/A N/A N/A MR MR		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03	N/A N/A N/A N/A N/A N/A MR MR MR MR DMRC		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Ma	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided intained by TDI Mall /I Provided	N/A N/A N/A N/A N/A N/A N/A MR		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Ma One	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided intained by TDI Mall /I Provided Provided	N/A		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Ma One 30m 5mm	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided intained by TDI Mall /I Provided Provided Provided	N/A		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Ma One 30m 5mm	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided intained by TDI Mall /I Provided Provided Provided Provided Alaintained by TDI Mall	N/A		
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system	N/A N/A Provided & 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Ma One 30m 5mm	N/A N/A N/A N/A Maintained by TDI Ma N/A Exhaust Fans Provide 10 Nos ABC-07 & CO ₂ - 03 Provided intained by TDI Mall /I Provided Provided Provided	N/A		

	Location of Reporter Page 1				
	Ecoulon of Repeater Panel	N/A	As above	N/A	
	Alternate source of powerHooter's location	N/A	As above	N/A	
8	MOEFA	N/A	As above	N/A	
9		Required	Provided	MR	
10	Public Address System	N/A	N/A	N/A	
10	Sprinkier System	Provided & Maintained by TDI Mall /DMRC			
	Basement	N/A	N/A	N/A	
	 Ground floor. 	N/A	N/A	N/A	
4.4	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants.	Provided & Maintained by TDI Mall /DMRC			
	 Size of Riser/Down-comer 	N/A	N/A		
	 Number of Hydrant per floor 	N/A	N/A	N/A	
	Hose box.	N/A	N/A	N/A	
12	Yard Hydrants.	1071	I IN/A	N/A	
	 Total number of hydrants. 	N/A	NT/A		
	Hose box.	N/A	N/A	N/A	
13	Pumping arrangements.	IN/A	N/A	N/A	
	Ground Level	Deprised 10 14			
	Discharge of main pump.	1900 TPM	aintained by TDI Ma	all /DMRC	
	Head of main pump.	1800 LPM	Provided	MR	
	Number of main pumps.	70 m	Provided	MR	
	Jockey Pump output.	02	Provided	MR	
	Jockey Pump head.	180 LPM	Provided	MR	
	Standby Pump output.	70 m	Provided	MR	
	Standby Pump head.	1800 LPM	Provided	MR	
	Auto Starting/Manual Stopping.	70 m	Provided	MR	
	Pump house access.	Required	Provided	MR	
	Terrace Level	Required	Provided	MR	
		Provided & Maintained by TDI Mall /DMRC			
	- somme go of pump.	N/A	As above	N/A	
	rieda of pullip.	N/A	As above	N/A	
	Tower suppry.	N/A	As above	N/A	
14	Auto starting of pump.	N/A	As above	NI/A	
17	Captive water storage for fire fighting.	ghting. Provided & Maintained by TDL Mall (D) (D)			
	Underground tank capacity.	N/A	50,000 ltr	N/A	
	Draw-off connection.	N/A	Provided	N/A	
	Fire Service Inlet.	N/A	Provided	N/A	
	recess to talk.	N/A	Provided	N/A	
15	Overhead tank capacity.	NA	NA	NA	
16	Exit Signage.	Required	Provided	MR	
	Provision of Lifts.	Provided & Maintained by TDI Mall /DMRC			
	Pressurization of lift shaft.	As above	N/A	N/A	
1.5	Pressurization of lift lobby.	As above	N/A	N/A	
	 Communication in lift car. 	N/A	N/A	N/A	
	• Fireman's switch.	N/A	N/A	N/A	
	• Lift signage.	N/A	N/A		
7	Standby Power Supply	Required	Provided	N/A	
8	Refuge Area	- James	TTOVIUCU	MR	
	Total area	DT/A			
	• Location	N/A	N/A	N/A	
9	Fire Control Room.	N/A	N/A	N/A	
	Detector system panel.	Provided & Main	ntained by TDI Mall	/DMRC	
	Flow switch panel.	N/A	N/A	N/A	
	PA system panel.	N/A	N/A	N/A	
	Battery backup.	N/A	N/A	N/A	
		N/A	N/A	N/A	
0	Building floor plan. Special Fire Protection S.	N/A	N/A	N/A	
	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A		
		T 4/ T F	IN/A	N/A	

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/2018/SZ/1732 dated 25/07/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Designation: ADO (BCP)

As approved, f.T. tetra en fortin