GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2021/ 323

Dated: 01 11 21

FIRE SAFETY CERTIFICATE

Certified that the **M/s. Azora** (A unit of Azora Hospitality LLP) running at Upper Ground Floor in a building comprised of basement, stilt, upper ground plus three upper floors located at A-19, Meera Bagh, Paschim Vihar, New Delhi, owned/occupied by Azora Hospitality LLP, was inspected by the officer concerned of this department on 09.10.2021 in presence of Sh. Naveen (V.P.) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- 'D' Assembly (restaurant) at **Upper Ground Floor only** with effect from O(1 + 1 + 2 + 1) for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 01 11 21 at New Delhi by.

Director Delhi Fire Service

Copy to:-

- Sh. Naveen,
 M/s. Azora (A unit of Azora Hospitality LLP),
 First Floor, A-19, Meera Bagh, Paschim Vihar, New Delhi.
- 2. The Deputy Health Officer, North DMC, Rohini Zone, Rohini, Sector-5, New Delhi.
- The Joint Commissioner of Police (Lic), 1st Floor, Police Station Defence Colony, New Delhi- 110024.

CONDITIONS

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. All the means of escapes /exits shall not be locked/bolted/blocked at any time for safe evacuation of the occupants in case of any emergency.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

			1/4			
0		INSPECTION REPORT				
	1.	Name & address of the building	 M/s. Azora (A unit of Azora Hospitality LLP), located at A- 19, Meera Bagh, Paschim Vihar, New Delhi. 			
	2,	Type of Occupancy	: Assembly (Restaurant)			
	3.	Type of Case	: New Case			
	4.	Details of previous NOC	: N/A			
	5.	Fire Safety directives letter No	: N/A.			
	6.	Date of inspection	: 09.10.2021			
	7	. Name of the Inspecting Officer	s : Aman Kumar Lathar, ADO (JWP)			
	8	••				
	9	9. Year of Construction	: 2019 (as submitted on MHA portal)			
	۱	0. Applicant's letter No.	: ID- 2021083019518			

The said restaurant is running at Upper Ground Floor in a building comprised of basement, stilt, upper ground plus three upper floors.

0.	- Minimum Standards on fire prevention and fire safety U/R 33	Requirement as UBBL / NBC-IV	Provided at site	Remarks MR/NMR			
	Access to building		D 11.1				
	Road width	12 mts	Provided	MR			
	• Gate width	4.5 mts	Provided	MR			
	• Width of internal road	NA	NA	NA			
2	Number, Width, Type & Arrangement of Exits						
-	a. Number of staircases	-	-	-			
	Upper Floors	02 Nos.	Provided	MR			
	Basements	N/A	N/A	Restaurant running at UGF only			
	b. Width of staircases	-	-	-			
	Upper Floors	1.50 mts each	Provided	MR			
	Basements	N/A	N/A	Restaurant running at UGF only			
	c. Protection of exits	-	-				
	• Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	e. No. of continuous staircases to terrace	01	01	MR			
	g. Width of Corridor	N/A	N/A	N/A			
	h. Door Size	1.5 mts. (02 nos.)	Provided	MR			
3	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	• Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	• Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.		and water and the second state of the second s				
	 Basements 	30 a/c per hour	N/A	Restaurant running at UGF only			
	• ground floor	12 a/c per hour	Provided	MR			

		RIA	and the second se	5- 			
5	Fire Extinguishers		Provided	M			
	Total numbers	06	a second to the second s	MR			
	Types	CO ₂ , ABC type	Provided	MR			
	IS marking	ISI marked	Provided				
6	First-Aid Hose Reels.		Provided	MR			
	 Total numbers on each floor 	01	Sec. 1993	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	Extra construction of the second			
7	Automatic fire detection and alarming system.						
	Type of detectors	Smoke & Heat		MR			
	Location of Main Panel	Required at GF	Provided				
		Required	Provided	MR			
	 Location of Repeater Panel 	Required	Provided	MR			
	 Alternate source of power 	Required	Provided	MR			
	Hooters' Location	-	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Provided				
10	Automatic Sprinkler System. Basement	N/A	Restaurant running at UGF only	N/A			
	Entire Restaurant	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
	-						
11	Internal Hydrants	100 mm	Provided	MR			
	Size of riser/down-comer		Provided	MR			
	Number of hydrants per floorHose Box	01	Provided	MR			
	Vand Hudrants						
12	The last floorests	N/A	N/A	N/A			
	Total number of hydrantsHose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level						
		N/A	N/A	N/A			
	 Discharge of main Pump 	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	 Number of main pumps 	N/A	N/A	N/A			
	 Jockey Pump out put 	N/A	N/A	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	 Standby Pump out put 	N/A	N/A	N/A			
	 Standby Pump Head 	N/A	N/A	N/A			
	Auto Starting/ Manual stopping	N/A	N/A	N/A			
	 Pump House Access 						
	Terrace level	9 9 9 9 9 9 9	Provided	MD			
	 Discharge of pump 	450 LPM	Provided	MR			
	 Head of the pump 	30 mts		MR			
	Power Supply	Required	Provided Provided	MR			
	1 Onor suppress		Description	MR			

)

e x

لمر	Captive Water Storage for fire figh	N3	×				
	• Undergrave de la fighting.						
	 Underground tank capacity Draw off 	N/A	N/A	N/A			
	 Draw-off connection Fire coming 	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	 Overhead Tank capacity 	20,000 14-	D. 111				
15	Exit Signage.	20,000 lts	Provided	MR			
16	Provision of Lifts.	Required	Provided	MR			
	r ressurization of Lift Shaft	N/A	N/A	N/A			
	• Pressurization of Lift lobby	N/A	N/A	N/A			
	 Communication In lift Car 	N/A	N/A	N/A			
	 Fireman's Grounding Switch 	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	 Flow Switch Panel 	N/A	N/A	N/A			
		N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans						
-	Special Fire Protection Systems for Protection of special Risks, if any:	Required	02 ABC type fire extinguishers found provided near elect. panel	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

DFA is put up for approval & signature please.

10

20(m) 20(4pm)

Aman Kumar Lathar Asstt. Div. Officer (JWP)

muler with heres

18/10/2021

ADO (SWP) p.J. O.