

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE CONNAUGHT PLACE: NEW DELHI-110001**

F.6/DFS/MS/EH/2021/SZ/ 308 No.

Dated: 27 / 10/2021

-10

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Daryaganj (A unit of Matchless Restaurant Pvt. Ltd) situated at Shop No-R1, Lower Ground Floor, Worldmark-I, Aerocity, New Delhi-110037, comprised of three tiers Basement. Ground, Mezzanine + 06 Upper Floors but the restaurant running at lower ground floor only was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/EH/2018/SZ/2337 dated 16/10/2018. The premise was re-inspected by the officers concerned of this department on 11/10/2021 in the presence of Mr. Vijay Kumar (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules. 2010 and that the said premises is fit for occupancy class "Group-D Assembly" with effect from 27 / 10/2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27/10 /2021 at New Delhi by

(Sunil Chawdhary) Dv. Chief Fire Officer (SZ) **Delhi Fire Service**

511

Copy to: -

- 1. Mr. Tanush Bhalla, M/s Daryaganj (A unit of Matchless Restaurant Pvt. Ltd) at Shop No-R1, Lower Ground Floor, Worldmark-I, Aerocity, New Delhi-110037
- 2. The Dy. Health Officer, South MCD, Public Health Department, Najafgarh Zone, Near Dhansa Stand, Najafgarh, New Delhi-110043 (W.r.t. Online ID: 2021080216534 dated 02 08 2021)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at
- all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

r1-8

n

| 1 | INSPECTION REPORT Name & Address of the Building M/s Daryaganj (A unit of Matchless Restt. Pvt. | | | |
|-----|--|--|--|--|
| | a rudiess of the Building | | | |
| | | | -R1, Lower GF, Wo | |
| 2 | Type of Occupancy | Assembly "Gro | irport, New Delhi-110 | 10.57 |
| 3 | Building comprised of | | dp=0 Mezzanine, Ground & | Six Uppe |
| | | | estaurant is at LGF of | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F.6/DFS/MS/EF | /2018/SZ/2337 Dt. 16 | 5/10/2018 |
| 7 | Fire Safety Directives Letter No | F.6/DFS/MS/BP/ | 2017/Hotel/368 Dt. 21/0 | 2/17 (Bldg |
| 8 | Date of Inspection | 14/10/2021 | | |
| 9 | Name of the Inspecting Officers | DO (SD) | | |
| | Name & Designation of Officers from the building side | Mr. Vijay Kuma | r (Manager) | |
| 10 | Year of construction | 2014 | | |
| 11 | Applicant letter No. | | 080216534 dated 02/0 | 8/2021 |
| S. | Minimum standards on Fire Prevention | Old FSC | Provided at Site | Remarks |
| No. | and Fire Safety U/R 33 | Requirement | | MR/NMF |
| 1 | Access to Building. (FSC No | . F.6/DFS/MS/Mi | xed/SZ/2021/09 dated (| 8/03/2021) |
| | Road width | Restt located | As above | MR |
| | • Gate width | within | As above | -NA- |
| | • Width of internal road | Worldmark-1 | As above | -NA- |
| 2 | Number, width, type & arrangement of | exits | | |
| | a. Number of Staircase | | Maintained by Bldg. | Mgmt |
| | Upper floors | -NA- | As above | -NA- |
| | Basement floor/Lower GF | 02 Nos | As above | MR |
| | b. Width of Staircase | | Maintained by Bldg. | Momt |
| | | -NA- | As above | -NA- |
| | | 2m / 1.35m | As above | MR |
| | | | | |
| | c. Protection of exits | | Maintained by Bldg. | 1 |
| | • Fire check door | Required | As above | MR |
| | Pressurization | Required | As above | MR |
| | d. No. of continuous staircase to terrace | Required | As above | MR |
| | e. Width of corridor | -NA- | -NA- | -NA- |
| | f. Door size | 2m/1.35m | 2m & 1.35m | MR |
| 3 | Compartmentation. | Provided & | Maintained by Bldg. | Mgmt |
| | • Fire check door. | Required | As above | MR |
| | | | | MR |
| | Sealing of electrical shafts. | Required | As above | IVIIX |
| | 0 | Required | As above As above | MR |
| | • Fire rating of shaft door. | Required | | MR |
| | Fire rating of shaft door.Water curtain | Required Required | As above As above | MR MR |
| | Fire rating of shaft door.Water curtainFire dampers. | Required Required -NA- | As above As above As above | MR MR -NA- |
| 4 | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. | Required Required -NA- Provided & | As above As above As above Maintained by Bldg | MR MR -NA- |
| 4 | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area | Required Required -NA- Provided & Required | As above As above As above Maintained by Bldg Smoke venting provide | MR MR -NA- . Mgmt d MR |
| 4 | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors | Required Required -NA- Provided & | As above As above As above Maintained by Bldg | MR MR -NA- Mgmt d MR |
| 4 | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area | Required Required -NA- Provided & Required -NA- | As above As above As above Maintained by Bldg Smoke venting provide | MR MR -NA- Mgmt d MR |
| | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors | Required Required -NA- Provided & Required | As above As above As above Maintained by Bldg Smoke venting provide | MR MR -NA- Mgmt d MR |
| | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors Fire Extinguishers. Total numbers | Required Required -NA- Provided & Required -NA- | As above As above As above Maintained by Bldg Smoke venting provide -NA- | MR MR -NA- Mgmt d MR -NA |
| | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors Fire Extinguishers. Total numbers Types | Required Required -NA- Provided & Required -NA- 06 Nos. ABC / CO ₂ | As above As above As above Maintained by Bldg Smoke venting provide -NA- Provided ABC & CO ₂ | MR MR -NA- Mgmt d MR -NA MR MR |
| 5 | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors Fire Extinguishers. Total numbers Types ISI Marking | Required Required -NA- Provided & Required -NA- 06 Nos. ABC / CO ₂ ISI marked | As above As above As above Maintained by Bldg Smoke venting provide -NA- Provided ABC & CO ₂ Provided | MR MR -NA- Mgmt d MR -NA- MR MR MR |
| | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. | Required Required -NA- Provided & Required -NA- 06 Nos. ABC / CO ₂ ISI marked Provided & | As above As above As above Maintained by Bldg Smoke venting provide -NA- Provided ABC & CO ₂ Provided Maintained by Bldg | MR MR -NA- . Mgmt d MR -NA- MR MR MR . Mgmt |
| 5 | Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement /Restt. Area Upper floors Fire Extinguishers. Total numbers Types ISI Marking | Required Required -NA- Provided & Required -NA- 06 Nos. ABC / CO ₂ ISI marked | As above As above As above Maintained by Bldg Smoke venting provide -NA- Provided ABC & CO ₂ Provided | MR MR -NA- Mgmt d MR -NA- MR MR MR |

M/s Daryaganj (U/o Matchless Restt. Pvt. Ltd) at Shop No. R-1, LGF, Worldmark 1, Aerocity. 1GI Airport, New Delhi 110037

N1-9

1.00

| 7 | Automatic fire detection & alarming sys | stem. (Provided | & Maintained by Bldg | g. Mgmt) |
|----------|---|-----------------|-----------------------|----------|
| | • Type of detectors | Required | Smoke & Heat | MR |
| | • Location of Main Panel | Required | Mezzanine floor | MR |
| | • Location of Repeater Panel | Required | FCR at GF | MR |
| | • Alternate source of power | Required | Provided | MR |
| | Hoofer's location | Required | All Area | MR |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System | -NA- | As above | -NA- |
| 10 | Automatic Sprinkler System | | k Maintained by Bldg. | |
| | • Basement/Restt. Area | Required | As above | MR |
| | • Upper floors | -NA- | As above | -NA- |
| | Sprinkler above false ceiling | -NA- | As above | -NA- |
| 11 | Internal Hydrants. | | | |
| | Size of Riser/Down-comer | -NA- | Maintained by Bldg. | |
| | Number of Hydrant per floor | | As above | -NA- |
| | Hose box. | -NA- | As above | -NA- |
| 12 | Yard Hydrants. | -NA- | As above | -NA- |
| | | | Maintained by Bldg. | |
| | Total number of hydrants.Hose box. | -NA- | As above | -NA- |
| 13 | Pumping arrangements. | -NA- | As above | -NA- |
| - | Ground Level | Pumping arrang | gements are common fo | r comple |
| | Discharge of main pump. | Provided & | Maintained by Bldg. 1 | |
| | Head of main pump. | -NA- | 2280 LPM | -NA- |
| | Number of main pumps. | -NA- | 105m | -NA- |
| | Jockey Pump output | -NA- | Two | -NA- |
| | tookey rump output. | -NA- | 2 x 180 LPM | -NA- |
| | toonog rump nead. | -NA- | 105m | -NA- |
| | Standby Pump output. | -NA- | 2280 LPM | -NA- |
| | Standby Pump head. | -NA- | 105m | -NA- |
| | Auto Starting / Manual Stopping. | -NA- | Provided | -NA- |
| | Pump House Access | -NA- | Provided | -NA- |
| | Terrace Level | Provided & | Maintained by Bldg. I | Mgmt |
| | Discharge of pump. | 450 LPM | 900 LPM | MR |
| | Head of pump. | 40m | Provided | MR |
| | Power supply. | Required | Provided | MR |
| | Auto starting of pump. | Required | Provided | |
| 14 | Captive water storage for Fire Fighting. | | Maintained by Bldg. N | MR |
| | Underground tank capacity. | -NA- | 1,50,000 Ltrs | |
| | Draw-off connection. | -NA- | Provided | -NA- |
| | Fire Service Inlet. | -NA- | Provided | -NA- |
| | Access to tank. | -NA- | Provided | -NA- |
| 15 | • Overhead tank capacity. | 10,000 Ltrs | 20,000 Ltrs | -NA- |
| 15 16 | Exit Signage. | Required | Provided | MR MR |
| 10 | Provision of Lifts. | Provided & | Maintained by Bldg. M | Mamt |
| | • Pressurization of lift shaft. | -NA- | As above | -NA- |
| | • Pressurization of lift lobby. | -NA- | As above | |
| | Communication in lift car. | -NA- | As above | -NA- |
| | • Fireman's switch. | -NA- | | -NA- |
| | • Lift signage. | -NA- | As above | -NA- |
| 17 | Standby Power Supply | | As above | -NA- |
| 18 | Refuge Area | Required | Provided | MR |
| | • Total area | | | |
| | Location | -NA- | 550m ² | -NA- |
| | Location | -NA- | 6 th Floor | -NA- |

M/s Daryaganj (U/o Matchless Restt. Pvt. Ltd) at Shop No. R-1, LGF, Worldmark-1, Aerocity, IGI Airport, New Delhi-110037

N-10

| 19 | Fire Control Room. | Provided & Maintained by Bldg. Mgmt | | |
|----|--|-------------------------------------|----------|------|
| | Detector System Panel. | -NA- | As above | -NA- |
| | • Flow Switch Panel. | -NA- | As above | -NA- |
| | • PA system Panel. | -NA- | As above | -NA- |
| | Battery backup | -NA- | As above | -NA- |
| | Building floor plan | -NA- | As above | -NA- |
| 20 | Special Fire Protection System for the | -NA- | As above | -NA- |
| | Protection of special Risk, if any : | | | |

Covered area of the restaurant is 213.36 m² and as per NBC (Part-IV) the number of occupant load comes out to approx. 142 persons (213.36/1.8=142.24). Thus the capacity of restaurant is 142 persons, which is covered under DFS Act 2007, Rules 2010. Accordingly, inspection of Eating House is carried out as per NBC (Part-IV).

The Fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The main building has been issued FSC by this department vide letter No. F.6/DFS/MS/Mixed/SZ/2021/09 dated 08/03/2021.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued in the name of vide letter No. F.6/DFS/MS/EH/2018/SZ/2337 dated 16/10/2018, renewal under Rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

- 1 la la ...

Signature of the Inspecting Officer

| / | 7.7, pelat- | Name : S.K. Dua Designation: DO (SD) |
|-----------|----------------------|---|
| DCFO (SZ) | 12/10 | |
| | 0.0.5.0 | |
| | F.T. letter is put u | Ap for mp. pl- |
| | | Kive |
| | Defo(p) | 26 10 |
| | 21/10 | |
| | M.S. Cell | |

Woused MAA online Postal 28/10/2