

No. F.6/DES/MS/FH/SZ/2021/ 2/86

Dated: 1/10 2021

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Hotel Diplomat Restaurant located at ground floor in Hotel Diplomat. 9, Sardar Patel Marg. Chanakyapuri, New Delhi 110021, comprised of Basement. Ground & Two Upper Floors but restaurant running at ground floor only was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/EH/2018/SZ/1830 dated 06/08/2018. The premise was re-inspected by the officer concerned of this department on 20/09/2021 in the presence of Mr. Sandeep Balodi and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules. 2010 and that the said premises is fit for occupancy class "Group–D Assembly" with effect from [[]/[]0/2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on [ / / [ ] /2021 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

Copy to: -

ofe

- 1. The Addl. Commissioner of Police (Lic.), 1<sup>st</sup> Floor, P.S. Defence Colony, New Delhi 110049
- 2. Mr. Sandeep Balodi. M/s Hotel Diplomat Restaurant at ground floor in Hotel Diplomat. 9. Sardar Patel Marg. Chanakyapuri. New Delhi 110021

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBI 2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016). if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub-rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION I	REPORT
--------------	--------

	INSPECTIO	ON REPORT			
1	No. 11 A. 11 A. 15	Vertical Diplomat Restaurant (Restaurant at			
		Cround Floor in Hotel Diplomat) at 9. Sardar Patel Marg. Chanakyapuri. New Delhi. 1100°1 Assembly "Group: D" (Restaurant at Gd. Floor)			
2	Type of Occupancy	Assemply . Cuon	) (Restaurant ar Go	. 1 1000	
3	Building comprised of	Basement, Groun	d & 02 t pper 1 loors		
d	Type of Case	Renewal			
5	Details of Previous XOC	L 6 DLS MS FH 2018 SZ 1830 dated 06 08 2018			
()	Fire Safety Directives Letter No	NI			
7	Date of Inspection	20 09/2021			
8	Name of the Inspecting Officers	DO (SD)			
()	Name & Designation of Officers	Mr. Sandeep Bal	()(1)		
	from the building side	1002			
10	Year of construction	1982	ns 1913469 dated 06:0	8 2021	
11	Applicant letter No.	Online ID: 2021051913469 dated 06:08 2021  Old FSC   Provided at Site   Remarks			
S. No.	Minimum standards on Fire Prevention	CHA LIN	Tioriaca	MR/NMR	
	and Fire Safety U/R 33	Requirement	1	tel Diplomat)	
1	Access to Building. (F.6/DFS/MS	S/GH/2020/SZ/98 0	lated 07/02/2020 of Ho As above	NIR	
	<ul> <li>Road width</li> </ul>	Restaurant at	As above	-//	
	<ul> <li>Gate width</li> </ul>	Gd. Floor in	As above	-//-	
	<ul> <li>Width of internal road</li> </ul>	Hotel Diplomat	As above		
2	Number, width, type & arrangement of	of exits	March 1 Latel	Diplomat	
	a. Number of Staircase		Maintained by Hotel   Restt. at GF	-X 1-	
	• Upper floors	-NA-		-\.\-	
	Basement floor	-NA-	As above		
	b. Width of Staircase		Maintained by Hotel	-\.\.	
	Upper floors	-NA-	As above	-//-	
	Basement floor	-NA-	As above		
	e. Protection of exits		Maintained by Hotel	-X \-	
	Fire check door	-NΛ-	As above	-/\/.\-	
	<ul> <li>Pressurization</li> </ul>	-NA-	As above	MR	
	d. No. of continuous staircase to terrace	Required	As above	-1.1-	
	e. Width of corridor	-NA-	-NA-	AIR	
	f. Door size	2 Exits *	1.5m & 1m	(old case)	
			X Colored to all by Haral		
3	Compartmentation.		Maintained by Hotel	-\ \-	
	Fire check door.	-NA-	As above		
	<ul> <li>Sealing of electrical shafts.</li> </ul>	-NA-	As above	-/ /-	
	Fire rating of shaft door.	-NA-	As above	-/-/-	
	Water curtain	-NA-	As above	-1.1-	
		-NA-	As above	-/-	
	Fire dampers.		  : Maintained by Hote	Diplomat	
4	Smoke Management system.		As above	\ \ \ \	
	Basement	-NA-		VIR	
	<ul> <li>Upper floor / Restt. Area</li> </ul>	Required	As above	1110	
5	Fire Extinguishers.				
	Total numbers	06 Nos.	Provided	MR	
		ABC / CO <sub>2</sub>	ABC & CO <sub>2</sub>	NIR	
	• Types	ISI marked	Provided	VIR	
	• ISI Marking				
6	First Aid Hose Reels.		Maintained by Hote		
	<ul> <li>Lotal numbers on each floor.</li> </ul>	One	Provided	MR	
	<ul> <li>Length of hose-reel hose.</li> </ul>	30m	Provided	NIR	
		5mm	Provided	NIR	
	Nozzle Diameter	541111			

M. Diplomot Re-taurant (In Diplomat Hotel), 9. Sardar Patel Mary, Chanakyapuri, New Delhi, 1100 M.

7	Automatic fire detection & alarming sy	stem. (Provided	L& Maintained by Hot	el Diplomais
	• Type of detectors	-N.1-	As above	a 📐 🗎
	<ul> <li>Location of Main Panel</li> </ul>	-NA-	As above	1.1-
	Location of Repeater Panel	-NA-	As above	1.7.
	Alternate source of power	-NA-	As above	1/1-
	Hoofer's location		As above	->1
8	MOEFA	-N.1-		NR
9		Required	Provided	-1.1-
10	Public Address System.	-NA-	-NA- : Maintained by Hotel	
• (,	Automatic Sprinkler System  Basement		-NA-	-NA-
		-NA- -NA-	Provided	-1.7.1-
	Upper floors / Restt. Area     Sprint for above 6.1	-NA-	-NA-	-1.1-
11	• Sprinkler above false ceiling Internal Hydrants.		Maintained by Hotel	
	Size of Riser/Down-comer	-NA-	-NA-	-1/1-
		-NA-	-ΝΛ-	-1.1-
	<ul><li>Number of Hydrant per floor</li><li>Hose box.</li></ul>	-NA-	-NA-	-N.A-
12	Yard Hydrants.	Provided &	Maintained by Hotel l	Diplomat
	• Total number of hydrants.	-NA-	-NA-	-/:/-
	<ul> <li>Hose box.</li> </ul>	-NA-	-N:\-	-/ /-
13	Pumping arrangements.			
•••	Ground Level			
		-NA-	-NΛ-	-1.1-
	<ul><li>Discharge of main pump.</li><li>Head of main pump.</li></ul>	-NA-	-NA-	-NA-
	<ul><li>Number of main pumps.</li></ul>	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-1.1-
	<ul> <li>Jockey Pump head.</li> </ul>	-N∆-	-NA-	-NA-
	<ul> <li>Standby Pump output.</li> </ul>	-ΝΛ-	-NA-	-NA-
	<ul> <li>Standby Pump head.</li> </ul>	-NA-	-NA-	-N.\- -N.\-
	<ul> <li>Auto Starting / Manual Stopping.</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>Pump House Access</li> </ul>	-NA-	-NA-	
	<ul> <li>Terrace Level</li> </ul>	Provided & Maintained by Hotel D		MR
	<ul> <li>Discharge of pump.</li> </ul>	450 LPM	As above As above	MIR
	<ul> <li>Head of pump.</li> </ul>	35m	As above	MR
	Power supply.	Required Required	As above	MR
	Auto starting of pump.		Maintained by Hotel I	i
14	Captive water storage for Fire Fighting.	-NA-	18,000 Ltrs	-NA-
	<ul> <li>Underground tank capacity.</li> <li>Draw-off connection.</li> </ul>	-NΛ-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	- Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	5.000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by Hotel Diplomat		
10	Pressurization of lift shaft.	-NA-	-NA-	-1.1-
	<ul> <li>Pressurization of lift lobby.</li> </ul>	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
	• Lift signage.	-NA-	-NA-	\.\/\-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area	,		
	Total area	-ΝΛ-	-NA-	-1./
	<ul> <li>Location</li> </ul>	-ΝΛ-	-NA-	-NA-
		1		

19	Fire Control Room.	-N.\-	-NA-	-\\-
	Detector System Panel.	-NA-	-NA=	-//-
	• How Switch Panel.	-NA-	-NA-	, -\ \
	• P \ system Panel.	-NA-	-NA-	- \-
	Battery backup     Building floor plan	-NA-	-NA-	-/,/-
20	Special Fire Protection System for the	-NA-	-N.1-	-//-
	Protection of special Risk, if any:	1		

<sup>\*</sup> The restaurant in the Hotel Diplomat building is running since the beginning and same has been mentioned at N/12 (copy placed at  $C^{\prime}$ ) in the main file of the Hotel Diplomat. Therefore, only two door exits without mentioning of the width are required in this case, which have already been provided in the restaurant. If agreed, we may consider the width of doors of 1.5 m & 1.0 mtrs.

The Fire protection systems provided in the building were test checked and found functional at the time of inspection. Further, The main building (Hotel Diplomat) has been issued FSC vide this department letter No. F.6/DFS/MS/GH/2020/SZ/98 dated 07/02/2020 (C/188).

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificated issued vide letter No. F.6/DFS/MS/EH/2018/SZ/1830 dated 06/08/2018, renewal under Rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Office of Signature

Name

S.K. Dua

Designation: DO (SD)

DCFO (SZ)

D

D 6 0 0

Mis- Ull