

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2021/ 617

Dated: 25/11/2021

To

The Principal,
Dayanand Model School,
Arya Samaj Premises, West Patel Nagar,
New Delhi-110008.

Sub.: Regarding issuance of Fire Safety Certificate in r/o Dayanand Model School, Arya Samaj Premises, West Patel Nagar, Road, New Delhi-110008.

Sir,

Please refer to your e-mail dated 22.10.2021 received through e-mail ID <dayanand_school_wpn@yahoo.com> on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Mr. Sandeep Nagia, Superintendent of the School, on 08.11.2021 to check the status of the shortcomings pointed out by this department vide letter No. F.6/DFS/MS/School/SZ/2016/1103 dated 29.04.2016, but no improvement was observed as seen during the course of inspection and this department has already issued a letter in this matter vide this office letter No. F.6/DFS/MS/School/SZ/2019/5703 dated 20.09.2019.

In view of the above, 'Fire Safety Certificate' cannot be issued at this stage. You are requested to rectify the above-mentioned fire safety arrangements under intimation to this department.

Yours faithfully


(Atul Garg)
Director
Delhi Fire Service

Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

-for information please.

C-9

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2019/SZ/ 5703

Dated: 20/9/19

To,

The Principal,
Dayanand Model School,
Arya Samaj Premises, West Patel Nagar,
New Delhi-110008.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Dayanand Model School, Arya Samaj Premises, West Patel Nagar, New Delhi-110008.

Sir,

This has reference to your Letter No. 78/2019-20 dated 07.08.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 22.08.2019 to see the shortcomings already communicated by this department vide letter no. F.6/DFS/MS/School/2016/1103 dated 29.04.2016 in the presence of Smt. Anjna Luthra (Principal) & it was observed that shortcomings have not been complied so far.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)

CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi-110054

(With a request to take further action as school does not have fire NOC)

dlcsm
17/9/19

c-6

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001
E-mail : gargatul@hotmail.com Ph. 011-26189168

No: F.6/DFS/MS/School/2016/ 1103

Dated: 29/09/16

To,

The Principal,
Dayanand Model School, Arya Samaj Premises,
West Patel Nagar, New Delhi-110008.

Sub: - Regarding grant of Fire Safety Certificate in r/o Dayanand Model School located at Arya Samaj Premises, West Patel Nagar, New Delhi-110008.

Madam,


Please refer to your letter No. 06/2016-17 dated 11.04.2016 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by the officer concerned of this department on 22.04.2016 to see the compliance of the requisite Fire Safety measures. Sh. Rajeev Kumar (Manager) was also present at the time of inspection.

During the course of inspection it was observed that the school building having two blocks namely Primary Block & Secondary Block. Primary Block is comprised of ground floor plus one upper floor. The upper floor is served by a single staircase having width 82 cms. Secondary Block is comprised of ground floor plus two upper floors. The upper floors are served by two staircases having width 175 cms & 100 cms from ground floor to first floor and three staircases having width 100 cms, 98 cms & 90 cms from first floor to second floor. This department has issued shortcomings vide letter No. F.6/DFS/MS/School/2013/1043 dated 26.03.2013. The school building is directly approachable to the fire fighting vehicles but the school building does not meet the required norms in the light of Delhi Fire Service Act 2007, and Rule 2010, due to the following shortcomings: -

1. In Primary Block either existing staircase width is to be increased from 82 cms to 150 cms or an additional staircase is to be provided having width not less than 75 cms.
2. Three Co2 type Fire Extinguishers of 4.5 kg/2.2kg capacity each and nine ABC type Fire Extinguishers of 05 kg capacity each or WCO2 type fire extinguishers of capacity 09 ltr. each are not provided in the school building.
3. First Aid Hose Reel system is not provided in the school building.
4. Fire Pump of 450 LPM discharge with 30 M head is not provided.
5. Over Head water storage tank of 10000 ltr capacity is not provided.
6. Exit signs are not provided in the school building.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,


Atul Garg
Dy. Chief Fire Officer
Delhi Fire Service

5/10/16