GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2021/ 537

Dated: 20 12 2021

Tel: 011-23414000

- 81

FIRE SAFETY CERTIFICATE


Certified that the M/s Ghee Wala Guest House located at 4135, Urdu Bazar, Jama Masjid, Delhi, comprised of Ground + 02 upper floors: Ground floor - 06 guest rooms + reception, 1st floor - 06 guest rooms + 01 staff room, 2nd floor - 04 guest rooms, total 16 guest room was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/NDZ/2018/2158 dated 19.09.2018. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 10.12.2021 in presence of Mr. Moinuddin (Owner) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 16 guest rooms (Ground floor -06 guest rooms, 1st floor-06 guest rooms, 2nd floor-04 guest rooms) with effect from 20 12 20 21. for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule

Copy to:-

- 1. The Commissioner, North Delhi Municipal Corporation, S.P.M, Civic Centre. Delhi: - to ensure the occupancy as detailed above.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi: -w.r. to online I.D. no. 2021120127621 dated 01.12.2021.
- 3. The Licensee, M/s Ghee Wala Guest House at 4135, Urdu Bazar, Jama Masjid, Delhi.

Conditions for the validity of Fire Safety Certificate:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.



N/36

5.	Fire Extinguisher								
	Α	T	otal numbers		06 no.	06			
	B	T	ypes		CO ₂ & ABC	06 no.	MR		
	С	1	SI marking		Required	CO ₂ & ABC	MR		
6	First-Aid-Hose Reels.				Required	ISI marked	MR		
	A				01 nos.	01			
	В		ength of hose reel hose		30 mtrs.	01 nos.	MR		
	C		ozzle diameter			30 mtrs.	MR		
7	Automatic Fire Detection And Alarming				5 mm	5 mm	MR		
	A Type of detectors			ig S					
					CO detectors (required as per GN dated 27.05.2019)	Provided	MR		
	B]	Location of main panel		At reception.	Provided	MR		
	C		Location of repeater panel		NA	NA	NA		
	D		Alternate source of power		Required	Provided	MR		
	E		Hooters		Audible in entire building	Provided at every floor	MR		
8	M	DE	FA		NA	NA .	NA		
9	Pu	bli	c Address System.			NA	NA		
10	Au	tor	natic Sprinkler System.	I	1				
	A	ba	sement		NA	NA	NA		
	B	upper floor			NA	NA	NA		
	C	Sprinkler above false ceiling			NA	NA	NA		
11	Internal Hydrants								
	A size of riser/down-comer]	NA	NA	NA		
	B	Number of hydrants per floor		1	NA	NA	NA		
		Hose box			NA	ŅA	NA		
12	Yard Hydrants.								
	A Total number of hydrants			1	NA	NA	NA		
		-			NA	NA	NA		
13	Pumping Arrangements.								
	A	-1	Ground Level						
		a	Discharge of main Pump	N	JA	NA	NA		
		b	Head of Main Pump	N	JA	NA	NA		
		c	Number of main pumps	N	JA	NA	NA		
		d	Jockey pump out put	N	JA	NA	NA		
		e e	Jockey pump head	N	IA	NA	NA		
		f	Standby pump out put	_	IA	NA	NA		
		g	Standby pump Head	N	IA	NA	NA		
		n	Auto Starting /Manual stopping	_	IA	NA	NA		
	i	i	Pump house access	N	A	NA	NA		
	B					006 L D. (D.C.D.		
	2	1	Discharge of pump	_	25 LPM	225 LPM	MR		
	ł	>	Head of the Pump		5mtrs.	25mtrs	MR		
		;	Power supply		equired	Provided	MR		
		1	Auto starting of pump	R	equired	Provided	MR		

5

N/37

14	Captive Water Storage for Fire Fighting.								
	A Underground tank capacity	NA	NA	NA					
	B Draw-off connection	NA	NA	NA					
	C Fire service inlet	NA	NA	NA					
	D Access to tank	NA	NA	NA					
	E Overhead tank capacity	2,500 ltrs	2,500 ltrs	MR					
15	Exit Signage.	Required	Provided	MR					
16	Provision of Lifts.								
	A Pressurization of lift shaft	NA	NA	NA					
	B Pressurization of lift lobby	NA	NA	NA					
	C Communication in lift car	NA	NA	NA					
	D Firemen's grounding switch	NA	NA	NA					
	E Lift signage	NA	NA	NA					
17	Standby Power Supply	Provided	MR						
18	Refuge Area.								
	A Total area	NA	NA	NA					
	B Location	NA	NA	NA					
19	Fire Control Room								
	A Detector system panel	NA	NA	NA					
	B Flow switch panel	NA	NA	NA					
	C PA system panel	NA	NA	NA					
	D Battery backup	NA	NA	NA					
20	E Building floor plans	NA	NA	NA					
20	Special Fire Protection Systems For Pro Risks, If Any:	NA	NA						

Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Provided but not functional (PNF).

Note: 02 number of staircases have been required in the guest house and 02 staircases of width 103 and 105 cms have been mentioned provided in the inspection reports 28/N and henceforth. However the same was not found at site. The guest house had already been issued 'NOC' on single staircase on 06.04.1992 vide letter no. F6/DFS/MS/90/GH/2161. The matter of staircase width has already been discussed elaborately at 11/N to 16/N on file and 2nd staircase was not required. The area also falls under special area wherein most of the guest houses have been granted NOC/ FSC with single staircase of 80 cms. It appears that the requirement of 02 staircases has been inadvertently mentioned in the inspection reports at 28/N and thereafter and same has been corrected in this inspection report.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

If agreed and in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/2158 dated 19.09.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

2021

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (SPM)

DOUCOD

P