C-42



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 4-0

Dated:\\\\.\.\.\\\\/2022

FIRE SAFETY CERTIFICATE

Certified that the Aman Continental located at 1048-984, Main Bazar, Mantola, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (03 guest rooms + Reception + Lounge + Office), 1st floor (08 guest rooms), 2nd floor (10 guest rooms), 3rd floor (10 guest rooms) and 4th floor (08 guest rooms + store + staff room), total 39 guest rooms owned/occupied by Aman department Continental was earlier granted **FSC** by this F6/DFS/MS/GH/NDZ/2018/2453 dated 31/10/18. Now, the premises was re-inspected by the officer concerned of this department on 14/01/22 in the presence of Sh. Amandeep and found that the said guest house building having given an affidavit given by owner dated 08.12.2019 regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (03 guest rooms + Reception + Lounge + Office), 1st floor (08 guest rooms), 2nd floor (10 guest rooms), 3rd floor (10 guest rooms) as above 31 guest rooms upto third floor only with effect from ----for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 19 01 20 2 at New Delhi by.

(**Dr. S.K.Tomar**)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online ID No. 2021102424981 dated 24.10.21& mail id.<amancontinental@yahoo.com>dated 07.01.2022.
- 3. The Manager, Aman Continental, 1048-984, Main Bazar, Mantola, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- This clearance/ FSC shall stand cancelled, if guest house owner/occupier fails to comply all conditions
 mentioned in the gazette notification dated 27.05.2019 & letter of extension of time period issued on dated
 20.12.2021, latest by 31.03.2022.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

~113

INSPECTION REPORT

1. Name & address of the building Aman Continental at 1048-984, Main

Bazar, Mantola, Pahar Ganj, New Delhi.

2. Type of occupancy:- Residential, Sub Division-A-1

Ground + 04 Upper floors (total 31 guest rooms)
Ground floor (03 guest rooms + Reception + Lounge + Office), 1st floor (08 guest rooms), 2nd floor (10 guest rooms) and 4th floor sealed an affidavit given by owner dated 08.12.2019 regarding not to use any floor above third floor.

(31 guest rooms).

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/NDZ/2018/2453 dated

31/10/18.

5. Fire safety directives No.- N/A

6. Date of inspection:- 14/01/22.

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC) Sh. Rajinder Singh (DO/CD)

8. Name & designation of officer From the building side:-

om the building side:- Mr. Amandeep

9. Year of construction:- 2014

10. Applicant's letter No:- online ID No. 2021102424981 dated 24.10.21&mail id. amancontinental@yahoo.com dated 07.01.2022.

		id. <u>amancontinental@yahoo.com</u> dated 07.01.2022. Old Case			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	Required	6 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arra				
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	1.5 mtr.	1.55 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	

Nly

	2) Upper floors	12 a/c per hour	Natural/exhaust	MIR 🧻
5.	Fire Extinguishers		,,,,,	200
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			- P. C.
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
<i>1</i> ,	Automatic Fire Detection &	em		
	1) Type of detectors CO Type	Required	Provided	MR
	2) Location of main panel	Required	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Required	Provided	MR
ł,	MOEFA	Required	Provided	MR
),	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Dasement(Less than 189 SQM)	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	 a) Discharge of main pump 	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	e) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	 e) Jockey pump head 	N/A	N/A	N/A
	 Stand by pump output 	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Torrace level		The second second	
	 a) Discharge of pump 	450 LPM	450 LPM	MR
	b) Head of pump	40 mtr.	40 mtr.	MR
	e) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
4.	Captive Water Storage for F	ire Fightine	1	IVIK
	Under ground tank capacity	N/A	N/A	N/A

20.	Risk, if any:	em ioi i iotec	non or special	
20.	e) Building floor plan Special Fire Protection Syst	N/A	N/A	N/A N/A
	, , , ,			
	d) Battery backup	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	panel b) Flow switch panel	N/A	N/A	N/A
	a) Detector system	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	
	e) Lift signage	Required	Provided	MR MR
	d) Fireman's switch	Required	Provided	MR
	c) Communication in lift car	Required	Provided	MR
	b) Pressurization of lift lobby	N/A	N/A	N/A
	a) Pressurization of lift shaft	N/A	N/A	N/A
16.	Provision of Lifts.			
15.	Exit Signage.	Required	Provided	MR
	capacity .	, i		1.00
	c) Access to tank d) Over head tank	N/A 10,000 ltr.	10,000 ltr.	MR
	b) Fire service inlet	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A N/A	N/A N/A

The fire protection systems provided in the building were randomly tested, checked and found nonfunctional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/2453 dated 31/10/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only .

Signature of the inspecting officer

18/1/22 Name: - Rajinder Atwal Designation: - DO (CD) Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

45 eposim Pease

MS