GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/School/2022/SZ/ / 0 /

FIRE SAFETY CERTIFICATE

Certified that **St. Mary's Public School (Junior Branch)** at Khasra No-142, 150, Z-More, Neb Sarai, New Delhi-110068, comprised of ground plus three upper floors owned/occupied by St. Mary's School Management was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2018/SZ/2282 dated 09/10/2018. The premises was re-inspected by officer concerned of this department on 27/01/2022 in the presence of Dr. Thomas George (Director) of the school and found that the said school premises have deemed complied with the fire prevention and fire safety arrangements in accordance with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the building is fit for occupancy **class-B "Educational"** (School) with effect from $0 \ge 1/0 \ge 1/2022$ for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued <u>02/02</u>/2022 at New Delhi by

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- The Principal, St. Mary's Public School (Junior Branch), 150, Z-More, Neb Sarai, New Delhi-110068.
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 110054.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept unlocked and free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

| | INSPECTIO | ON REPORT | |) 100 | | | |
|--------|---|--|--|--|--|--|--|
| 1 | INSPECTION REPORT Name & Address of the Building St. Mary's Public School (Junior Branch), Khasra | | | | | | |
| • | Traine te riesiess of the Dansing | No-142, 150, Z-More, Neb Sarai, New Delhi-68 | | | | | |
| 2 | Type of Occupancy | Educational, Group-B (School) | | | | | |
| 3 | Building Comprised of | Ground + 03 upp | and the second s | | | | |
| 4 | Type of Case | Renewal | | The Control of the Co | | | |
| 5 | Details of Previous NOC | | ool/2018/SZ/2282 dated | 09/10/2018 | | | |
| 6 | Fire Safety Directives Letter No | | Safety/2011/3298 to 3398 da | | | | |
| 7 | Date of Inspection | 27-01-2022 | | | | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | | | | |
| 9 | Name & Designation of Officers | Dr. Thomas George (Director) | | | | | |
| | from the building side | | | | | | |
| 10 | Year of construction | 2009 | | | | | |
| 11 | Applicant letter No. | Gmail dated 25-0 | 01-2022 | | | | |
| S. No. | Minimum standards on Fire Prevention | NBC / BBL | Remarks | | | | |
| | and Fire Safety U/R 33 | requirements | | MR/NMR | | | |
| 1. | Access to Building. | | | | | | |
| | Road width | 6 mtr | Provided | MR | | | |
| | Gate width | 4.5 mtr | 5.10, 3.70 & 2.68m | MR | | | |
| | Width of internal road | -NA- | -NA- | -NA- | | | |
| 2 | Number, width, type & arrangement of exits. | | | | | | |
| | a) Number of Staircase | | | | | | |
| | Upper floors. | 02 Nos | 03 Nos | MR | | | |
| | Basement floor. | -NA- | -NA- | -NA- | | | |
| | b) Width of Staircase | | | | | | |
| | > Upper floors | 1.5m / 0.75m | 1.24m, 0.90m to 1.05m | MR | | | |
| | SPF HOUSE | | and 1.50m (iron) | (old case) | | | |
| | Basement floor | -NA- | -NA- | -NA- | | | |
| | c) Protection of exits | | | | | | |
| | Fire check door | -NA- | -NA- | -NA- | | | |
| | Pressurization | -NA- | -NA- | -NA- | | | |
| | d) No. of continuous staircase to terrace | One | Provided | MR | | | |
| | e) Width of corridor | -NA- | -NA- | -NA- | | | |
| | f) Door size | 1m | Provided | MR | | | |
| 3 | Compartmentation. | | | | | | |
| | Fire check door. | -NA- | -NA- | -NA- | | | |
| | Sealing of electrical shafts. | -NA- | -NA- | -NA- | | | |
| | Fire rating of shaft door. | -NA- | -NA- | -NA- | | | |
| | Water curtain | -NA- | -NA- | -NA- | | | |
| | Fire dampers. | -NA- | -NA- | -NA- | | | |
| 4. | Smoke Management system. | | • | | | | |
| | Basement | 30 ACPH | -NA- | -NA- | | | |
| | Upper floors | 12 ACPH | -NA- | -NA- | | | |
| 5. | Fire Extinguishers. | | | | | | |
| | Total numbers | 08 Nos | 17 Nos | MR | | | |
| | | ABC / CO2 | CO2 & ABC | MR | | | |
| | • Types | | | | | | |
| | ISI Marking | ISI marked | Provided | MR | | | |
| 6. | First Aid Hose Reels. | | | | | | |
| | Total numbers on each floor. | One | Provided | MR | | | |
| | Length of hose-reel hose. | 30m | Provided | MR | | | |
| | Nozzle Diameter | 5mm | Provided | MR | | | |
| | Nozzle Diameter St. Mary's Public School (Junior Branch), Kha | | | | | | |

St. Mary's Public School (Junior Branch), Khasra No-142, 150, Z-More, Neb Sarai, New Delhi

| 7. | Automatic fire detection & alarming system. | | | |
|------------|---|------------------------------|--------------------------|----------------------|
| | Type of detectors | -NA- | -NA- | -NA- |
| | Location of Main Panel | -NA- | -NA- | -NA- |
| | Location of Repeater Panel | -NA- | -NA- | -NA- |
| | Alternate source of power | -NA- | -NA- -NA- Provided | -NA- -NA- -NA- |
| | Hooter's location | -NA- -NA- -NA- | | |
| 8. | MOEFA | | | |
| 9. | Public Address System | | -NA- | |
| 10. | Automatic Sprinkler System | | | |
| | Basement | -NA- | -NA- | -NA- |
| | Upper floors | -NA- | -NA- | -NA- |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA- |
| 11. | Internal Hydrants. | | | |
| 11. | Size of Riser/Down-comer | -NA- | -NA- | -NA- |
| | Number of Hydrant per floor | -NA- | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| 12. | Yard Hydrants. | | | |
| 12. | | -NA- | -NA- | -NA- |
| | Total number of hydrants. | -NA- | -NA- | -NA- |
| 12 | Hose box. | -IVA- | 414.4 | 1477 |
| 13. | Pumping arrangements. | | | |
| | Ground Level | -NA- | -NA- | -NA- |
| | Discharge of main pump. | -NA- | -NA- | -NA- |
| | Head of main pump. | | -NA- | -NA- |
| | Number of main pumps.Jockey Pump output. | -NA- | -NA- | -NA- |
| | Jockey Pump output.Jockey Pump head. | -NA- | | -NA- |
| | Standby Pump output. | -NA- | -NA- | |
| | > Standby Pump head. | -NA- -NA- -NA- -NA- | -NA- -NA- -NA- | -NA- -NA- -NA- |
| | > Auto Starting/Manual Stopping. | | | |
| | Pump house access. | | | |
| | • | | | |
| | Terrace Level | 450 LPM | | |
| | Discharge of pump. | 450 LPM 40m | Provided Provided | MR |
| | Head of pump. | | | MR |
| | Power supply. | Required | Provided | MR |
| 1.4 | > Auto starting of pump. Captive water storage for fire fighting. | Required | Provided | MR |
| 14. | Underground tank capacity. | -NA- | -NA- | -NA- |
| | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | -NA- | -NA- | -NA- |
| | ➤ Draw-off connection ➤ Fire Service Inlet. | -NA- | -NA- | -NA- |
| | Access to tank. | -NA- | -NA- | -NA- |
| | Overhead tank capacity. | 10,000 Ltr | Provided | |
| 15 | Exit Signage. | Required | Provided | MR |
| 15. 16. | Provision of Lifts. | Required | riovided | MR |
| 10. | | -NA- | NIA | NI A |
| | Pressurization of lift shaft. | -NA- | -NA- | -NA- |
| | Pressurization of lift lobby. | | -NA- | -NA- |
| | Communication in lift car. | -NA- | -NA- | -NA- |
| | Fireman's switch. | | | |
| | Lift signage. | -NA- | -NA- | -NA- |
| 17. | Standby Power Supply | -NA- | -NA- | -NA- |
| 18. | Refuge Area | | | |
| | Total area | -NA- | -NA- | -NA- |
| | • Location | -NA- | -NA- | -NA- |
| | t. Mary's Public School (Junior Branch) Khasr | | | |

St. Mary's Public School (Junior Branch), Khasra No-142, 150, Z-More, Neb Sarai, New Delhi

| 19. | Fire Control Room. | | | |
|-----|--|------|--|------|
| 17. | Detector system panel. Flow switch panel PA system panel. | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | Battery backupBuilding floor plan | -NA- | -NA- | -NA- |
| 20. | Special Fire Protection System for the Protection of special Risk, if any. | -NA- | Provided 02 Nos ABC type fire extinguisher near electrical panel | -NA- |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Neeping in view of the deemed compliance of the minimum standard on fire prevention and fire issued vide letter no required under the rules, the FSC safety F6/DFS/MS/School/2018/SZ/2282 dated 09/10/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

approved, F.T. Letter is particle
me signature of 1