

469

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/2022/WZ/ CH/29

Dated: 04/02/2022

**FIRE SAFETY CERTIFICATE**

Certified that the **Haldiram Products Pvt. Ltd. Shop No.5A,6,7 at D- Mall, Rohini Twin District Centre, Sector-10, Rohini, Delhi -110085** is running at ground and mezzanine floor of a building, comprised of **Three Tiered Basement, Ground + Five upper floors** was granted NOC by this department vide letter no. **F.6/DFS/MS/2018/WZ/1088 dated 16.05.2018**. The premises was re-inspected by the officers concerned of this department on **06.10.2021** in the presence of **Sh. Praveen Kumar** in accordance with rule 33 of the Delhi Fire Service Rules, 2010. Hence the NOC is renewed and premises is fit for occupancy **Class (Assembly) Restaurant for Ground + Mezzanine floor only** with effect from 04/02/2022 for a period of **03 (Three) years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 04/02/2022 at New Delhi by

  
**(Dhrampal Bhardwaj)  
Dy.Chief Fire Officer  
Tel;-01123414250**

Copy to :-

1. The Authority Signatory Haldiram Products Pvt. Ltd. Shop No.5A,6,7 at D- Mall, Rohini Twin District Centre, Sector-10,Rohini, Delhi -110085.
2. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054.

**Conditions for the validity of Fire Safety Certificate:**

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in**
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

**INSPECTION REPORT**

1. Name & address of the building : M/s Haldiram Products Pvt. Ltd. Shop No.5A,6,7 at D- Mall, Rohini Twin District Centre, Sector-10,Rohini, Delhi -110085.
2. Type of Occupancy : Assembly (**Restaurant running is Ground + Mezzanine floor**)
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/2018/WZ/1088 dated 16.05.2018
5. Fire Safety directives letter No : N/A
6. Date of inspection : 05.10.2021
7. Name of Inspecting Officer : A.K.Sharma ADO(Rohini) & Do (NW)
8. Name and designation of officers  
From the building side : Mr. Francon
9. Year of Construction : It is in D Mall
10. Applicant's letter No. : Online Application No.2021090820671 dated 08.09.2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	<b>Access to building</b> (Twin District Centre, D Mall, Sector-10, Rohini issued FSC vide letter No.F.6/DFS/MS/2021/WZ/420 dated 27.08.2021)			
	• Road width	Accessible	Accessible	MR
	• Gate width	Accessible	Accessible	MR
	• Width of internal road	NA	NA	NA
2.	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	• Upper Floors	Restaurant within mall	As Above	MR
	• Basements	Restaurant within mall	As Above	MR
	b. Width of staircases			
	• Upper Floor	Restaurant within mall	As Above	MR
	• Basements	Restaurant within mall	As Above	MR
	c. Protection of exits			
	Fire check door	Restaurant within mall	As Above	MR
	• Pressurization	Restaurant within mall	As Above	MR
	d. No. of continuous staircases to terrace	Restaurant within mall	As Above	MR
	e. Width of Corridor	Restaurant within mall	As Above	MR
	f. Door Size	1.50m & 2m	Provided	MR
3.	<b>Compartmentation</b>			
	• Fire check door	Restaurant within mall	As Above	MR
	• Sealing of electrical shafts	Restaurant within mall	As Above	MR
	• Fire Rating of shaft door	Restaurant within mall	As Above	MR
	• Water Curtain	Restaurant within mall	As Above	MR
	• Fire Dampers	Restaurant within mall	As Above	MR
4.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	• Basements	Restaurant within mall	As Above	MR
	• Upper floors	Restaurant within mall	As Above	MR
5.	<b>Fire Extinguishers</b>			
	• Total numbers	One " 300m2	05nos.	MR
	• Types	ABC/CO2	ABC/CO2	MR
	• IS marking	ISI marked	Yes	MR
6.	<b>First-Aid Hose Reels</b>			
	• Total numbers on each floor	01	As Above	MR
	• Length of hose reel hose	30mm	As Above	MR
	• Nozzle diameter	5m	As Above	MR
7.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	• Type of detectors	Restaurant within mall	As Above	MR

	<ul style="list-style-type: none"> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>	Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
8.	<b>MOEFA</b>	Required	Provided	MR
9.	<b>Public Address System</b>	Restaurant within mall	As Above	MR
10.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>Basement</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Ground &amp; Upper Floors</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Sprinkler above false ceiling</li> </ul>	Restaurant within mall	As Above	MR
11.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>Size of riser/down-comer</li> </ul>	100mm	As Above	MR
	<ul style="list-style-type: none"> <li>Number of hydrants per floor</li> </ul>	One(near to Restaurant)	As Above	MR
	<ul style="list-style-type: none"> <li>Hose Box</li> </ul>	One(near to Restaurant)	As Above	MR
12.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>Total number of hydrants</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Hose Box</li> </ul>	Restaurant within mall	As Above	MR
13.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>Ground Level</li> <li>➤ Discharge of main Pump</li> <li>➤ Head of Main pump</li> <li>➤ Number of main pumps</li> <li>➤ Jockey Pump out put</li> <li>➤ Jockey pump head</li> <li>➤ Standby Pump out put</li> <li>➤ Standby Pump Head</li> <li>➤ Auto Starting/Manual Stopping</li> <li>➤ Pump House Access</li> </ul>	Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Terrace level</li> <li>➤ Discharge of pump</li> <li>➤ Head of the pump</li> <li>➤ Power Supply</li> <li>➤ Auto Starting of pump</li> </ul>	NA	As Above	MR
		NA	As Above	MR
		Required	As Above	MR
		Required	As Above	MR
14.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>Underground tank capacity</li> <li>➤ Draw-off connection</li> <li>➤ Fire service inlet</li> <li>➤ Access to tank</li> </ul>	Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Overhead Tank capacity</li> </ul>	Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
15.	<b>Exit Signage.</b>	Required	Provided	MR
16.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>Pressurization of Lift Shaft</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Pressurization of Lift lobby</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Communication In lift Car</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Fireman's Grounding Switch</li> </ul>	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> <li>Lift Signage</li> </ul>	Restaurant within mall	As Above	MR
17.	<b>Standby power supply</b>	Required	As Above	MR
18.	<b>Smoke Management System</b> [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> <li>➤ Total Area</li> </ul>	NA	NA	NA
	<ul style="list-style-type: none"> <li>➤ Location</li> </ul>	NA	NA	NA

**Smoke Management System** [Provided & Maintained by Mall management]

<ul style="list-style-type: none"> <li>• Detector System Panel</li> <li>• Flow Switch Panel</li> <li>• PA System Panel</li> <li>• Battery backup</li> <li>• Building Floor Plans</li> </ul>	Restaurant within mall	As Above	MR
	Restaurant within mall	As Above	MR
	Restaurant within mall	As Above	MR
	Restaurant within mall	As Above	MR
	Restaurant within mall	As Above	MR
20. <b>Special Fire Protection System for Protection of special Risks, if any:</b>	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2018/WZ/1088 dated 16.05.2018 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer  
Name Ajay Kumar Sharma  
Designation ADO(Rohini)

DO (NW)   
07/10/2021

Dy CPO (WZ)

  
11/10/2021

~~ADO~~ Rohini

FT letter to put up for kind personal and signature please.

  
13/10/21

Dy CPO (WZ)

why Mezzanine furnace not in Caf.

~~ADO~~ Rohini