C-20

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ / 2/ 2

Dated: 25/02/2022

## FIRE SAFETY CERTIFICATE

Certified that the **Baby Public School**, 17 & 17-A, Prem Vihar, Gali No.-4, Ghasi Pura, Najafgarh, New Delhi-110043, having total 08 rooms (including class rooms & office etc.) owned/occupied by Baby Public School was issued FSC by this department vide letter No F6/DFS/MS/School/2017/SZ/1332 dated 08/09/2017. The school building was re-inspected by the officer concerned of this department on 17/02/2022 in the presence of Sh. Mithilesh Kumar Singh (Manager). The School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (**Ground plus one upper floor only**) is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on 25 | 02 | 2022 at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Copy to:-

- The Principal, Baby Public School, 17 & 17-A, Prem Vihar, Gali No.-4, Ghasi Pura, Najafgarh, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

INSPECTION REPORT

Name & address of the building: Baby Public School, 17 & 17-A, Prem Vihar, Gali No.-4, Ghasi Pura, Najafgarh, New Delhi-110043

Building comprised of : G+2 but school running at ground plus one upper floor only 3. Type of Occupancy

Educational 4. Type of Case Renewal 5. Details of Previous NOC

F6/DFS/MS/School/2017/SZ/1332 dated 08/09/2017 6. Fire Safety directives letter No :

N/A 7. Date of inspection 17/02/2022 8. Name of Inspecting Officer A.D.O. R.K.Yadav

9. Name and designation of officers From the building side

1.

5.

: Sh. Mithilesh Kumar Singh (Manager) 10. Year of Construction : 2009-10 (G+I<sup>st</sup>) & 2015 (II<sup>nd</sup> Floor) 11. Applicant's letter No

S. No	fire	nimum Standards on fire prevention and e safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR			
1.	Ac	Access to building Requirement site MR/NMR						
		Road width	Accessible 6 m	06 m	M/R			
		Gate width	4.5 m	Directly accessible	M/R M/R			
		Width of internal road	N/A	from road	N/A			
2.	Nu	mb <mark>er, Width, Type &amp; Arrangement of Exit</mark>	S	N/A				
	a. N	Number of staircases		1	1			
		Upper Floors	02 No 'e		100			
		Basements	02 No.'s	02 No.'s	MR			
			N/A	N/A	N/A			
	b. V	Vidth of staircases						
	'	Upper Floor	1.50 & .75 m	1.32 & .82 m	MR, being old			
	•	Basements	NI/A	21/4	case			
			N/A	N/A	N/A			
		rotection of exits  Fire check door						
			N/A	N/A	N/A			
	_	Fressurization	N/A	N/A	N/A			
	d. N	lo. of continuous staircases to						
		errace	Required	One	MR			
	e. W	idth of Corridor	Old Case	1.26 m	M/R, being old			
	f. D	oor Size	1.0	1.0	case			
			1.0 m	1.0 m	MR			
	Comp	partmentation						
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
	Smoke	Management System	1 1/2 1	TWA	IVA			
			N/A	NI/A	N//A			
	•	Basement		N/A	N/A			
	•	Upper floors	Required	Natural ventilation	MR			
	Fire Ex	tinguishers						
	•	Total numbers	05 no's	Provided	MR			
	•	Гуреѕ	ABC/CO <sub>2</sub> type	Provided	MR			
		S marking	ISI marked	Provided	MR			

MII

	First-Aid Hose Reels						
	<ul> <li>Total numbers on each floor</li> </ul>	N/A	N/A	N/A			
	Length of hose reel hose	N/A	N/A	N/A			
	Nozzle diameter	N/A	N/A	N/A			
	Automatic fire detection and alarming system		7177	18/73			
	<ul> <li>Type of detectors</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
	MOEFA	N/A	N/A	N/A			
	Public Address System	N/A	N/A	N/A			
0.	Automatic Sprinkler System	14/71	14/71	1772			
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	<ul> <li>Sprinkler above false ceiling</li> </ul>	· N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A			
	Dun-Tilang Agg	N/A N/A	N/A N/A	N/A N/A			
	<ul> <li>Pump House Access</li> <li>Terrace level</li> </ul>	TVA	14/7	IVA			
	► Discharge of pump	N/A	N/A	N/A			
	➤ Head of the pump	N/A	N/A N/A	N/A N/A			
	Power Supply	N/A	N/A	N/A N/A			
	Auto Starting of pump	N/A	N/A	N/A			
14.	Captive Water Storage for fire fighting			11/11			
14.	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A				
	Fire service inlet			N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	N/A	N/A	N/A			
		N/A	. N/A	N/A			
		N/A	N/A	N/A			



1712

16.	TIONS	ion of Lifts.					
					(No Lift)		
	•	Pressurization of Lift Shaft	N/A		,		
	•	Pressurization of Lift lobby		, N/A	N/A		
	•	Communication In lift Car	N/A	N/A	N/A		
	•	Fireman's Grounding Switch	N/A	N/A	N/A		
	•	Lift Signage	N/A	N/A	N/A		
17.	S4	-	N/A	N/A	N/A		
1/.	Stand	y power supply	N/A	N/A	N/A		
18.	Refuge Area						
	<b>A</b>	Total Area					
	>	Location	N/A	N/A	N/A		
			N/A	N/A	N/A		
19.	Fire Control Room						
	•,	Detector System Panel	N/A	N/A	N/A		
	<ul><li>Flow Switch Panel</li><li>PA System Panel</li></ul>	N/A	N/A	N/A			
		N/A	N/A	N/A			
	•	Battery backup	N/A	N/A	N/A		
	<u> </u>	Building Floor Plans	N/A	N/A	N/A		
20.	Specia of spec	Fire Protection System for Protection ial Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2017/SZ3/1332 dated 08/09/2017 renewal in accordance with the Circular No. F. 6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per letter submitted by the Manager (placed at C-17) the school is running at ground plus one upper floor and second floor of the building is used for storage purpose.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

D.O. (South West

22/2/2022

APOKKP1

PO