## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/Restaurant/WZ/ 75

Dated: 01/04/2022

## FIRE SAFETY CERTIFICATE

Certified that the M/s Burger King India Ltd. Shop No.21 to 24, Ground floor, situated at D Mall, Sector-10, Rohini, Delhi-110085, is running in a mall at ground floor comprised of Three Tiered Basement, Ground + five upper floors has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/2019/WZ/797 dated 10.04.2019. The premises was re-inspected by the officer concerned of this department on 03.03.2022 in the presence of Mr. Vijay (Store Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group D "Assembly" (Eating House) for Shop No.21 to 24, ground floor with effect from Olympic Value 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

ary

Copy to:-

1. The Dy. Health Officer, North MCD, Sec-5, Rohini Zone, Delhi-110085.

2. Authorized Signatory, M/s Burger King India Ltd. Shop No.21 to 24, Sector-10, D Mall, Rohini, Delhi-85.

## Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner/ occupier shall submit a declaration **every year** in **Form 'K'**[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms">http://delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms</a>
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

**INSPECTION REPORT** 

1. Name & address of the building: M/s Burger King India Ltd. Shop No.21 to 24 located at Gr. floor,

Sector-10, D Mall, Rohini, Delhi-110085.

2. Type of Occupancy : Assembly

3. Type of Case : Renewal (Ground floor Shop No. 21 to 24) 4. Details of Previous NOC

: F.6/DFS/MS/EH/2019/WZ/797 dated 10.04.2019 5. Fire Safety directives letter No : NBC Part-IV

6. Date of inspection : 03.03.2022

7. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)

8. Name and designation of officers

From the building side : Mr. Vijay (Store Manager)

9. Year of Construction : 2015

S. No.	Minimum Standards on the prevention	eation no.2022012701264 d NBC	Provided	Remarks			
	and fire safety U/R 33	Requirement	at site	MD/NMD			
.•	Access to building(Twin District Centre, D Mall, Sector-10, Rohini issued FSC vide letter No.F.6/DFS/MS/2021/WZ/420 dated 27.08.2021)						
	Road width	Accessible	Accessib	le MF			
	• Gate width	Accessible	Accessib	ble MR			
	Width of internal road	NA	NA	NA			
•	Number, Width, Type & Arrangement of [Provided & Maintained by Mall management]						
	a. Number of staircases						
	<ul> <li>Upper Floors</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Basements</li> </ul>	Restaurant within mall	As Above	MR			
	b. Width of staircases						
	<ul> <li>Upper Floor</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Basements</li> </ul>	Restaurant within mall	As Above	MR			
	c. Protection of exits						
	Fire check door	Restaurant within mall	As Above	MR			
	<ul> <li>Pressurization</li> </ul>	Restaurant within mall	As Above	MR			
	d. No. of continuous staircases to terrace	Restaurant within mall	As Above	MR			
	e. Width of Corridor	Restaurant within mall	As Above	MR			
	f. Door Size	2.0m	2.0m &1.5m	MR			
	Compartmentation						
	Fire check door	Restaurant within mall	As Above	MR			
	<ul> <li>Sealing of electrical shafts</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Fire Rating of shaft door</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Water Curtain</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Fire Dampers</li> </ul>	Restaurant within mall	As Above	MR			
	Smoke Management System [Provided & Ma		ient]				
	Basements	Restaurant within mall	As Above	e MR			
	Upper floors	Restaurant within mall	As Above	e MR			
	**						
	Fire Extinguishers	07nos.	08nos.	MF			
	Total numbers	ABC/CO2	ABC-03				
	• Types	ISI marked	Yes	MF			
	IS marking	151 marked	103	1711			
	First-Aid Hose Reels	01	As Abov	e MF			
	Total numbers on each floor	01					
	• Length of hose reel hose	30mm	As Abov				
	Nozzle diameter	5m	As Abov				
	Automatic fire detection and alarming system [Provided & Maintained by Mall management]						
	<ul> <li>Type of detectors</li> </ul>	Restaurant within mall	As Above				
	<ul> <li>Location of Main Panel</li> </ul>	Restaurant within mall	As Above	e MR			

	NIN			(F)			
	/			• 41			
	<ul><li>Location of Repeater Panel</li><li>Alternate source of power</li></ul>	Restaurant within mall	As Above	•.			
	Hooters' Location	Restaurant within mall	As Above	1			
8.	MOEFA	Restaurant within mall	As Above	$\frac{N}{M}$			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System (Provided a N	Restaurant within mall	As Above	MR 70.			
	Automatic Sprinkler System [Provided & M  Basement	laintained by Mall managemen	t]				
	<ul> <li>Ground &amp; Upper Floors</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Sprinkler above false ceiling</li> </ul>	Restaurant within mall	As Above	MR			
11.	Internal Hydrants [Provided & Maintained b	Restaurant within mall	As Above	MR			
	or insert down-comer						
	<ul> <li>Number of hydrants per floor</li> </ul>	100mm	As Above	MR			
	Hose Box	One(near to Restaurant)	As Above	MR			
12.	Yard Hydrants [Provided & Maintained by N	One(near to Restaurant)	As Above	MR			
	rotal number of hydrants	Restaurent					
	Hose Box	Restaurant within mall	As Above	MR			
13.	Pumping Arrangements [Provided & Mainte	Restaurant within mall	As Above	MR			
	Ground Level	management]					
	<ul><li>Discharge of main Pump</li></ul>	Restaurant within mall	A 41	100			
	Head of Main pump	Restaurant within mall	As Above	MR			
	Number of main pumps	Restaurant within mall	As Above	MR			
	> Jockey Pump out put	Restaurant within mall	As Above	MR			
	Jockey pump head	Restaurant within mall	As Above As Above	MR			
	Standby Pump out put	Restaurant within mall	As Above As Above	MR MR			
	Standby Pump Head	Restaurant within mall	As Above	MR			
	Auto Starting/Manual Stopping	Restaurant within mall	As Above As Above	MR			
	Pump House Access	Restaurant within mall	As Above	MR			
	Terrace level		A S AUUVE	IVIIX			
	> Discharge of pump	NA	As Above	MR			
	> Head of the pump	NA	As Above	MR			
	Power Supply	Required	As Above	MR			
	Auto Starting of pump	Required	As Above	MR			
14.	Captive Water Storage for firefighting [Provided & Maintained by Mall management]						
	Underground tank capacity	Restaurant within mall	As Above	MR			
	> Draw-off connection	Restaurant within mall	As Above	MR			
	> Fire service inlet	Restaurant within mall	As Above	MR			
	Access to tank	Restaurant within mall	As Above	MR			
	Overhead Tank capacity	Restaurant within mall	As Above	MR			
5.	Exit Signage.	Required	Provided	MR			
6.		ned by Mall management]	Tiovided	IVIK			
	Pressurization of Lift Shaft     Pressurization of Lift Shaft	Restaurant within mall	As Above	MR			
	Pressurization of Lift lobby     Communication In 1th Communication	Restaurant within mall	As Above	MR			
	Communication In lift Car     Firemen's Grounding Switch	Restaurant within mall	As Above	MR			
	<ul> <li>Fireman's Grounding Switch</li> </ul>	Restaurant within mall	As Above	MR			
	Lift Signage		A - A1	MR			
	Lift Signage	Restaurant within mall	As Above	IVIIC			
7.	Lift Signage  Standby power supply	Restaurant within mall Required	As Above As Above	MR			
		Required					
7.	Standby power supply Refuge Area. [Provided & Maintained by M	Required [all management]	As Above	MR			
	Standby power supply  Refuge Area. [Provided & Maintained by M	Required [all management] NA	As Above	MR NA			
	Standby power supply  Refuge Area. [Provided & Maintained by M  > Total Area	Required [all management]  NA  NA	As Above	MR			

7 (77)		
Restaurant within mall	As Above	MR
Restaurant within mall	As Above	MR
Restaurant within mall	As Above	MR
Restaurant within mall	As Above	MR
NA	Kitchen suppression	NA
	installed	
	Restaurant within mall Restaurant within mall Restaurant within mall Restaurant within mall NA	Restaurant within mall As Above Restaurant within mall As Above NA Kitchen suppression system & gas detector found

tems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/EH/2019/WZ/797 dated 10.04.2019 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO (Rohini)

FT letter is put up for and perusal and Degnature please.