

430



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2022/SZ/ 84

Dated: 11 / 4 / 2022

FIRE SAFETY CERTIFICATE

Certified that the **M/s EMBEY Restaurant** situated at **A-279/3, A Block, Mahipalpur Extn, New Delhi -110037** located at ground floor of a building comprised of Basement, Ground plus Three Upper floor was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2018/SZ/249 dated 15/02/2018 for the name of Barichi Restaurant. The restaurant premise was re-inspected by the officer concerned of this department on 05/04/2022 in the presence of Mr. Bhushan Kumar Jain and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** (**Restaurant at Ground floor only**) with effect from 11/.../.../2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 11 / 4 / 2022 at New Delhi by

**(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)**

Copy to: -

1. The DHO, Public Health Department, (Najafgarh Zone), SDMC, Najafgarh, New Delhi-110043, (Ref. MHA Portal ID 2022032804302 dated 28/03/2022)
2. M/s EMBEY Restaurant situated at A-279/3, A Block, Mahipalpur Extn, New Delhi - 110037.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

2/11

INSPECTION REPORT

	Name & Address of the Building	M/s EMBEY Restaurant situated at A-279/3, A Block, Mahipalpur Extn, New Delhi -37		
2	Type of Occupancy	Group-D-4 Assembly		
3	Building Comprised of	Basement, Ground + Three upper floor		
4	Type of Case	Renewal / Name Change		
5	Details of Previous NOC	F6/DFS/MS/EH/2018/SZ/249 Dated 15/02/2018 for the name of Barichi Restaurant		
6	Fire Safety Directives Letter No	UBBL / NBC - 2016		
7	Date of Inspection	05/04/2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Bhushan Kumar Jain		
10	Year of construction	2014	Restt. running at ground floor of the building	
11	Applicant letter No.	MHA Portal ID 2022032804302 dt 28/03/2022		
S.No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	Road width	Required	12 mtr	MR
	Gate width	N/A	N/A	N/A
	Width of internal road	N/A	N/A	N/A
2	Number, width, type & arrangement of exits.			
	Number of Staircase			
	Upper floors.	N/A	N/A	N/A
	Basement floor.	N/A	N/A	N/A
	Width of Staircase			
	Upper floors	N/A	N/A	N/A
	Basement floor	N/A	N/A	N/A
	Protection of exits			
	Fire check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
	No. of continuous staircase to terrace	N/A	N/A	N/A
	Width of corridor	N/A	N/A	N/A
	Door size	Two exit	1.0 & 2.0 mtr	MR /old case
3	Compartmentation.			
	Fire check door.	N/A	N/A	N/A
	Sealing of electrical shafts.	N/A	N/A	N/A
	Fire rating of shaft door.	N/A	N/A	N/A
	Water curtain	N/A	N/A	N/A
	Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.			
	Basement	12 ACPH	N/A	N/A
	Upper floors	12 ACPH	Exhaust fan Provided in restt.	MR
5	Fire Extinguishers.			
	Total numbers	05 Nos	05 Nos	MR
	Types	ABC/CO ₂	ABC & CO ₂	MR
	ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.			
	Total numbers on each floor.	One	Provided	MR
	Length of hose-reel hose.	30m	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming system.			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A

W/12

20 Bu S

	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground floor & upper floor	Required	Provided in restt.	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.			
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	Provided	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	10,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A

N/13

	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 167 dated 07/04/2021

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2018/SZ/249 Dated 15/02/2018 for the name of Barichi Restaurant, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended for the name of M/s EMBEY Restaurant.

Accordingly, DFA is put up for approval and signature please.

RK
5/4/2022

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/BCP

DO (SD) = on m/Reol F.T.

Dy CPO/SZ
[Signature]

ADO/BCP
[Signature]

As approved, f.t. letter is put up for your signature @

RK
8/4

Dy CPO/SZ
[Signature]

MCS . *[Signature]*

Uploaded
[Signature]
14/04/2022