## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2022/91

Dated 13 / 4 /2022

## FIRE SAFETY CERTIFICATE

Certified that M/s Tata Starbucks Pvt Ltd. (A Unit of Starbucks Coffee A Tata Alliance) located at Shop No 61, Ground Floor, Basant Lok Vasant Vihar, New Delhi-110057 in the building comprised of Basement, Ground plus Two Upper Floors owned /occupied by Starbucks Coffee A Tata Alliance have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 02/04/2022 in the presence of Mr. Tanuj Chauhan and that the premise is fit for occupancy class Group—D Assembly Building (Restaurant at Ground Floor only) with effect from 13/4/2022 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13 / 4 /2022 at New Delhi by

Copy to: -

- The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016 (Ref. MHA Portal ID 2022020901868 dated 09/02/2022)
- 2. M/s Tata Starbucks Pvt Ltd. (Starbucks Coffee A Tata Alliance) located at Shop No 61, Ground Floor, Basant Lok Vasant Vihar, New Delhi-110057.

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	INSPECTIO	N REPORT			
1	Name & Address of the Building	M/s Tata Starbu	cks Pvt Ltd. (Starbucks	Coffee A	
		Tata Alliance) Shop No 61, Ground Floor, Basant Lok Vasant Vihar, New Delhi-110057.			
2	Type of Occupancy	Assembly Building "Group-D" Restaurant			
3	Building Comprised of	Basement, Ground plus Two Upper Floors,			
		Restaurant at Ground floor only.			
4	Type of Case	New Case			
5	Details of Previous NOC	Nil Nil			
6	Fire Safety Directives Letter No	F6/DFS/MS/2021/SZ/150 dated 05/02/2021 for PVF			
		Priya Cinema.			
7	Date of Inspection	02/04/2022			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers	Mr. Tanuj Chauh	an		
	from the building side	2021			
10	Year of construction	2021	2022020901868 dated 09	/02/2022	
11	Applicant letter No.		Provided at Site	Remarks	
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	MR/NMR	
	Access to Building. FSC No. F6/DFS/MS/	2021/SZ/150 date	d 05/02/2021 for PVR Pr	iya Cinema	
1	Road width	Restaurant	As above	MR	
	Road width     Gate width	Priya Cinema	As above	N/A	
	Width of internal road	NA	As above	N/A	
2	Number, width, type and arrangements of exits.  a. Number of Staircase Provided & Maintained by PVR Priya Cinema				
	a. Number of Staircase	N/A	As above	N/A	
	Upper floors	N/A	As above	N/A	
	Basement floor		ded in PVR Priya Cinem	a	
	b. Width of Staircase	N/A	As above	N/A	
	Upper floors	N/A	As above	N/A	
	Basement floor	Provided in PVR Priya Cinema			
	c. Protection of exits	N/A As above N/A			
	Fire check door	N/A	As above	N/A	
	Pressurization	Required	As above	MR	
	d. No. of continuous staircase to terrace	N/A	N/A	N/A	
	e. Width of corridor	2 No's Exit each	1.50 mtr & 1.50 mtr	MR	
	f. Door size	1.50 mtr		o Cinema	
3	Compartmentation.	Provided & Maintained by PVR Priya Cinema  Required As above MR			
	Fire check door.	Required	As above	MR	
	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	Provided Provided	MR	
	<ul> <li>Fire rating of shaft door.</li> </ul>	2 hrs	N/A	N/A	
	Water curtain	N/A		N/A	
	Fire dampers.	N/A	N/A		
4.	Smoke Management system.		Maintained by PVR Priy	N/A	
	Basement	N/A	As above		
	Upper floors	Required	Exhaust fans provided	IVIK	
5.	Fire Extinguishers.			) AD	
	Total numbers	20 Nos	30 Nos.	MR	
	• Types		ABC-04, W.CO <sub>2</sub> -02	MR	
	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.	Provided &	Maintained by PVR Pri	ya Cinema	
6.			02 in Restaurant	MR	
	<ul> <li>Total numbers on each floor.</li> </ul>		30m	MR	
	Length of hose-reel hose.	Hose Reel	John	MR	

7	Automatic Fire Detection and Alarming s	ystem.	ettis terresi li lauren alligilia, us massus e alastellik herijak eti e ete atal matelje seestel			
	Type of detectors	Required	Smoke & Heat	MR		
	<ul> <li>Location of Main Panel</li> </ul>	Required	As above	MR		
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Alternate source of power</li> </ul>	Required	As above	MR		
	<ul> <li>Hooter's location</li> </ul>	Required	As above	MR		
8.	MOEFA	Required	As above	MR		
9.	Public Address System	Required	As above	MR		
10.	Automatic Sprinkler System		Maintained by PVR Priya			
	Basement	Required	As above	MR		
	<ul> <li>Upper floors</li> </ul>	Required	Provided in Restt.	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants.		Provided & Maintained by PVR Priya Cinema			
	Size of Riser/Down-comer	Required	As above	MR		
	Number of Hydrant per floor	Required	As above	MR		
	Hose box	Required	As above	MR		
12.	Yard Hydrants.	_	Maintained by PVR Priya			
	Total number of hydrants.	N/A	As above	N/A		
	• 2. Hose box.	N/A N/A				
13.	Pumping arrangements.	N/A	As above	N/A		
	Ground Level	D il 10 Min il 11 Direction				
			Provided & Maintained by PVR Priya Cinema			
	beinge of main pump.	2280 LPM	As above	MR		
	<ul><li>Head of main pump.</li><li>Number of main pumps.</li></ul>	70 mtr	As above	MR		
	Jockey Pump output.	Two	As above	MR		
	> Jockey Pump head.	180 LPM	As above	MR		
	Standby Pump output.	70 mtr 2280 LPM	As above	MR		
	Standby Pump head.	70 mtr	As above	MR		
	<ul><li>Auto Starting / Manual Stopping.</li></ul>	Required	As above As above	MR		
	Access to pump house	Required	As above	MR		
	Terrace Level	Required As above MR Provided & Maintained by PVR Priya Cinema				
	<ul><li>Discharge of pump.</li></ul>	900 LPM	As above			
	<ul><li>Head of pump.</li></ul>	35 m	As above	MR		
	Power supply.	Required	As above	MR		
	Auto starting of pump.	Required	As above	MR		
14.	Captive water storage for Fire Fighting.	-	Maintained by PVR Priya	MR		
	Underground tank capacity.	2,00,000 Ltrs	As above	MR		
	Draw-off connection.	Required	As above			
	Fire Service Inlet.	Required	As above	MR MR		
	> Access to tank.	Required	As above			
	Overhead tank capacity.	20,000 Ltrs	As above	MR		
15.	Exit Signage.	Required	Provided	MR MR		
16.	Provision of Lifts.	•	Maintained by PVR Priya			
	Pressurization of lift shaft.	Required	As above	MR		
	Pressurization of lift lobby.	Required	As above	MR		
	Communication in lift car.	Required	As above	MR		
	Fireman's switch.	Required	As above			
	Lift signage.	Required	As above As above	MR MR		
17	Standby Power Supply	Required				
18.	Refuge Area	Required	Provided (DG Set)	MR		
16.	Neinge Alex	NT/A	27/4	21/4		
	<ul><li>Total area</li><li>Location</li></ul>	N/A N/A	N/A N/A	N/A N/A		
19.	Fire Control Room.		Maintained by PVR Priya			
	> Control ROUIII,	rioviaea & N	VIAINTAINEG DV PVK PRIVA	Cinema		

4.000-00-00-00-00-0	Flow Switch Panel.	Required	As above	MR
	<ul><li>PA system Panel.</li><li>Battery backup</li><li>Building floor plan</li></ul>	Required	As above	MR
		Required	As above	MR
		Required	As above	MR
20.	Special Fire Protection System for the Protection of special Risk, if any:	Required	As above	MR

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Designation: ADO / BCP

DO (SD) on M) Rest

Defos

600

614/2

614

P/ 5 8

en

10 8/04/or

Anysup

out yout