## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/Restaurant/WZ/97

Dated: 21 04 2022

## FIRE SAFETY CERTIFICATE

Certified that the Dawat-E-Mehfil, GA-7 & 8, Ground Floor, Metro Walk, Sector-10, Rohini, Delhi - 110085, restaurant is running at ground floor of a building comprised of Ground + One floor owned/ occupied by Amusement Park has already been issued FSC by this department vide letter No. F.6/DFS/MS/2019/926 dated 01/05/2019. The premises was re-inspected by the officer concerned of this department on 11.04.2022 in the presence of Sh. Ashwani Sehgal (General Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Class (Assembly Restaurant) for GA-7 & 8, Ground Floor with effect from 21/04/2022 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .21/04/2022 at New Delhi by

(Dhrampal Bhardwaj) Dy.Chief Fire Officer

Tel;-01123414250

Copy to :-

1. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054.

2. Sh. Narinder Kumar Walia, Dawat-E-Mehfil, GA-7 & 8, Ground Floor, Metro Walk, Sector-10, Rohini, Delhi - 110085

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available WWW.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT 1. Name & address of the building: Dawat-E-Mehfil, GA-7 & 8, Ground Floor, Metro Walk, Sector-10, Rohini, Delhi – 110085. (Previous FCS Name is Dawat-e-Mahfil (A unit of Duke Retail) GA-7 & 8, Gr. Floor, Metro Walk, Sec-10, Rohini. 2. Type of Occupancy : Assembly Building (Restaurant) 3. Type of Case : Renewal (Ground floor unit No.GA-7 & 8) 4. Details of Previous NOC : F6/DFS/MS/2019/926 dated 01/05/2019 5. Fire Safety directives letter No 6. Date of inspection : 11.04.2022 7. Name of Inspecting Officer : A.K.Sharma ADO (Rohini) 8. Name and designation of officers From the building side : Sh. Ashwani Sehgal (General Manager) 9. Year of Construction 2006-07 10. Applicant's letter No. Online e-mail Dated 08.04.2022. Minimum Standards on fire prevention S. UBBL/NBC Provided at site Remarks and fire safety U/R 33 No. Requirement MR/NMR 1. Access to building [Amusement Park of Adventure Island, Metro Walk issued FSC vide letter No. F.6/DFS/MS/WZ/2020/427 dated 22.10.2020] Road width Gate width Restaurant within Mall As Above MR Width of internal road Number, Width, Type & Arrangement of Exits[Provided & Maintained by Mall management] 2. d. Number of staircases Upper Floors Restaurant within Mall As Above NA Basements Restaurant within Mall As Above NA e. Width of staircases Upper Floor Restaurant within Mall As Above NA Basement Restaurant within Mall As Above NA f. Protection of exits Fire check door Restaurant within Mall As Above NA Pressurization Restaurant within Mall As Above NA d. No. of continuous staircases to terrace Restaurant within Mall As Above NA e. Width of Corridor Restaurant within Mall As Above NA f. Door Size 1.5 m 1.2m &1.0 m MR (Old case) 3. Compartmentation Fire check door Restaurant within Mall As Above NA Sealing of electrical shafts Restaurant within Mall As Above Fire Rating of shaft door NA Restaurant within Mall As Above Water Curtain NA Restaurant within Mall Fire Dampers As Above NA Restaurant within Mall As Above NA

		11				
4.	Smoke Management System[Provided & Maintained by Mall management]			NA		
4.	Basements	30 ACFII		MR		
	Upper floors	12 ACPH	Natural Ventilated	1712		
5.	Fire Extinguishers		0.431	MR		
	Total numbers	03 No's	04Nos	MR		
	• Types	ABC/CO <sub>2</sub> /W.CO <sub>2</sub>	ABC-2/Wco2-02			
	IS marking	ISI marked	Provided	MR		
6.	First-Aid Hose Reels[Provided & Maintained by Mall management]					
	<ul> <li>Total numbers on each floor</li> </ul>	One (Near to Restaura		MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	As Above	MR		
	Nozzle diameter	5 mm	As Above	MR		
7.	Automatic fire detection and alarming system[Provided & Maintained by Mall manage					
	Type of detectors	Required	Provided	MR		
	<ul> <li>Location of Main Panel</li> </ul>	NA	As Above	NA		
	<ul> <li>Location of Repeater Panel</li> </ul>	NA	As Above	NA		
	Alternate source of power	NA	As Above	NA		
	Hooters' Location	NA	As Above	NA		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	NA	As Above	NA		
10.	Automatic Sprinkler System[Provided & Maintained by Mall management]					
	Basement	NA	As Above	NA		
	Ground Floor	NA	As Above	NA		
	Sprinkler above false ceiling	NA .	As Above	NA		
11.	Internal Hydrants[Provided & Maintained by Mall management]					
	Size of riser/down-comer	100mm	As Above	MR		
	Number of hydrants per floor	One (near to Restaura	nt) As Above	MR		
	Hose Box	One (near to Restaura	nt) As Above	MR		
12.	Yard Hydrants[Provided & Maintained by Mall management]					
	Total number of hydrants	NA	NA	NA		
12	Hose Box	NA	NA	NA		
13.	Pumping Arrangements[Provided & Maintained by Mall management]					
	Ground Level					
	Discharge of main Pump	NA	NA	NA		
	Head of Main pump	NA	NA	NA		
	Number of main pumps	NA	NA	NA NA		
	> Jockey Pump out put	NA	NA	NA		
	> Jockey pump head	NA	NA	NA NA		
	Standby Pump out put	NA	NA	NA NA		
	Standby Pump Head	NA	NA			
	Auto Starting/Manual Stopping	NA	NA NA	NA		
			11/1	NA		

,	> Pump House Access						
	, amp rouse Access	NA	NA	NA			
	Terrace level	[Provided & Mainta	[Provided & Maintained by Mall management]				
	Discharge of pump	NA	As Above	MR			
	➤ Head of the pump	NA	As Above	MR			
	> Power Supply	Required	As Above	MR			
	Auto Starting of pump	Required	As Above	MR			
4.	Captive Water Storage for firefighting[Provided & Maintained by Mall management]						
	<ul> <li>Underground tank capacity</li> </ul>	NA	As Above	NA			
	Draw-off connection	NA	As Above	NA			
	Fire service inlet	NA	As Above	NA			
	Access to tank	NA	As Above	NA			
	<ul> <li>Overhead Tank capacity</li> </ul>	NA	As Above	MR			
5.	Exit Signage.	Required	Provided	MR			
6.	Provision of Lifts.[Provided & Maintained by Mall management]						
	Pressurization of Lift Shaft	NA	NA	NA			
	<ul> <li>Pressurization of Lift lobby</li> </ul>	NA	NA	NA			
	Communication In lift Car	NA	NA	NA			
	<ul> <li>Fireman's Grounding Switch</li> </ul>	NA	NA	NA			
	<ul> <li>Lift Signage</li> </ul>	NA	NA	NA			
17.	Standby power supply	Required	As Above	MR			
18.	Refuge Area.[Provided & Maintained by Mall management]						
	> Total Area	NA	NA	NA			
	Location	NA	NA	NA			
19.	Fire Control Room[Provided & Maintained by Mall management]						
	Detector System Panel	NA	NA	NA			
	<ul> <li>Flow Switch Panel</li> </ul>	NA	NA	NA			
	<ul> <li>PA System Panel</li> </ul>	NA	NA	NA			
	Batter backup	NA	NA	NA			
	<ul> <li>Building Floor Plans</li> </ul>	NA	NA	NA			
20.	Special Fire Protection System for	NA	NA	NA			
	Protection of special Risks, if any:						

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

ase)

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in UBBL/NBC Part-4, and removal of shortcomings issued vide

letter no. 250 dated 16.03.2022, the FSC issued vide letter no. F.6/DFS/MS/2019/926 dated 01/05/2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

DO (NW)

DH CO (M2)

2014/2014

partedini Sir, F. T is put up for you persual & Signalum please

Dycko(w2)

2/1/1/2012

M81 WY