

E-53

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

No. F.6/DFS/MS/EH/2022/SZ/117 **NEW DELHI-110001**

Dated 05/05/2022

FIRE SAFETY CERTIFICATE

Certified that M/s Kasbah Restaurant, (A Unit of The Alliance Group) at N Block Market, Greater Kailash-1, New Delhi 110048 comprised of Basement, ground plus two Upper floors, but **restaurant running at First Floor only** owned/occupied by A Unit of The Alliance Group was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2019/SZ/1439 Dated 15/07/2019. The restaurant premise was re-inspected by the officer concerned of this department on 21/04/2022 in the presence of Mr. Mandeep Singh and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building" (Restaurant running at First Floor only)** as above with effect from 05/05/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 05/05/2022 at New Delhi by


(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-16
(Ref. MHA Portal ID 2022040305300 dated 03/04/2022)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

N/19

INSPECTION REPORT

| | | | | |
|--------------|--|---|-------------------------|-----------------------|
| 1 | Name & Address of the Building | M/s Kasbah Restaurant, (A Unit of The Alliance Group) at N Block Market, Greater Kailash-I, New Delhi 110048. | | |
| 2 | Type of Occupancy | Group D-4 Assembly (Restaurant at 1st Floor) | | |
| 3 | Building Comprised of | Basement, Ground + Two upper floor | | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F6/DFS/MS/E/11/2019/SZ/1439 Dt. 15/07/2019 | | |
| 6 | Fire Safety Directives Letter No | Circular dated 04.04.2005 | | |
| 7 | Date of Inspection | 21/04/2022 | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar, ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Mr. Mandeep | | |
| 10 | Year of construction | 2005 | | |
| 11 | Applicant letter No. | MHA Portal ID 2022040305300 dated 03/04/2022 | | |
| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Rule 35(6) Requirements | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. | | | |
| | Road width | 4-5 mtr | Provided | MR |
| | Gate width | N/A | N/A | N/A |
| | Width of internal road | N/A | N/A | N/A |
| 2 | Number, width, type & arrangement of exits. | | | |
| | a. Number of Staircase | | | |
| | Upper floors. | 02 No's | 02 Nos | MR |
| | Basement floor. | N/A | N/A | N/A |
| | b. Width of Staircase | | | |
| | Upper floors | 1.25 mtr | 1.30 & 1.20 mtr | MR |
| | c. Basement floor | N/A | N/A | N/A |
| | d. Protection of exits | | | |
| | Fire check door | N/A | N/A | N/A |
| | e. Pressurization | N/A | N/A | N/A |
| | f. No. of continuous staircase to terrace | Required | 01 Provided | MR |
| | g. Width of corridor | N/A | N/A | N/A |
| | h. Door size | 2 Nos | 02 Nos provided | MR (old case) |
| 3 | Compartmentation. | | | |
| | Fire check door. | N/A | N/A | N/A |
| | Sealing of electrical shafts. | N/A | N/A | N/A |
| | Fire rating of shaft door. | N/A | N/A | N/A |
| | Water curtain | N/A | N/A | N/A |
| | Fire dampers. | N/A | N/A | N/A |
| 4 | Smoke Management system. | | | |
| | Basement | 12 ACPH | N/A | N/A |
| | Upper floors | 12 ACPH | Exhaust fan | MR |
| 5 | Fire Extinguishers. | | | |
| | Total numbers | 12 Nos | 12 Nos | MR |
| | Types | ABC/CO ₂ | ABC & CO ₂ | MR |
| | ISI Marking | ISI marked | Provided | MR |
| 6 | First Aid Hose Reels. | | | |
| | Total numbers on each floor. | One | Provided | MR |
| | Length of hose-reel hose. | 30m | Provided | MR |
| | Nozzle Diameter | 5mm | Provided | MR |
| 7 | Automatic fire detection & alarming system. | | | |
| | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |

2/80

| | | | | |
|----|--|---------------|----------|-----|
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooter's location | N/A | N/A | N/A |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System | N/A | N/A | N/A |
| 10 | Automatic Sprinkler System | | | |
| | Basement | N/A | N/A | N/A |
| | Restaurant area | Required | Provided | MR |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants. | | | |
| | Size of Riser/Down-comer | 100 mm | Provided | MR |
| | Number of Hydrant per floor | One | Provided | MR |
| | Hose box. | One | Provided | MR |
| 12 | Yard Hydrants. | | | |
| | Total number of hydrants. | N/A | N/A | N/A |
| | Hose box. | N/A | N/A | N/A |
| 13 | Pumping arrangements. | | | |
| | Ground Level | | | |
| | Discharge of main pump. | N/A | N/A | N/A |
| | Head of main pump. | N/A | N/A | N/A |
| | Number of main pumps. | N/A | N/A | N/A |
| | Jockey Pump output. | N/A | N/A | N/A |
| | Jockey Pump head. | N/A | N/A | N/A |
| | Standby Pump output. | N/A | N/A | N/A |
| | Standby Pump head. | N/A | N/A | N/A |
| | Auto Starting/Manual Stopping. | N/A | N/A | N/A |
| | Pump house access. | N/A | N/A | N/A |
| | Terrace Level | | | |
| | Discharge of pump. | 450 & 225 LPM | Provided | MR |
| | Head of pump. | 39m & 38m | Provided | MR |
| | Power supply. | Required | Provided | MR |
| | Auto starting of pump. | Required | Provided | MR |
| 14 | Captive water storage for fire fighting. | | | |
| | Underground tank capacity. | N/A | N/A | N/A |
| | Draw-off connection. | N/A | N/A | N/A |
| | Fire Service Inlet. | Required | Provided | MR |
| | Access to tank. | N/A | N/A | N/A |
| | Overhead tank capacity. | 10,000 Ltrs | Provided | MR |
| 15 | Exit Signage. | Required | Provided | MR |
| 16 | Provision of Lifts. | | | |
| | Pressurization of lift shaft. | N/A | N/A | N/A |
| | Pressurization of lift lobby. | N/A | N/A | N/A |
| | Communication in lift car. | N/A | N/A | N/A |
| | Fireman's switch. | N/A | N/A | N/A |
| | Lift signage. | N/A | N/A | N/A |
| 17 | Standby Power Supply | Required | Provided | MR |
| 18 | Refuge Area | | | |
| | Total area | N/A | N/A | N/A |
| | Location | N/A | N/A | N/A |
| 19 | Fire Control Room. | | | |
| | Detector system panel. | N/A | N/A | N/A |
| | Flow switch panel. | N/A | N/A | N/A |
| | PA system panel. | N/A | N/A | N/A |
| | Battery backup. | N/A | N/A | N/A |

N/21

| | | | | |
|----|--|-----|-----|-----|
| | Building floor plan. | N/A | N/A | N/A |
| 20 | Special Fire Protection System for the Protection of special Risk, if any. | N/A | N/A | N/A |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2019/SZ/1439 Dt. 15/07/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name: - Sh. Rajesh Kumar
Designation: - ADO/BCP

DO(SD)

21/7/2019

DyFO(S2)

ADO/BCP

As approved, F.T. letter is put up for your signature pl

DyFO(S2)

M.S. UP

1/14/2019