GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2022/136

Dated 23 /05/2022

FIRE SAFETY CERTIFICATE

Certified that M/s Bikanervala International, located at 7, Masjid Moth, Greater Kailash-II, New Delhi- 110048 comprised of Basement, ground plus Two Upper floors Owned/occupied by Mr. Umesh Aggarwal was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/SZ/2019/183 Dt. 25/01/2019. The restaurant premise was reinspected by the officer concerned of this department on 18/05/2022 in the presence of Mr. Bhagwati Prashad of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules. 2010 and that the premises is fit for occupancy Class D "Assembly Building" with effect from 23/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on $\frac{33}{0.5}$ /2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-16 (Ref. MHA Portal ID 2022050309213 dated 03/05/2022).
- 2. M/s Bikanervala International, located at 7, Masjid Moth. Greater Kailash-II, New Delhi- 110048

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

171

N	90
(4	0

, , ,

	INSPECTIO	ON REPORT			
1	Name & Address of the Building	M/s Bikanervala International, located at 7,			
2			eater Kailash-II, N		
2	Type of Occupancy	Group-D-4 Assembly			
3	Building Comprised of	Basement, Ground + 02 upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/EH/SZ/2019/183 Dt. 25/01/2019			
6	Fire Safety Directives Letter No	F6/DFS/MS/EH/2005/718 dated 04/04/2005			
7	Date of Inspection	18/05/2022			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar, ADO (BCP)			
9	Name & Designation of Officers	Mr. Bhagwati Prashad			
	from the building side				
10	Year of construction	2005			
11	Applicant letter No.	MHA Portal ID 2022050309213 dated 03/05/2022			
S.	Minimum standards on Fire Prevention	Old NOC Provided at Site Remarks			
No.	and Fire Safety U/R 33	Requirements	Trovided at Site	MR/NMR	
1	Access to Building.	Requirements		MICHVIN	
	Road width	Required	9 mtr	MR	
	Gate width	Required		N/A	
	Width of internal road	N/A	Approachable		
2	Number, width, type & arrangement of e		N/A	N/A	
		AIIS.			
	a. Number of Staircase				
	Upper floors.	02 No	Provided	MR	
	Basement floor.	02 No	Provided	MR	
	b. Width of Staircase				
	Upper floors	1.25 mtr	0.92m & 1.10m	MR (old case)	
	c. Basement floor	1.25 mtr	0.92m & 1.10m	MR (old case)	
	d. Protection of exits				
	Fire check door	Required	Provided	MR	
	e. Pressurization	N/A	N/A	N/A	
	f. No. of continuous staircase to terrace	Required	Provided	MR	
	g. Width of corridor	N/A	N/A	N/A	
	h. Door size	2 exits	1.70m & 1.05m	MR (old case)	
3	Compartmentation.				
	Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts.	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
1	Smoke Management system.	IN/A	IV/A	IN/A	
4	Smoke Management system.				
	Basement	30 ACPH	Exhaust fan provided	MR	
	Upper floors	12 ACPH	Exhaust fan provided	MR	
5	Fire Extinguishers.				
	Total numbers	10 Nos	10 Nos	MR	
	Types	ABC/CO ₂	ABC & CO ₂	MR	
	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.				
	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming syst		riorided	IVIIC	
7		Required	Smoke & heat	MR	
	Type of detectors				
	Location of Main Panel	Required	Ground floor	MR	

Non

	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Battery backup	MR
	Hooter's location	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System	IVA	111121	
	Basement	Required	Provided	MR
	Restaurant area	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.	14/74	.,,,,,	
11	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.	One	1101100	
12	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	13/13	1	
13	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level	IVA	1,1,1,1	
	Discharge of pump.	450 & 180 LPM	Provided	MR rold case
	Head of pump.			
	Power supply.	35m	Provided	MR
	Auto starting of pump.	Required	Provided	MR
		Required	Provided	MR
14	Captive water storage for fire fighting.	21/4	N/A	N/A
	Underground tank capacity	N/A N/A	N/A	N/A
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet. Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltrs	Provided	MR jold case
1.5		Required	Provided	MR
15	Exit Signage. Provision of Lifts.	required	Trovided	
16	Pressurization of lift shaft.	N/A	N/A	NA
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N.A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
_	Total area	N/A	N/A	NA
	Location	N/A	N/A	NA
9	Fire Control Room.		-	
	Detector system panel	N/A	N/A	NA
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N'A	N/A
	Battery backup.	N/A	N'A	

N/22

20	Building floor plan.	N/A	N/A	N/A
	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2019/183 Dt. 25/01/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: - Sh. Rajesh Kumar Designation: - ADO/BCP

DO (8D)

LIV P

Difo(b)

F. f.

As approved

ADO/B(P

pulip

Jane

Synatuse

23/5/22

Dychysz

uphoaded

whishon