## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/SZ/2022/ 252

Dated: 07/06/2022

## FIRE SAFETY CERTIFICATE

Certified that the **Hemkunt House** located at Plot No. 06, Rajendra Place, New Delhi-110008, comprised of Basement, Ground plus thirteen upper floors was issued No Objection Certificate by this department vide letter No. F6/MS/DFS/2003/2431 dated 09.10.2003 for occupancy of building and re-inspected by the officers concerned of this department on 30.05.2022 in presence of Mr. Baldev Dhiman, Building Manager, and found that the said business building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class Group E (Business Building) with effect from for produced and subject to compliance of the conditions under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 67/66/2692 at New Delhi by.

Director Delhi Fire Service

Copy to: -

- 1. The Building Manager, Hemkunt House, 06, Rajendra Place, New Delhi-110008.
- 1. The Joint Director (Building) C&I, DDA, Building Section, DDA, Vikas Sadan, INA, New Delhi.

## Following Fire Safety Directives Must Be Adhered To:-

- Providing of fire safety measures does not give any guarantee that there will be No fire. These
  equipments/installation can minimize the losses if maintained in good working condition and
  handled efficiently in case of fire.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.



## INSPECTION REPORT

: Hemkunt House, 6, Rajendra Place, New Delhi- 110008. 1. Name & address of the building

: Business (Class - E)

: Building comprised of basement, ground plus thirteen upper 2. Type of Occupancy 3. Building Composition

floors

: Renewal 4. Type of Case

: F6/MS/DFS/2003/2431 dated 09.10.2003 5. Details of previous NOC

: F6/DFS/MS/2002/1569 dated 16.09.2002 6. Fire Safety directives letter No

: 30.05.2022 7. Date of inspection

: Vedpal Chhikara, DO (SW) & P.V. Rathee, ADO (SRD) 8. Name of the Inspecting Officers

9. Name and designation of officers

P

: Mr. Baldev Dhiman, Building Manager from the building side

: Before 1987 9. Year of Construction

: Online email Id hemkuntassociation@gmail.com dated 26.05.2022

	M	inimum Standards on fire	Requirement as per NOC dt. 09.10.2003	ation@gmail.com da  Provided at site	Remarks MR/NMR		
0.	prevention and fire safety U/R 33  Access to building Provided MR						
			09 mts	Provided	MR		
		Road width	06 mts	Provided	MR		
		Gate width	N/A	N/A	N/A		
	•	Width of internal road					
	Numbe	er, Width, Type & Arrangement of					
		ber of staircases	02	02	MR		
	•	Upper Floors	02.	02	MR		
	•	Basements	02				
	h Wid	th of staircases			MR		
	0. Wid		1.25 & 0.75 mts	1.26 & 0.95 mts			
	•	Upper Floors	1.25 & 0.75 mts	1.26 & 0.95 mts	MR		
	•	Basements					
	c. Prot	ection of exits	Required	Provided	MR		
	•	Fire check door	•	N/A	N/A		
		Pressurization	N/A				
	.,	of continuous staircases to terrace	01	01	MR		
	1		N/A	N/A	N/A		
	g. Wie	ith of Corridor	N/A	N/A	N/A		
	h. Do	or Size	N/A	1			
3	Com	partmentation.		D :1.1	MR		
		Fire check door	Required	Provided	IVIK		
			Required	Sealed	MR		
	•	Sealing of electrical shafts	N/A	N/A	N/A		
	•	Fire Rating of shaft door	N/A	N/A	N/A		
	•	Water Curtain	N/A	N/A	N/A		
	•	Fire Dampers	14/12				
4	Smoke Management System.						
_		Basements	30 a/c per hour	Provided  Natural ventilation	MR MR		
	•	Upper floors	12 a/c per hour	Natural ventilation provided	IVIIC		
		Extinguishers					

N-13

	Total numbers	30 nos.	Provided	MR			
	<ul> <li>Types</li> </ul>	ABC, CO <sub>2</sub> type	Provided	MR			
	<ul> <li>IS marking</li> </ul>	ISI marked	Provided	MR			
	First-Aid Hose Reels.						
	<ul> <li>Total numbers on each floor</li> </ul>	01	Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR			
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR			
	Automatic fire detection and alarming system						
	Type of detectors	Heat/Smoke	Provided	MR			
	Location of Main Panel	Required	Provided	MR			
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Alternate source of power	Required	Provided	MR			
}	Hooters' Location  MOEFA	Required	Provided	MR			
) }	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System	required					
	Basement	Required	Provided	MR			
	Upper floors	N/A	Provided in corridor only	y N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
11	Size of riser/down-comer	150 mm	150 mm	MR			
	Number of hydrants per floor	01	Provided	MR			
	Hose Box	Required	Provided	MR			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements	·					
	Ground Level						
	<ul> <li>Discharge of main Pump</li> </ul>	2850 LPM	Provided	MR			
	➤ Head of Main pump	60 m	Provided	MR			
		01	01	MR			
		180 LPM	Provided	MR			
	➤ Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	2850 LPM		MR(old case			
	Standby Pump out put		pump)				
	Standby Pump Head	60 m	Provided	MR			
	Auto Starting/ Manual stopping	Required	Provided	MR			
	Pump House Access	Required	Provided	MR			
	Terrace level						
	Discharge of pump	N/A	N/A	N/A			
	➤ Head of the pump	N/A	N/A	N/A			
	> Power Supply	N/A	N/A	N/A			
	> Auto Starting of pump		N/A	N/A			
		N/A	IN/A	IN/A			
14	-	1,00,000 ltr.	1,00,000	MR			
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	Required	Provided	MR			
	P Draw-off connection	Required					
	> Fire service inlet	Required	Provided	MR			

Off

nd

ety

lo.

ed

122

N-IM

		Overhead Tank capacity	50,000 lts	50,000 lts	N/A			
	Exit Sig		Required	Provided	MR			
	Provision of Lifts.							
	•	Pressurization of Lift Shaft	N/A	N/A	N/A			
		Pressurization of Lift lobby	N/A	N/A	N/A			
		Communication In lift Car	N/A	N/A	N/A			
		Fireman's Grounding Switch	Required	Provided	MR			
	•	Lift Signage	Required	Provided	MR			
	Standl	y power supply	Required	Provided	MR			
	Refuge Area.							
	~	Total Area	N/A	N/A	N/A			
	>	Location	N/A	N/A	N/A			
Q.	Fire Control Room							
	•	Detector System Panel	Required	Provided at ground floor	MR			
		Flow Switch Panel	Required	Provided	MR			
		B. I. O	Required	Provided	MR			
		La .	Required	Provided	MR			
			Required	Provided	MR			
0		Fire Protection Systems for tion of special Risks, if any:	Required	CO <sub>2</sub> & DCP extinguisher found provided	MR			

The fire protection systems provided in the building were test checked at random and found satisfactory at the time of inspection.

Note: All the shortcomings pointed out by this department vide letter No. F.6/DFS/MS/SZ/2022/427 dated 23.02.2022 have been compiled by the building management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the NOC issued vide letter No. F6/MS/DFS/2003/2431 dated 09.10.2003, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up for approval & signature please

Signature of the Inspecting Officer Name- Vedpal Chhikara

Divisional Officer (SW)

Signature of the Inspecting Officer Name- P.V. Rathee Divisional Asstt. Div. Officer (S.Rd)

Rather 31/5/22

Dyer (\$2)

Sirector 2/06/2002

Amo/SR)