C58



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2022/ 9 4 2

Dated: 23/05/2022

FIRE SAFETY CERTIFICATE

Certified that Hotel Mandakini Palace located at 8/29, W.E.A Abdul Aziz Road, Karol Bagh, New Delhi- 110005, comprised of basement, ground plus three upper floors. Ground floor having 02 guest rooms, first, second & third floor each having 08 guest rooms respectively (total 26 guest rooms), a pantry for staff in temporary shed on terrace, owned/occupied by Sh. Sumit Anand, was granted Fire Safety Certificate vide this department letter No. F.6/DFS/MS/GH/SZ/2019/1159 dated 31.05.2019, The guest house was re-inspected by the officer concerned of this department on 04.05.2022 in presence of Sh. Mohan Bisht (Manager) and found that the owner has removed temporary shed on terrace and have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules. 2010 and that the premises is fit for occupancy class Residential (guest house) for Ground floor 02 guest rooms, first, second & third floor each having 08 guest rooms respectively (total 26 guest rooms only), with effect from 33 05 2022 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 23/05/1021 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Following Fire Safety Directives must be achered to: -

- 1. No occupancy used above third floor and basement are separate from guest house shall be strictly adhered by Owner/Occupier.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- All comments / directions of licensing department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.ia
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form 3' (sub Rule (1) of Rule 3") along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building

: M/s. Hotel Mandakini Palace, 8/29, WEA. Karol Bagh, New

Type of Occupancy

: Residential

3. Building Composition

: Said guest house building comprised of basement, ground plus three upper floors, using basement as incidental storage, ground floor having 02 guest rooms, 1^{st} , 2^{nd} & 3^{rd} floor each having 08

e

nt

fi

'n

R

h

ire

all

f or

king ety

tion

dari

berm

pro avai

ertif copy

guest rooms respectively (total 26 guest rooms)

4. Type of Case

: Renewal

Details of previous NOC

: F.6/DFS/MS/GH/SZ/2019/1159 dated 31.05.2019

6. Fire \$afety directives letter No

: Nil

7. Date of inspection

: 04.05.2022

8. Name of the Inspecting Officers

: P.V. Rathee, ADO (SRD)

9. Name and designation of officers

from the building side

: Sh. Mohan Bisht (Manager)

9. Year of Construction 10. Applicant's letter No

: Before 2007

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety requirements as NBC/BBL	Provided at site	Remarks MR/NMR			
1	Acress to building						
	 Road width 	Accessible	07 mts	MR			
	Gate width	N/A	Directly accessible from road	N/A			
	Width of internal road	N/A	N/A	N/A			
<u> </u>	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	-	-			
	Upper Floors	01 No.	01 No.	MR being old case			
	Basements	01 No.	01 No.	MR being old case			
	b. Width of staircases			WIN being old case			
	Upper Floors	1.2 5 mts	126 Cms	MR being old case			
	Basements	1.2 5 mts	115 Cms				
	c. Protection of exits			MR being old case			
	Fire check doorPressurization	Required	Provided	MR			
		N/A	N/A	N/A			
	e. No. of continuous staircases to terrace	One	One				
	g. Width of Corridor	1.0 Mt.	155 Cms	MR			
	h. Door Size	Old case	102 cms X 206 cms	MR			
	Compartmentation.		7 ST STATE OF CHIS	MR being old case			
	 Fire check door 	Required	Provided	MR			
	Sealing of electrical shaftsFire Rating of shaft door	Required	Sealed				
		N/A	N/A	MR			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
	Smoke Management System. N/A N/A N/A						
	 Basements 	30 a/c per hour	Exhaust fans are provided	MD			
	 Upper floors 	12 a/c per hour	Exhaust fans are provided	MR			
	Fire Extinguishers MR						
	 Total numbers 	02 at each floor CO ₂ , ABC	Provided				
	• Types		Provided	MR MR			
	 IS marking 	131 marked	Provided	MR			

N-31

	First-Aid Hose Reels.		Provided	MI				
	Total numbers on each floor	One	Provided	MI				
	 Length of hose reel hose 	30 m		MF				
	Nozzle diameter	5 mm	Provided					
	Automatic fire detection and alarming system.							
	Type of detectors	Carbon Monoxide	Provided	MF				
	 Location of Main Panel 	Required	Provided near reception	MF				
	Location of Repeater Panel	N/A	N/A	N/A				
	Alternate source of power	Required	Provided	MR				
	Hooters' Location	N/A	N/A	N/A				
	MOEFA	Required	Provided	MR				
	Public Address System.	Required	Provided	MR				
)	Automatic Sprinkler System.							
	Basement	Required	Provided	MR				
	Upper Floor	N/A	N/A	N/A				
	Sprinkler above false ceiling	N/A	N/A	N/A				
	Internal Hydrants							
	Size of riser/down-comer	N/A	N/A	N/A				
	Number of hydrants per floor	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
2	Yard Hydrants.							
	Total number of hydrants	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
3	Pumping Arrangements.							
	Ground Level	-	-	-				
	Discharge of main Pump	N/A	N/A	N/A				
	Head of Main pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey Pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby Pump out put	N/A	N/A	N/A				
	Standby Pump Head	N/A	N/A	N/A				
	Auto Starting/ Manual stoppin		N/A	N/A				
	Pump House Access	N/A	N/A	N/A				
	Terrace level Discharge of	900 LPM	450 L DV 4 . 00	-				
	Discharge of pump Head of the pump	40 M	450 LPM x 02 Nos. 40 M each	MR				
	Power Supply	Required	Provided Provided	MR				
	Auto Starting of pump	Required	Provided	MR				
14			Flovided	MR				
•	Captive Water Storage for fire fighting Underground tank capacity	N/A	2711					
	 Draw-off connection 	N/A N/A	N/A	N/A				
	Fire service inlet	N/A	N/A Provided	N/A				
	 Access to tank 	N/A	Provided	N/A				
	 Overhead Tank capacity 	10000 lts	N/A	N/A				
15	Exit Signage.		10000 lts	MR				
16	Provision of Lifts.	Required	Provided	MR				

VIZ.

	Pressurization of Lift Shaft	N-22		\
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car.	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	Required	Provided	MR
7	Standby power supply	Required	Provided	MR
3	Refuge Area.	Required	Provided	MR
	Total Area	N/A	N/A	N/A
	Fire Control Room	N/A	N/A	N/A
	Detector System Panel			
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
	Special Fire Protection Systems for	N/A	N/A	N/A
0	Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked at random and found satisfactory at the time of inspection.

Note:- Three room's door on each floor are painted with fire resistant paint. (Certificate placed at C-55) and entry or exit of basement are separate from guest house building (Placed at C-56)

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F.6/DFS/MS/GH/SZ/2019/1159 dated 31.05.2019, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name P.V. Rathee Asstt. Div. Officer (SRD)

) yefo (2)

11/5 Whi of

rectuly 2000

CHA

Sent to me

Change the DFA

The refund.

(52)

10/2/201