## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/GH/SZ/2022/ 250

RY OF DELHI DELHI-110001 Dated: 30/05/2022

## FIRE SAFETY CERTIFICATE

Certified that Sehej Inn located at 51/3, New Market, W.E.A, Karol Bagh, New Delhi- 110005, comprised of basement, ground plus three upper floors. Ground floor having 03 guest rooms, first, second & third floor each having 07 guest rooms respectively (total 24 guest rooms), owned/occupied by M/s Sehej Inn, was granted Fire Safety Certificate vide this department letter No. F.6/DFS/MS/GH/2019/SZ/1580 dated 06.08.2019, The guest house was re-inspected by the officer concerned of this department on 20.05.2022 in presence of Sh. Hansraj (Lease Holder) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential (guest house) for basement (Incidental Storage), Ground floor 03 guest rooms, first, second & third floor each having 07 guest rooms respectively (total 24 guest rooms only), with effect from 50 05 102 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 30 05 2012 at New Delhi by.

(Sunil Chaudhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

## Following Fire Safety Directives must be adhered to: -

- No occupancy used above third floor and basement are separate from guest house 1. shall be strictly adhered by Owner/Occupier.
- All the means of escape shall be kept free of all type of obstruction all the time. 2.
- All the employees shall be acquainted with the use and maintenance of all fire 3. equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition 4. all the time and any lapse rendering non-functional of fire safety measures. management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric 5. installation etc. may be got verified from the concerned authorities.
- The Fire Safety Certificate may not be treated in any case for regularizations of 6. unauthorized construction / unauthorized use of land if any.
- All comments / directions of licensing department shall always be permitted and 7. followed.
- The owner /occupier shall submit a declaration every year in form 'K' provided in 8. the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to 9. the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

## INSPECTION REPORT

1. Name & address of the building

: M/s. Hotel Sehej Inn, 51/3, New Market, WEA, New Rohtak

Road, Karol Bagh, New Delhi- 110005

Type of Occupancy

: Lodging House 3. Building Composition

: Said guest house building comprised of basement, ground plus three upper floors, using basement as incidental storage, ground

floor having 03 guest rooms, 1st, 2nd & 3rd floor each having 07

guest rooms respectively (total 24 guest rooms only)

4. Type of Case

: Renewal

5. Details of previous NOC

: F.6/DFS/MS/GH/2019/SZ/1580 dated 06.08.2019

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 20.05.2021

: Sh. Hansraj, Lease Holder

8. Name of the Inspecting Officers 9. Name and designation of officers

: P.V. Rathee, Asstt. Div. Officer (SRD)

9. Year of Construction

from the building side

: 2008-09

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt. 06.08.2019	Provided at site	Remarks MR/NMR				
1	Access to building							
	Road width	Accessible	09 mtrs	MR				
	Gate width	N/A	Directly accessible	N/A				
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-	-	-				
	Upper Floors	01	01	MR				
	Basements	02	01	NMR				
	b. Width of staircases	-	-	- INIVIR				
	Upper Floors	1.25 mts	1.25 mts	MR being old case				
	Basements	1.25 & 0.75 mts	1.25 & 0.75 mts	MR being old case - N/A				
	c. Protection of exits	-	-					
	<ul> <li>Fire check door</li> </ul>	N/A	N/A					
	Pressurization	N/A	N/A	N/A				
	e. No. of continuous staircases to terrace	01	01	MR				
	g. Width of Corridor	1.25 mt.						
	h. Door Size	1.0 mt.	1.85, 1.12 mts	MR being old case				
3	Commenter and disc	1.0 mt.	0.86 mts	MR, Old case				
,	Compartmentation.							
	• Fire check door	N/A	N/A	N/A				
	<ul><li>Sealing of electrical shafts</li><li>Fire Rating of shaft door</li></ul>	N/A N/A	Sealed					
	Water Curtain	N/A N/A	N/A	N/A				
	Fire Dampers	N/A N/A	N/A N/A	N/A				
1	Smøke Management System.							
	Basements	30 a/c per hour	Exhaust fan provided	1.45				
	Upper floors	12 a/c per hour	Natural Ventilation	MR				
5	Fire Extinguishers	per nour	- Tanarai Ventriation	MR				
	Total numbers	15	Provided	ed NO				
	Types	W/CO <sub>2</sub> , CO <sub>2</sub> type ISI marked	Provided	MR				
	IS marking		Provided	MR MR				
				1411				

		11/31		/			
6	First-Aid Hose Reels.						
	Total numbers on each floor	01	Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
-07	Type of detectors	Carbon Monoxide	Provided	Mp			
	<ul> <li>Location of Main Panel</li> </ul>	Required	Provided near reception	MR MR			
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	MIN			
	Alternate source of power	Required	Provided	N/A			
	Hooters' Location	N/A	N/A	MR			
8	MOEFA	Required	Provided	N/A			
0	Public Address System.	Required		NMR			
10	Automatic Sprinkler System.	Required	Provided	MR			
	Basement	Required	D :1:				
	Upper Floor	N/A	Provided	MR			
			N/A	N/A			
11	Sprinkler above false ceiling     Internal Hydrants	N/A	N/A	N/A			
	Size of riser/down-comer	21/4					
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.	N/A	N/A	N/A			
	Total number of hydrants	21/4					
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.	N/A	N/A	N/A			
	Ground Level						
	<ul><li>Discharge of main Pump</li><li>Head of Main pump</li></ul>	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	<ul> <li>Standby Pump Head</li> </ul>	N/A	N/A	N/A			
	Auto Starting/ Manual stopping	N/A N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace level		N/A	N/A			
	<ul> <li>Discharge of pump</li> </ul>	450 LPM					
	Head of the pump	30 mts	Provided	MR			
	Power Supply	Required	Provided	MR			
	<ul> <li>Auto Starting of pump</li> </ul>	Required	Provided Provided	MR			
14	Captive Water Storage for fire fighting.	required	Provided	MR			
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	NI/A			
	Draw-off connection	N/A	N/A	N/A N/A			
	Fire service inlet	N/A	Provided	IN/A			
	Access to tank	N/A	N/A	N/A			
15	Overhead Tank capacity  Exit Signage.	5000 lts		MR, being old case			
16	Provision of Lifts.	Required	Provided	MR			
	Processing						
	Pressurization of Lift Shaft     Pressurization of Lift Shaft	N/A	N/A	N/A			
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> </ul>	N/A	N/A	N/A			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
	Bridge	Required	Provided	MR			

¥

	N/32					
	Standby power supply	Required	Provided	MR		
	Refuge Area.					
	► Total Area	N/A	N/A	N/A		
) · 	➤ Location	N/A	N/A	N//		
	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	<ul> <li>Flow Switch Panel</li> </ul>	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were checked at random and found satisfactory at the time of inspection.

Note:- Fire Check Door not required as owner/occupier has applied in CAF MHA Portal. Number of beds is less than 10 at each floor. Management of guest house has submitted an undertaking that we will use basement for storage purpose only and will not use above 3<sup>rd</sup> floor for any type of occupancy placed at C-84.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F F.6/DFS/MS/GH/2019/SZ/1580 dated 06.08.2019, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name P.V. Rathee

Asstt. Div. Officer (S.Rd)