

FORM 'H' : FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/2022/NDZ/ 198

Dated: 6/7/2022

FIRE SAFETY CERTIFICATE

Certified that the Haldiram (A unit of Haldiram Ethnic Foods Pvt. Ltd.), Shop No. C9/14, Krishna Nagar, Shahdara, Delhi-110051 building comprised of Basement, Ground, 1st Floor, 2nd Floor & 3rd Floor but restaurant is running only in Basement(Storage), Ground (Restaurant) & 1st Floor (Restaurant), owned / occupied by Haldiram Ethnic Foods Pvt. Ltd., have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officer concerned of this department on 28/06/2022 in the presence of Sh. Gurusev Singh Chawla and found that the building / premises is fit for the occupancy class "Assembly" (Group-D) / **Eating House** with effect from 6.7.22. for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 6/7/22 at New Delhi.

(ATUL GARG)
DIRECTOR.

Copy to :-

1. Joint Commissioner of Police (Lic.), PS : Defence Colony, New Delhi-110049 w.r.t.-Online MHA portal ID-2022052711404 Dated 14/06/2022.
2. Authorized Signatory. Haldiram (A unit of Haldiram Ethnic Foods Pvt. Ltd.), Shop No. C9/14, Krishna Nagar, Shahdara, Delhi-110051.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. Basements shall be used strictly as per Building-By-Laws.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: Haldiram (A unit of Haldiram Ethnic Foods Pvt. Ltd.), Shop No. C9/14, Krishna Nagar, Shahdara, Delhi-110051.
2. Building comprised of : Basement, Ground, 1st Floor, 2nd Floor & 3rd Floor but Restaurant is running on Basement (Storage), Ground & 1st Floor (Restaurant) only]
3. Type of Occupancy : **Assembly (Eating House)**
4. Type of Case : **New**
5. Details of previous NOC : **Nil**
6. Fire Safety directives Letter No. : **Nil**
7. Date of inspection : **28/06/2022**
8. Name of the Inspecting Officer : **A.K. Jaiswal, D.O. (East)**
9. Name and designation of Officer from the building side : **Sh. Gurusev Singh Chawla**
10. Year of Construction : **2011**

11. Applicant's letter No.: MHA Portal ID-2022052711404 Dated 14/06/2022

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	6 mtr	On Main Road	MR
	• Gate width	NA	On Main Road	NA
	• Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	2	2	MR
	• Basements	2	2	MR
	b. Width of staircases			
	• Upper floors	1.50 m	Provided	MR
	• Basements	1.50 m	Provided	MR
	c. Protection of exits			
	• Fire check door	Required in basement	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	1.50 mtr	Provided	MR
3.	Compartmentation			
	• Fire check door	Required in basement	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	Required	Provided	MR
	• Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	6	10	M/R
	• Types	ISI marked ABC/CO ₂	Provided	M/R
	• IS marking	Required	Provided	M/R



N/2

6.	First - Aid Hose Reels			
	• Total numbers on each floor	1	1	MR
	• Length of hose reel hose	30 Mtr.	30 Mtr.	MR
	• Nozzle diameter	5 mm	5 mm	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	N/A	Provided	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basements	N/A (Area less than 200m ²)	Provided	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	150 mm	150 mm	MR
	• Number of hydrants per floor	1	1	MR
	• Hose Box	1	1	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main pump	N/A	N/A	N/A
	➤ Head of main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Staring/Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	450 LPM	900 LPM (Electrical) 900 LPM (Diesel) 180 LPM (Jockey)	MR
	➤ Head of the pump	40 MH	40 MH	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw of connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	20,000 Ltr.	25,000 ltr	MR

ISSUING (1) of rule 35
2/3
TAL. TER. NEW DEL.

15	Exit Signage	Required	Provided	MR
16	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Ashok Kumar Jaiswal

Signature of the Inspecting Officer
Name : Ashok Kumar Jaiswal
Designation : D.O. (East Division)



DY. CFO (NDZ)

Ashok Kumar Jaiswal
4/7/22

CFO

Where is ADO concerned.

Vijay
4/7/22

DY CFO (NDZ)

Ashok Kumar Jaiswal
4/7/22

~~DO (CFO)~~

ADO was on D/off and not available

DY CFO (NDZ)

Ashok Kumar Jaiswal
4/7/22

Ashok Kumar Jaiswal
4/7/22