

C-12

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/School/2022/ 740

Dated: 6/7 /2022

FIRE SAFETY CERTIFICATE

Certified that the **Lance Fort International School** located at **Khasra No. 51/11 & 51/20, Village, Salempur Mazra, Opp. Sunil Colony, Burari, Delhi-110084** comprised of **Ground floor only** owned/ occupied by owned/ occupied by **Lance Fort International School** have complied with the fire prevention and safety requirements in accordance with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on **23.06.2022** in the presence of **Mr. Prince Tyagi (Managing Director)** and that the building/premises is fit for occupancy **Group B Educational for ground floor only** with effect from ...6/7/22... for a period of **three years**, subject to compliance of the conditions mentioned below:

Issued on ...6/7/22... at New Delhi


(Atul Garg)
Director

Ph: 011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.
2. The Principal, Lance Fort International School located at Khasra No. 51/11 & 51/20, Village, Salempur Mazra, Opp Sunil Colony, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in./wps/wcm/connect/doiit fire/FIRE/Home/Forms>.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

INSPECTION REPORT

- 1. Name & address of the building : Lance Fort International School at Kh No. 51/11 & 51/20. Village, Salempur Majra, Burari, Delhi-84
- 2. Type of Occupancy : Educational
- 3. Composition of building : Ground floor only
- 4. Type of Case : New Case
- 5. Details of previous NOC : Nil
- 6. Fire Safety directives letter No : Nil
- 7. Date of inspection : 23.06.2022
- 8. Name of the Inspecting Officers : ADO (RN)
- 9. Name and designation of officers from the building side : Mr Prince Tyagi (Managing Director)
- 10. Year of Construction : 2018
- 11. Applicant's letter No. : Online E-mail I D dated: 15.06.2022

Plot Area-9000sq. yd Covered area ----200sq. yd No of student—240aprox Total class room -17+10nos

Minimum Standards on fire prevention and fire safety U/R 33		Dir. Of Education	Provided at site	Remarks MR/NMR
1	Access to building	Circular 1.3.2011.		
	• Road width	06m	06m	MR
	• Gate width	4.5m	05m	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	NA	02	NA
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	NA	2.20m	NA
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
d. No. of continuous staircases to terrace	NA	NA	NA	
e. Width of Corridor	NA	NA	NA	
f. Door Size	1.0m	1.20m	MR	
3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	12 a/c per hour	No basement	NA
	• Upper floors	12 a/c per hour	Natural Ventilated	MR
5	Fire Extinguishers			

MR
A

	<ul style="list-style-type: none"> ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	NA	NA	NA
15	Exit Signage.	NA	NA	NA
16	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in working condition.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of education Circular dated 01.03.2011, fire safety certificate is recommended.

DO (NW)
 29/06/2022
 By SFO (W2)
 29/6/2022
 Director (NW)
 30/06/22
 ADO/RN

CAO

Signature of the Inspecting Officer
 Name:- C.L. Meena
 Designation:- ADO/RN