4225

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/Hotel/2022/SZ/ 4-9

Dated: 1.3./.0.7./2022

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Vivanta by Taj (Ambassador) situated at Subramaniam Bharti Marg, Sujan Singh Park, New Delhi–110003, comprised of Basement, Ground + 04 upper floors owned/occupied by (Ambassador Hotel, IHCL SeleQtions) was issued FSC by this department vide letter No. F6/DFS/MS/Hotel/2019/SZ/1211 dated 06/06/2019. The premise was re-inspected by officer concern of this department on 05/07/2019 in the presence of Ms. Sheetal Singh (GM) and observed that the said hotel building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Hotel Building" with effect from 3 0.2. 2022 for period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Rules 2010.

Issued on 13/0 Hat New Delhi by

Copy to: -

- M/s Hotel Vivanta by Taj (Ambassador) situated at Subramaniam Bharti Marg, Sujan Singh Park, New Delhi–110003
- 2. The Joint. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-49


Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the First schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not be treated as regularization (Clause 2.8 of UBBL- 2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- $6. \;\;$ The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1	Name & Address of the Building	ON REPORT			
	Address of the Building	Hotel Vivan	ta by Taj (Ambassado	r) situated	
		at Subramar	niam Bharti Marg, Su	jan Singh	
2	Type of O	Park, New D	elhi-110003		
3	Type of Occupancy		Hotel Building"		
4	Building Comprised of	Basement, Ground Plus Four Upper Floors			
5	Type of Case	Renewal			
6	Details of Previous NOC	F6/DFS/MS/H	lotel/2019/SZ/1211 dated (06/06/2019	
7	Fire Safety Directives Letter No	Nil			
8	Date of Inspection	05/07/2022			
9	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers	Ms. Sheetal Singh (GM)			
10	from the building side		5		
11	Year of construction	1945			
S. No.	Applicant letter No.	Outdoor diary no 2850 dated 29/06/2022			
. No.	Minimum standards on Fire Prevention and	BBL/NBC	Provided	Remarks	
1	The Salety U/R 33	Requirements		MR/NMR	
1	Access to Building.				
	 Road width 	15 mtr	Provided	MR	
	Gate width	4.5 mtr	Provided	MR	
	Width of internal road	Required	Provided	MR	
2	Number, width, type & arrangement of ex	ite	110.100		
	a) Number of Staircase	its.			
	> Upper floors.	04 Nos	GF to Terrace – 03 Nos	MR	
		041103	1 st F to Terrace -01 No	IVIIX	
	Basement floor.	02 Nos	Provided	MR	
	b) Width of Staircase	021103	Trovided	IVII	
	Upper floors	1.25 mtr	1.25m, 1.2m, 1.40m &	MR	
			1.45m	(old case	
		1.25 mtr	1.07 0.110	MR	
	Basement floor		1.07m & 1.10 m	(old case)	
	c) Protection of exits				
	Fire check door	Required	Provided	MR	
	> Pressurization	Required	Provided	MR	
	d) No. of continuous staircase to terrace	Required	03 No's Provided	MR	
-	e) Width of corridor	Required	Provided	MR	
_	f) Door size	Required	1 m Provided	MR	
3	Compartmentation.				
	 Fire check door. 	Required	Provided	MR	
	 Sealing of electrical shafts. 	Required	Provided	MR	
-	 Fire rating of shaft door. 	-NA-	-NA-	-NA-	
-	 Water curtain 	-NA-	-NA-		
	 Fire dampers. 	-NA-		-NA-	
4	Smoke Management system.		-NA-	-NA-	
8	Basement	30 ACPH	E.L.		
1	Upper floors		Exhaust fan	MR	
5	Fire Extinguishers.	12 ACPH	Exhaust fan	MR	
	Total numbers				
	• Types		130 No's	MR	
	- 1	ISI marked	ABC, CO2, M.Foam &		
	 ISI Marking 	- markey	W.CO2	MR	
T	Cinc Ald II		Provided	MR	
I	First Aid Hose Reels.			MIK	
	 Total numbers on each floor. 		04 at each floor	1	
	 Length of hose-reel hose. 	Hose-reels		MR	
	Nozzle Diameter	nose-reeis	30m	MR	
A			5mm	MR	
A	utomatic fire detection & alarming system.			MIK	
	 Type of detectors 	Required	Smol /II		
			Smoke / Heat	MR	

1 0 000	NAME OF TAXABLE PARTY.
आजादी.	The second
अग्रान	Histier

				1
	 Location of Main Panel 	Required	Control room	MR
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	 Alternate source of power 	Required	Provided	MR
	 Hooter's location 	Required	Provided in all area	MR
8	MOEFA			
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System	Required	Provided	MR
	Basement	Required	Provided	MR
	 Upper floors 	Required	Guest area & restt.	MR
	Sprinkler above false ceiling			
11	Internal Hydrants.	Required	Provided	MR
	Size of Riser/Down-comer			
		100 mm	Provided	MR
	Number of Hydrant per floor	04 No's	Provided	MR
	Hose box.	04 No's	Provided	MR
12	Yard Hydrants.			
	 Total number of hydrants. 	07 Required	Provided	MR
	Hose box.	07 Required	Provided	MR
13	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	1620 LPM	Provided	MR
	Head of main pump.	45m	Provided	MR
	Number of main pumps.	02	Provided	MR
	Jockey Pump output.	180 LPM	Provided	MR
	Jockey Pump head.	45m	Provided	MR
	Standby Pump output.	-NA-	-NA-	-NA-
	 Standby Pump head. Auto Starting/Manual Stopping 	-NA-	-NA-	-NA-
	 Auto Starting/Manual Stopping Pump house access 	Required	Provided	MR
	Terrace Level	Required	Provided	MR
	Discharge of pump.	-NA-	374	
	Head of pump.	-NA-	-NA- -NA-	-NA-
	Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14	Captive water storage for fire fighting.		-NA-	-NA-
	Underground tank capacity.	1,00,000 ltrs	Provided	MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	 Overhead tank capacity. 	10,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			1411
	 Pressurization of lift shaft. 	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	 Lift signage. 	Required	Provided	MR
17	Standby Power Supply	Required	Provided	
18	Refuge Area	- required	TTOVIGEG	MR
	Total area	-NA-	-NA-	1
	• Location			-NA-
		-NA-	-NA-	-NA-



19	Fire Control Room.			
	Detector system panelFlow switch panel	Required	Provided	MR
		-NA-	-NA-	-NA-
	• PA system panel.	Required	Provided	MR
	Battery backup. Building floor plan. Special Fire Protection System for the Protection of special Risk, if any.	Required	Provided	MR
20		Required	Provided	MR
		-NA-	-NA-	-NA-

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/Hotel/2019/SZ/1211 dated 06/06/2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

Dy. CFO (SZ)

Dérecter M

More ML

Have synature PI

fettel in

Me

Director 7/1/92

fm