GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001</u>

~

No F 6/DFS/MS/2022/School/WZ/ 7 82

Dated: 2 6 / 7 /2022

(-16

New Kumar Sile

FIRE SAFETY CERTIFICATE

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

MC

art

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi 54.
- 2. The Principal, Ryan Shalom Montessori, Block-A-3, Sector-16, Rohini, Delhi-85. Conditions for the validity of Fire Safety Certificate:
- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

NIY

- F 1	Name & address of the house NSPECT	ION REPORT						
2	Type of Occupancy	om Montessori Di						
	Type of Case Educational Educational							
4	Details of Previous NOC Fire Seferts View in the set of the set o							
5	Fire Safety direct	MS/2019/WZ/1052 of	r floor)					
6	Fire Safety directives letter No : Director o Date of inspection : 08 07 2022	f Education Circular	dated 17.05.2019					
7	Name of Inspecting Official in 08.07.2022	2	Dated 01.03.2011.					
8		- ma ADO(Rohini)						
0	Name and designation of officers	(Konini)						
9	From the building side : Mrs. Savit Year of Construction : 2008 & 20	a Chawla (Section Ir						
1	U. Applicant's latte λ_1	09						
5. No	-FF-real Siciler No							
	and fire safety U/P 22	Director of		1				
	and fire safety U/R 33	Education	Provided at site	Remarks				
		Circular Dated		MR/NMR				
1.	Access to huild	01.03.2011.						
	Access to building							
	Road width	Accessible	A					
	• Gate width	NA	Accessible	MR				
•	Width of internal road		2.54m	NA				
2.	Number, Width, Type & Arrangement of a. Number of staircases	Exite	NA	NA				
	a. Number of staircases							
	 Upper Floors 	01						
	• Basements	01	01	MR				
	b. Width of staircases	NA	NA	NA				
	Upper Floor							
	Basements	1.5m	1.5m	MR				
		NA	NA					
	c. Protection of exits			NA				
	Fire check door	NA						
	 Pressurization 	NA	NA	NA				
	d. No. of continuous staircases to terrace	NA	NA	NA				
	e. Width of Corridor	NA	01	NA				
	f. Door Size	1.0m	NA	NA				
3.	Compartmentation	1.0m	1.02m	MR				
	Fire check door							
		NA	NA	NA				
	 Sealing of electrical shafts Fire Bating of shaft down 	NA	NA					
	 Fire Rating of shaft door Water Curtain 	NA	NA	NA				
		NA		NA				
	Fire Dampers	NA	NA	NA				
4.	Smoke Management System NA NA NA							
	• Basements 20 c/c = -1							
	Upper floors		NA	NA				
		12 a/c per hour	Natural ventilated	MR				
5.	Fire Extinguishers							
	Total numbers	02nos.	10nos.	MD				
	• Types	ABC/CO2	ABC-10	MR				
	IS marking	ISI marked	Yes	MR				
5.	First-Aid Hose Reels		105	MR				
	 Total numbers on each floor 	NA	Provided	N V .				
	 Length of hose reel hose 	NA	Provided	NA				
	 Nozzle diameter 	NA	Provided	NA				
	Automatic fire detection and alarming syst	em	riovided	NA				
	Type of detectors NA NA							
	 Location of Main Panel 	NA	NA	NA				
	 Location of Repeater Panel 	NA		NA				
		14/1	NA	NA				

T]:



	N	115		
				-
	Alternate source of power	NA	NA	N
	 Hooters' Location 	NA	NA	NA
8.	MOEFA	NA	NA	NA
9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System		NA	NA
	 Basement 	NA	NA	NA
	 Ground & Upper Floors 	NA	NA	NA
	 Sprinkler above false ceiling 	NA		1471
11.	Internal Hydrants	NA	NA	NA
	Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
12	Hose Box			1
12.	Yard Hydrants	NA	NA	NA
	Total number of hydrantsHose Box	NA	NA	NA
13.	Hose Box Pumping Arrangements		L	1
13.	Ground Level	NA	NA	NA
	 Discharge of main Pump 	NA	NA	NA
	 > Head of Main pump 	NA	NA	NA
	 Number of main pumps 	NA	NA	NA
	 Jockey Pump out put 	NA	NA	NA
	 Jockey pump head 	NA	NA	NA
	 Standby Pump out put 	NA	NA	NA
	 Standby Pump Head 	NA	NA	NA
	 Auto Starting/Manual Stopping 	NA	NA	NA
	 Pump House Access 	NA	NA	NA
	Terrace level	NA NA	NA	NA
	 Terrace level Discharge of pump 	NA	450lpm	NA
	 Discharge of pump Head of the pump 	NA NA	4301pm 40m	NA
	 Power Supply 	NA	NA	NA
	 Auto Starting of pump 	NA	NA	NA
4.	Captive Water Storage for fire fighting	1 1		
	Underground tank capacity	NA	NA	NA
	 Draw-off connection 	NA	NA	NA
	 Fire service inlet 	NA	NA	NA
	Access to tank	NA	NA	NA
	 Overhead Tank capacity 	NA	4000ltr	NA
5.	Exit Signage.	Required	Provided	MR
<i>6.</i>	Provision of Lifts.	• • • • • •		1
		NA	NA	NA
	Pressurization of Lift Shaft Pressurization of Lift Johny	NA	NA	NA NA
	 Pressurization of Lift lobby Communication In lift Car 	NA	NA	NA
	 Communication in fift Car Fireman's Grounding Switch 	NA	NA	NA
	 Lift Signage 			
		NA	NA	NA
	Standby power supply	NA	NA	NA
. 1	Refuge Area.			
	Total Area	NA	NA	NA
	Location	NA	NA	NA
F	Fire Control Room			
	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
1	 Building Floor Plans 	NA	NA	NA

N/16

Special Fire Protection System for	NA	NA	NA
Protection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures required stipulated in **Director of Education Circular**, the FSC issued vide letter no. F.6/DFS/MS/2019/WZ/1052 dated 17.05.2019 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

DO (NW)

ð

Rohiti

14/07/222

FT letter is put up for kind perusal and signature please.

eFo(W?)