

Copy to:-

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/SZ/2022/ 865

0001 आज़ादी न अमृत महोत्सव Dated: 0.5/8/2022

FIRE SAFETY CERTIFICATE

Certified that the Vidya Memorial School located at Molarband Extension, Badarpur Delhi-44, was granted NOC by this department vide letter no.-Border, New F.6/DFS/MS/2006/3105 dated 17.10.2006 for Ground floor only. The school building was reinspected by Assistant Divisional Officer (M. Road) from this department on 26.07.2022 in the presence of Sh. R. K. Sharma (Owner) and found that the school building is comprised of ground + 2 upper floors. The school has deemed complied with the fire prevention and fire safety requirements in accordance with the Circular no. F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building (Ground + 2 upper floor) is fit for occupancy of Group B "Educational Building" with effect from 0.5/8./2022 renewed for a period of three years, subject to conditions printed below.

Director **Delhi Fire Service**

- 1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
- 2. The Principal, Vidya Memorial School located at Molarband Extension, Badarpur Border, New Delhi-44.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas. occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J. [sub Rule (1) of Rule 37] along with a copy of this certificate, six months prior to its expiry.

				SPECTION REPORT	ſ		
1	N	ame	e & address of the building		School located at 1r Border, New Delhi-44	Molarband t.	
2	B	uild	ing is comprised of	Ground + 2 upper flo			
3	T	ype	of occupancy	Education, Group-B			
4	T	ype	of case	the second design of the secon	(addition of 02 upper	floors in a	
5	D	etai	ls of previous NOC		105 dated 17.10.2006	for Ground	
	-		C. P. J. Lu	floor only	2 (2011/2208 to 2208	datad	
6	FI	re s	afety direction letter no.	P6/Estate/CC/Fire Sa 01.05.2022	afety/2011/3298 to 3398	Jaleu	
7	D	ate	of inspection	26.07.2022			
8			e of the inspecting officers	Rajesh Kumar Shukl			
9			e of the designation or er from the building side	f Sh. R. K. Sharma (O	wner)		
10	_		of construction	2006 & 2008			
11	-		icant's letter no.	Outdoor Diary no. 28	862 dated 29.06.2022		
S.No			mum standard of fire			Remarks	
	p	reve	ention and fire safety U/R	•		MR/NMF	
	-	33		dated 01.03.2011			
1	Α	cce	ss to Building:				
	A		Road width	Accessibility	Provided	MR	
				(previous inspection			
				conducted as per			
				circular dated			
				17.01.2005)			
	B	-	Gate width	NA	NA	NA	
	C		Width of internal road	NA	NA	NA	
2	-		ber, Width, Type and Arr	angement of Exits:			
	A	-	Number of staircases	02	02 nos.	MR	
		a		02 nos.			
		b	Basement	NA	NA	NA	
	B	+	Vidth of staircases	1	1.20 mtrs & 0.80 – 0.95	140	
		а	Upper floor	1 staircase of 1.5 mtrs or if main staircase width is < 1.5 mtrs an additional staircase of 0.75 mtrrs width is required.	n.20 mtrs & 0.80 – 0.95 mtrs.	MR	
		b	Basement	NA	NA	NA	
	C	P	rotection of exits				
		a	Fire check door	NA	NA	NA	
	_	b	Pressurization	NA	NA	NA	
	D		aircases to terrace	01 no.	01 no.	MR	
-	E		idth of corridor	NA	NA	NA	
	F		oor size	1.0 mtrs.	1.0 mtrs. (class room)	MR	
			rtmentation:				
	A		e check door	NA	NA	NA	
	B		aling of electrical shafts	NA	NA	NA	
-	C		e rating of shaft door	NA	NA	NA	
-	D E		ater curtain e dampers	NA	NA	NA	
			Management System:	NA	NA	NA	
	D			NIA			
-	3		per floor	NA	NA	NA	
	_	SP		NA	NA	NA	

0/2

ŧ

1 idya Memorial School located at Molarband Extension. Badarpur Border, New Delhi-44.

2/3

5.	Fi	re Extinguisher:					
	A	Total numbers	09 nos.	09 nos.	MR		
	B	Types	CO ₂ & ABC	Provided	MR		
	C	1SI marking	Required	Provided	MR		
6	Fi	rst-Aid-Hose Reel:	Tiovided	IVIN			
	A	Total numbers of each floor	01 no.	01 no.	MR		
	B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR		
	C	Nozzle diameter	5 mm	5 mm	MR		
7	Αı	itomatic Fire Detection and A	larming System:				
	А	Type of detectors	NA	NA	NA		
	B	Location of main panel	NA	NA	NA		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate source of power	NA	NA	NA		
	E	Hooters	NA	NA	NA		
8	M	OEFA:	NA	NA	NA		
9	Pu	blic Address System:	NA	NA	NA		
10	Au	itomatic Sprinkler System:			INA		
	A	Basement	NA	NA	NA		
	B	Upper floor	NA	NA	NA		
	С	Sprinkler above false ceiling	NA	NA			
11	Internal Hydrants:						
	A	Size of riser/down-comer	NA	NA	NA		
	B	Number of hydrants per floor	NA	NA	NA		
	С	Hose box	NA	NA	NA		
12	Ya	rd Hydrants:		1471	INA		
	A	Total number of hydrants	NA	NA	NA		
	B	Hose box	NA	NA	NA		
13	Pu	mping Arrangements:					
Α		Fround level					
	a	Discharge of main pump	NA	NA	NA		
	b	Head of main pump	NA	NA	NA		
	c	Number of main pumps	NA	NA	NA		
	d	Jockey pump out put	NA	NA	NA		
	e	Jockey pump head	NA	NA	NA		
	f	Standby pump out put	NA	NA	NA		
	g	Standby pump head	NA	NA	NA		
	h	Auto starting /manual	NA	NA	NA		
	.+	stopping	NIA				
B	i Ter	Pump house access race Level	NA	NA	NA		
5	a	Discharge of pump	450 L DM4	4501 214			
	b	Head of the pump	450 LPM 40 mtrs.	450 LPM	MR		
ľ	c	Power supply	Required	40 mtrs. Provided	MR		
ŀ	d	Auto starting of pump	Required	Provided	MR		
				Frovided	MR		

2/4

Vidya Memorial School located at Molarband Extension, Badarpur Border, New Delhi 44

A Underground tank capacity	NA	NA	NA			
	NA	NA	NA			
B Draw-off connection	NA	NA	NA			
C Fire service inlet	NA	NA	NA			
D Access to tank	10,000 ltrs	10,000 ltrs	MR			
E Overhead tank capacity	Required	Provided	MR			
Exit Signage:	Required					
Provision of Lifts:		NA	NA			
A Pressurization of lift shaft	NA	NA	NA			
B Pressurization of lift lobby	NA	NA	NΛ			
C Communication in lift car	NA	NA	NA			
D Firemen's grounding switch	NA	NA	NA			
E Lift signage	NA	NA	NA			
Standby Power Supply:	NA	INA				
a server to the server of the	NA	NA	NA			
A Total area B Location	NA	NA	1111			
			NA			
the second second	NA	NA	NA			
	NA	NA	NA			
	NA	NA	NA			
C PA system panel	NA	NA	NA			
 D Battery backup E Building floor plans 	NA	NA	NA			
E Building floor plans Special Fire Protection systems for	NA	NA				

<u>Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA),</u> Provided but Not Functional (PNF), Not Provided (NP).

<u>Note</u> :-In the previous inspection report the building comprised of Ground floor only while during inspection dated 26.07.2022 the building comprised of G+2 upper floors. Thus this is a case of addition / alteration. However education buildings below the height of 9.0 mtrs or below G+3 upper floors are not covered under Rule 27 of DFS Rules 2010. Hence fire safety provisions of Directorate of Education Circular no. F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 are applicable.

The fire safety provisions provided in the building were randomly tested, checked and found functional at the time of inspection.

If agreed to the note above & in view of the substantial compliance of the fire safety provisions as stated in the aforesaid circular, issuance of fire safety certificate to the building is recommended.

Accordingly, FSC is put up for approval and signatures please.

97 is a case of addition/Alpteration.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M. Road)

Dy.CFO Director Anymed