

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/WZ/2022/ 21 >

Dated: 01 08 2022

FIRE SAFETY CERTIFICATE

Restaurants Pvt. Ltd.) running at shop No. SH/GF/01A, Ground Floor, Pacific Mall building comprised of two tier basement, lower ground, ground plus four upper floors and ground plus seven upper floors (MLCP), located at Netaji Subhash Place Metro Station, DMRC Phase-III Corridor, New Delhi, owned/occupied by M/s. Connaught Plaza Restaurants Pvt. Ltd. The premises was inspected by the officer concerned of this department on 22.07.2022 in the presence of Sh. Anurag Srivastava (Manager- Licensing) & Sh. Shazeb Tariq (Manager-Licensing) and observed that the management have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- "Assembly" Group-D (Restaurant at Ground Floor only) with effect from Older Delhi Fire Service Rules and Sh. Shazeb Tariq (Manager-Licensing) and observed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 01/8/2022 at New Delhi by.

Atul Gar Directo

Copy to:-

- 1. The Owner / Occupier, M/s. McDonalds Family Restaurant (a unit of M/s. Connaught Plaza Restaurants Pvt. Ltd.), Shop No. SH/GF/01A, Ground Floor, Pacific Mall, Netaji Subhash Place, New Delhi.
- 2. The Dy. Health Officer, MCD, Keshav Puram Zone, New Delhi.
- 3. The Joint Commissioner of Police (Lic.), Police Station Defence Colony, First floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (https://www.delehlhlic.gov.in) along with a copy of this certificate, six months prior to its expiry.
- 8. This FSC is valid for the Restaurant at Ground Floor only.

INSPECTION REPORT

1. Name & address of the building : M/s. McDonalds Family Restaurant (A unit of Connaught

Plaza Restaurants Pvt. Ltd.) SH/GF/01A, GF, Pacific Mall, NSP, New Delhi.

2. Type of Occupancy

: Assembly (Restaurant)

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No : N/A.

6. Date of inspection

: 22.07.2022

7. Name of the Inspecting Officers: M.K. Chattopadhyay, D.O. (West Division) 8. Name and designation of officers

from the building side

: Sh. Anurag Srivastava (Manager-Lic.), Sh. Shazeb Tariq (Manager-Lic.)

9. Year of Construction

: 2021

10. Applicant's letter No.

: ID- 2022070614129

The said restaurant is running at Ground Floor of Pacific Mall comprised of 02 tier basements, lower ground, ground plus 04 upper floors and ground plus 07 upper floors (MLCP). The Pacific Mall is already granted FSC vide this office letter No. F.6/DFS/MS/Mercantile/2021/WZ/368 dated 02.08.2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as UBBL / NBC-IV	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	12 mts	Provided	MR			
	Gate width	06 mts	Provided	MR			
	Width of internal road	06 mts	Provided	MR			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	-	-			
	Upper Floors	N/A	N/A	Restaurant running at GF only			
	Basements	N/A	N/A	Restaurant running at GF only			
	b. Width of staircases	-	-	-			
	Upper Floors	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Basements	-	-	,			
	c. Protection of exits	N/A	Provided by Mall				
	Fire check door	N/A	Provided by Mall				
	 Pressurization 	N/A	Provided by Mall				
	e. No. of continuous staircases to terrace	2.0 mts.	Provided by Mall				
	g. Width of Corridor h. Door Size	1.5 mts. each	2.0, 1.5 mts	MR			
3	Compartmentation.						
3	Fire check door	N/A	Provided by Mall				
	 Sealing of electrical shafts 	N/A	Provided by Mall				
	Fire Rating of shaft door	N/A	Provided by Mall				
	Water Curtain	N/A	Provided by Mall				
	• Fire Dampers	N/A	Provided by Mall				
4	Smoke Management System.						
	Basements	30 a/c per hour 12 a/c per hour	N/A	Restaurant running at GF only			
	ground floor	12 a/c per nour	Provided	MR			

,			1412	12				
5	Fire Extinguishers	,		1				
	 Total numbers 	06	Provided	MR				
	• Types	CO ₂ , ABC type	Provided	MR				
	IS marking	ISI marked	Provided	MR				
6	First-Aid Hose Reels.							
	Total numbers on each floor	01	Provided by Mall near	MR				
	 Length of hose reel hose 	30 m	restaurant Provided					
	Nozzle diameter	5 mm		MR				
			Provided	MR				
7	Automatic fire detection and alarming							
	• Type of detectors	Smoke & Heat	Provided & connecte with Mall	d MR				
	 Location of Main Panel 	Required	Provided	MR				
	 Location of Repeater Panel 	Required	Provided by Mall	MR				
	 Alternate source of power 	Required	Provided by Mall	MR				
	 Hooters' Location 	Required	Provided in restauran & Mall	MR				
8	MOEFA	Required	Provided by Mall	MR				
9	Public Address System.	Required	Provided by Mall	MR				
10	Automatic Sprinkler System.							
	Basement Faction Base	N/A	Provided by Mall					
	Entire RestaurantSprinkler above false ceiling	Required	Provided by Mall	MR				
	Sprinkler above raise certing	Required	Provided by Mall	MR				
11	Internal Hydrants							
	Size of riser/down-comerNumber of hydrants per floor	150 mm	Provided near restaurant & Mall	MR				
	Hose Box	01	Provided	MR				
	• Hose Box	01	Provided	MR				
12	Yard Hydrants.							
	Total number of hydrants	N/A	Provided by Mall					
	Hose Box	N/A	Provided by Mall					
13	Pumping Arrangements.		•					
	 Ground Level 							
	Discharge of main Pump	2280 LPM	Provided by Mall	MR				
	Head of Main pump	88 m	Provided by Mall	MR				
	Number of main pumps	02	Provided by Mall	MR				
	 Jockey Pump out put 	02 x 180 LPM	Provided by Mall	MR				
	Jockey pump head	88 m	Provided by Mall	MR				
	Standby Pump out put	2280 LPM	Provided by Mall	MR				
	Standby Pump Head	88 m	Provided by Mall	MR				
	Auto Starting/ Manual stopping Pump House Access	Required	Provided by Mall	MR				
	amp House Access	Required	Provided by Mall	MR				
	• Terrace level							
	Discharge of pump	900 LPM	Provided by Mall	MR				
	Head of the pump	40 m	Provided by Mall	MR				
	Power Supply Auto Starting of pump	Required	Provided by Mall	MR				
	Tato Starting of pump	Required	Provided by Mall	MR				

1	Captive Water Storage for fire fightin	g.		140
	 Underground tank capacity 	2,00,000 lts	Provided by Mall	MR
	➤ Draw-off connection	Required	Provided by Mall	MR
	Fire service inlet	Required	Provided by Mall	MR
	> Access to tank	Required	Provided by Mall	MR
	Overhead Tank capacity	20,000 Its	Provided by Mall	MR
		Required	Provided	MR
	Exit Signage.			
1	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby	Required	Provided by Mall	MR
		Required	Provided by Mall	MR
		Required	Provided by Mall	MR
	Communication In lift Car Communication Switch		Provided by Mall	MR
	Fireman's Grounding Switch 1.10 Signage	Required	Provided by Mall	MR
	Lift Signage	Required	Provided	MR
	Standby power supply	Required		
3	Refuge Area.	27/4	N/A	N/A
	 Total Area 	N/A	N/A	N/A
	> Location	N/A	1,712	
9	Fire Control Room		Provided by Mall	MR
	 Detector System Panel 	Required	Provided by Mall	MR
	Flow Switch Panel	Required	Provided by Mall	MR
	PA System Panel	Required		MR
	Batter backup	Required	Provided by Mall	MR
	Building Floor Plans	Required	Provided by Mall	IVIIX
0.0	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Provided	MR

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

DFA is put up for approval & signature please.

Divisional Officer (West)

DalWest