

o. F6/DFS/MS/GH/NDZ/2022/ 399

FIRE SAFETY CERTIFICATE

Certified that the M/s Vakil Guest House located at 735-739, Motor Market, Jama Masjid, Delhi- 06, comprised of Ground + 04 upper floors: ground floor- (commercial use), 1st floor - (06 guest rooms + reception + 01 office + 01 waiting room), 2nd floor- (06 guest rooms + 01 store room + 01 staff room), 3rd floor- (06 guest rooms + 01 store + 01 staff room) and 4th floor - (02 rooms), total 19 guest rooms was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2019/2087 dated 31.10.2019. Now, the premise was re-inspected by the officer concerned of this department on 10.08.2022 in presence of Mr. Sarzil (Owner's Son) and found that the building is comprised of ground + 04 upper floors and now the floor wise occupancy is ground floor - (commercial use), 1st floor - (06 guest rooms + reception + office + 01 staff room), 2nd floor - (07 guest rooms + 01 staff room), 3rd floor - (06 guest rooms + 01 staff room + 01 store), & 4th floornot in use as per affidavit dated 19.07.2022. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy class of "Residential (Sub Division-A-1), 1st floor (06 guest rooms), 2nd floor (07 guest rooms) & 3rd floor (06 guest rooms) for total 19 guest rooms up Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued onat New Delhi by.

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2022080215666 dated 02.08.2022.
- 3. The Licensee, M/S Vakil Guest House at 735-739, Motor Market, Jama Masjid, Delhi- 06.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the
- The occupancy of 4th floor not allowed as per clause 7.31 in UBBL-2016.

hilect

1	Nan	ic & address of the building	ECTION REPOR	RT			
•		address of the building	M/s Vakil Guest House leasts I . To				
2	Buil	ding is comprised of	Market, Jama	M/s Vakil Guest House located at 735-739, Mot Market, Jama Masjid, Delhi-06.			
		ame is comprised of	Ground + 04	Ground + 04 upper floors			
			Ground floor - Commercial (mercantile) 1st floor - (06 guest rooms + reception + 01 office 01 staff room)				
			01 staff room)	guest rooms + recep	otion + 01 office		
			- Carri (OOIII)				
			3rd flaar (07)	2 nd floor - (07 guest rooms + 01 staff room)			
			room) 4th floor - not in use as per affidavit date				
3	Тур	e of occupancy	17.07.2022.				
4	Typ	e of case	Residential Gro	up A-1			
5			Renewal				
6	Eira	ails of previous FSC	F6/DFS/MS/GF	I/NDZ/2019/2087 c	lated 31 10 2010		
7	Dire	safety direction letter no.	Nil	2017/2007	ated 51.10.2019		
	Dat	e of inspection	10.08.2022	10.08.2022			
8	Nar	ne of the inspecting officers	Sh Sumit Kum	ar ADO (SDM)			
9	Nar	ne of the designation of officer	Mr. Sarzil (Ow	nor's son			
	troi	n the building side	war Sarzii (Ow	ner s son)			
10	Yea	r of construction	1970				
11		olicant's letter no.					
			02.08.2022	Online application no. 2022080215666 date			
S.No	Mi	nimum Standards on fire		n	T		
	Prevention and fire safety		Requirement/ Existing fire	Provided at Site	Remarks MR		
	req	uirements U/R 33	safety		NMR		
_			arrangements				
1		cess To Building:					
	Ro	ad width	Accessibility	15 mtrs.	MR		
	Gate width		NA	On road	NA		
_		dth of internal road	NA	NΛ	NA		
2		mber, Width, Type and Arrai	ngement of Exits:				
	Λ	Number of staircases					
		a Upper floor	01 nos.	01 nos.	MR		
	-	b Basement	NA	NA	NA		
	В	Width of staircases					
		a Upper floor	0.80 mtrs.	1.0 mtrs.	MR		
	C	b Basement Protection of exits	NA	NA	NA		
		a Fire check door	NA	NA	NIA		
		b Pressurization	NA	NA NA	NA NA		
	D	No. of continuous staircases	01 nos.	01 nos.	MR		
		to terrace	0.11001	or nos.	WIK		
	E	Width of corridor	NA	NA	NA		
	F	Door size	1.0 mtrs.	1.0 mtrs.	MR		
3	Co	mpartmentation:					
	Λ	Fire check door	NA	NA	NA		
	В	Sealing of electrical shafts	NA	NΛ	NA		
	C	Fire rating of shaft door	NΛ	NA	NA		
	D	Water curtain	NΛ	NA	NA		
	E	Fire dampers	NA	NA	NA		
		oke Management System:		1			
4			20 4 60011	NΛ	NIA		
4	Λ	Basements	⊥ 30 ACPH	11874	INA		
4	AB	Basements Upper floors	30 ACPH 12 ACPH	Natural	NA MR		

1

V

1	Λ	inguisher: 	1.00	()				
	В		09 nos	09 пов	MR			
		Types	CO, & ABC	CO. & ABC	MR			
	C	1SI marking	151 marked	151 marked	MR			
	First-Aid-Hose Reels:							
	^	Lotal numbers of each floor	01 nos	Ol nos	MR			
	В	Length of hose reel hose	30 mtrs	30 mtrs	MK			
	C	Nozzle diameter	5 mm	5 mm	MIK			
	Automatic Fire Detection And Alarming System:							
	A	Type of detectors (C() type)	Required	Provided	MR			
	В	Location of main panel	Required	Provided at 1"	MR			
	C	Location of repeater panel	NA	NA	NA			
	D	Alternate source of power	Required	Provided	MR			
	E	Hooters	Required	Provided	MIK			
	MOEF		NA	NA	NA			
0		Address System:	Required	Provided	MR			
U		atic Sprinkler System:						
	Λ	Basement	NA	NA	NA			
	В	Upper floor	NA	NA	NA			
	C	Sprinkler above false	NA	NA	NA			
1	Intern	ceiling al Hydrants:	1					
-	A	size of riser/down-comer	LNIA	Lauri				
	В	Number of hydrants per	NA NA	NA	NA			
		floor		NA	NA			
_	C	Hose box	NA	NA	NA			
2		Yard Hydrants:						
	Λ	Total number of hydrants	NA	NA	NA			
	В	Hose box	NA	NA	NA			
3	Pumpi	ng Arrangements:						
	A	Ground level						
	a)	Discharge of main pump	NA	NA	NA			
	b)	Head of main pump	NA	NA	NA			
	c)	Number of main pumps	NA	NA	NA			
	d)	Jockey pump out put	NA	NA	NA			
	e)	Jockey pump head	NA	NΛ	NA			
	f)	Standby pump out put	NA	NA	NA			
	g) h)	Standby pump head	NA	NΛ	NA			
	i)	Auto starting /manual stopping Pump house access	NA NA	NA	NA			
	B	Terrace level	NA	NA	NA			
	a)	Discharge of pump	225 LPM	225 1 124				
	b)	Head of the pump	30 mtrs.	225 LPM 30 mtrs	MR			
				4	MR			
	c)	Power supply	Required	Provided	MR			

	Captive Water Storage For Fire Fighting: NA NA				NA
4		Underground tank capacity		NA	NA
	-	Draw-off connection	NA	NA	NA
		Fire service inlet	NA	Provided	MR
	$C \mid$	Fire service inter	Required	3,000 ltrs.	MR
1	D	Access to tank	2,500 ltrs.	Provided	MR
	E	Overhead tank capacity	Required	Provided	
5	Exi	(Signage:			NA
6	Pro	vision of Lifts:	NA	NA	NA
-	A	Pressurization of lift shaft	NA	NA	NA
	В	Pressurization of lift lobby	NA	NA	NA
-	C	Communication in lift car	NA NA	NA	NA NA
-	D	Firemen's grounding switch	NA NA	NA	MR
-	E	Lift signage	Required	Provided	IVIIC
. 7	Sto	indby Power Supply:	Required		
17		fuge Area:		NA	NA
18			NA	NA	NA
	A	Total area	NA	1474	
	В	Location		NIA	NA
19	Fi	re Control Room :	NA	NA	NA
	A	Detector system panel	NA	NA	NA
	В	Flow switch panel	NA	NA	NA
	C	Pa system panel	NA	NA	NA
	D	Battery backup	NA	NA	NA
	E	Building floor plans	For Protection of	NA	
20	L Fire Protection Systems 101				

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2022/406 dated 30/05/2022 has been rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/2087 dated 31.10.2019 is recommended to be renewed up to 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Sumit Kumar Name ADO (SPM) Designation

12/8/22

MR MRIR

F.T. letter is lut up for Signature, Please
Sylongs
21108/20