## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

NEW DELHI-110001

F.6/DFS/MS/EH/2022/SZ/ 290

Dated 18 /10 /2022

## FIRE SAFETY CERTIFICATE

Issued on \_\_\_\_\_/\_\_\_\_/2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

No.

- 1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal 2022090216994 dated 03/09/2022)
- 2. M/s Amaltas Indian Tapas located at M-25, First Floor, Greater Kailash-2, New Delhi 110048.

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	INSPECTIO	ON REPO	RT	1111	i stetti er				
ı	Name & Address of the Building	M/s Amaltas Indian Tapas (Unit of Arigo Ventures Pvt Ltd) located at M-25, Greater Kailash-2, New Delhi 110048							
2	Type of Occupancy	Group-D Assembly Building (Eating House)							
3	Building Comprised of	Basement Ground plus Three upper floors							
4	Type of Case	Renewal / Name Change							
.5	Details of Previous NOC	F 6/DFS/MS/EH/2017/SZ/1583 dated 07/11/2017 for G+2 upper floors only							
6	Fire Safety Directives Letter No	Nil							
7	Date of Inspection	27/09/2022							
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)							
9	Name & Designation of Officers from the building side	Mr Udit Maheshwar							
10	Year of construction	1999 Restt. Running at First floor only							
1.1	Applicant letter No	MHA Portal 2022090216994 dated 03/09/20							
	Minimum standards on Fire Prevention	Old N	IOC	Provided at Site	Remarks				
5. No.		requirements			MR/NMR				
	and Fire Safety U/R 33	require							
1	Access to Building.	6 n	n	Provided	MR				
	Road width	N/A		N/A	N/A				
	Gate width	N/A		N/A	N/A				
	Width of internal road			IVA					
2	Number, width, type & arrangement of exits.								
	a) Number of Staircase								
	→ Upper floors.	02 N	os	02 Nos	MR				
	Basement floor.	N/A		Other property	N/A				
	b) Width of Staircase								
	➤ Upper floors	N/A N/A N/A Required N/A		1.30m & 0.93 m	MR (old case)				
	> Basement floor			N/A	N/A				
	c) Protection of exits			N/A	N/A				
	➤ Fire check door			N/A	N/A				
	> Pressurization			Provided	MR				
	d) No. of continuous staircase to terrace			N/A	N/A				
	c) Width of corridor Door size	Required		1.10m & 0.86 m	MR (old case)				
,	Compartmentation.								
3		N/A	`	N/A	N/A				
	Fire check door	N/A		N/A	N/A				
	<ul> <li>Sealing of electrical shafts.</li> </ul>	N/A		N/A	N/A				
	<ul> <li>Fire rating of shaft door.</li> </ul>	N/A N/A		N/A	N/A				
	Water curtain			N/A	N/A				
	Fire dampers			14/21					
4	Smoke Management system.			N/A	N/A				
	Basement	NA 12 ACPH E			MR				
	Upper floors			Exhaust Fans Provided	1,111				
-	Fire Extinguishers.								
5		08 N	os	08 Nos	MR				
		ABC/CO <sub>2</sub>		1	MR				
	Total numbers	ABC/0	$CO_2$	ABC-04 & CO <sub>2</sub> -04					
	<ul><li>Total numbers</li><li>Types</li></ul>			Provided	MR				
		ABC/O							
		ABC/0	$CO_2$						

	// _			The state of the s
111	1.31	4	-	
	312	i di	Fire	Test.

	Total numbers on each floor.	One	Provided	MR
	<ul> <li>Length of hose-reel hose.</li> </ul>	30m	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming syste	m.		
	<ul> <li>Type of detectors</li> </ul>	N/A	N/A	N/A
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	N/A
9	Public Address System	N/A		MR
10	Automatic Sprinkler System	IV/A	N/A	N/A
	Basement	Dagui- 1		
	<ul> <li>Ground/ upper floors.</li> </ul>	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants.	N/A	N/A	N/A
	Size of Riser/Down-comer	NI/A		
	Number of Hydrant per floor	N/A	100 mm	N/A
	Hose box.	N/A	One	N/A
12	Yard Hydrants.	N/A	One	N/A
	Total number of hydrants.	N//		
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	N/A	N/A	N/A
	Ground Level			
	<ul> <li>Discharge of main pump.</li> </ul>	N/A		
	Head of main pump.	N/A N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A N/A	N/A	N/A
	Jockey Pump head.		N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Tamp head.	N/A	N/A	N/A
	<ul><li>Auto Starting/Manual Stopping.</li><li>Pump house access.</li></ul>	N/A	N/A	N/A
	r ump nouse access.	N/A	N/A	N/A
	Terrace Level	N/A	N/A	N/A
	> Discharge of pump.	450 8 100		
	Head of pump.	450 & 180 LPM	Provided	MR
	Power supply.	35m	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	Required	Provided	MR
	Underground tank capacity.	NI/A		
	> Draw-off connection.	N/A	N/A	N/A
		N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	<ul> <li>Overhead tank capacity.</li> </ul>	5,000 Ltrs	Provided	MR
15	Exit Signage.	Required		(old case)
16	Provision of Lifts.	required	Provided	MR
	<ul> <li>Pressurization of lift shaft.</li> </ul>	N/A	27/4	
	<ul> <li>Pressurization of lift lobby</li> </ul>	N/A N/A	N/A	N/A
	<ul> <li>Communication in lift car.</li> </ul>	Required	N/A	N/A
		required	Provided	MR

N/A

Provided MR Required Fireman's switch. MR Provided Lift signage. Required MR Provided Required Standby Power Supply 17 18 Refuge Area N/A N/A N/A Total area N/A N/A N/A Location Fire Control Room. 19 N/A N/A N/A Detector system panel. N/A N/A N/A Flow switch panel. N/A N/A N/A PA system panel. N/A N/A N/A Battery backup. N/A N/A N/A Building floor plan.

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/NS/EH/2017/SZ/1583 dated 07/11/2017, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

N/A

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

Dy. CFO (\$Z)

20

MR

MR

MR

A DO/B()

As opporoved, F.T. Lettree is jouthy for your

synature P1.

[3/10/202]

Special Fire Protection System for the

Protection of special Risk, if any.

N/A