

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/WZ/2022/ 368

Dated: 30/12/22

## **FIRE SAFETY CERTIFICATE**

Certified that M/s. Tim Horton Restaurant (a unit of Apparel Gateway Café India Pvt. Ltd) running at Shop No. 20 &21, Ground Floor, P.P Tower, Plot No. C- 01, 02, 03, District Centre Wazirpur, NSP, New Delhi- 110034, owned/occupied by M/s. Tim Horton (a unit of Apparel Gateway Café India Pvt. Ltd). The premises was inspected by the officer concerned of this department on 22.12.2022 in the presence of Sh. Harshad Sharma, Project Manager and observed that the management have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- "Assembly" Group-D (Restaurant at Shop No. 20 &21, Ground Floor only) with effect from The Service Rules of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 30/12/22 at New Delhi by.

Copy to:-

- The Owner / Occupier, M/s. Tim Horton (a unit of Apparel Gateway Café India Pvt. Ltd) running at Shop No. 20 &21 .G.F, P.P Tower NSP, Plot No. C- 01, 02, 03, District Centre Wazirpur, New Delhi- 110034.
- 2. The Dy. Health Officer, MCD, Keshav Puram Zone, New Delhi.
- The Joint Commissioner of Police (Lic.), Police Station Defence Colony, First floor, New Delhi.

## Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (<a href="https://www.delehlhlic.gov.in">https://www.delehlhlic.gov.in</a>) along with a copy of this certificate, six months prior to its expiry.
- 8. This FSC is valid for the Restaurant at ground floor Shop No. 20 &21 only.

## INSPECTION REPORT

1. Name & address of the building : Tim Horton Restaurant (a unit of Apparel Gateway Café

India Pvt. Ltd), Shop No. 20 & 21-GF P.P Tower, NSP, Plot No. C- 01, 02, 03, District Centre Wazirpur, New Delhi-

2. Type of Occupancy 110034. : Assembly

3. Type of Case : New Case

Details of previous NOC : N/A
 Fire Safety directives Letter No. : N/A

6. Date of inspection : 22.12.2022

7. Name of the Inspecting Officer : M.K. Chattopadhyay, DO (West)

8. Name and designation of Officer

From the building side : Sh. Harshad Sharma, Project Manager

9. Year of Construction : 2002

10. Applicant's email date : Online ID- 2022113020902

The building is having two towers. Tower-A is comprised of Lower Ground, Upper Ground plus ten upper floors & Tower-B is comprised of Lower Ground, Upper Ground plus six upper floors. The restaurant is located at Tower-B.

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC/UBBL Requirements	Provided at site	Remarks MR/NMR		
1.	Access of building					
	Road width	12 mts	Provided	MR		
	<ul> <li>Gate width</li> </ul>	4.5 mts	Provided	MR		
	<ul> <li>Width of internal road</li> </ul>	06 mts	Provided	MR		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	<ul> <li>Upper floors</li> </ul>	NA	At ground floor	NA		
	<ul> <li>Basements</li> </ul>	NA	NA	NA		
	b. Width of staircases					
	Upper floors	NA	At ground floor	NA		
	• Basements	NA	NA	NA		
	D	NA	NA	NA		
	<ul> <li>c. Protection of exits</li> <li>Fire check door</li> <li>Pressurization</li> <li>d. No of continuous staircase to terrace</li> </ul>	NA NA	NA NA	NA NA		
		NA	NA	NA		
		NA	NA	NA		
	e. Width Of Corridor		Provided	MR		
	f. Door Size	1.5 m x 02 nos.	Provided	MK		
3.	Compartmentation					
,.	<ul> <li>Fire check door</li> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> <li>Fire Dampers</li> </ul>	NA	NA	NA		
		NA	NA	NA		
		NA	NA	NA		
		NA	NA	NA		
		NA	NA	NA		
	Smoke managements System	,				
•	Basements	NA	NA	NA		
	Upper floor	Required	Provided	MR		
	Fire Extinguishers		Duanidad	MR		
,.	Total numbers	04	Provided Provided	MR		
	1000	ABC, CO2 & WCO2	Provided	W		

	• Types	ISI marked	Provided	MR		
	IS marking  People					
	First - Aid Hose Reels	01	Provided	MR		
	Total numbers on each floor	30 m	Provided	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	5 mm	Provided	MR		
	Nozzle diameter     Nozzle diameter	stem				
7.	Nozzle dianteel  Automatic fire detection and alarming system  Smoke Provided MR					
	<ul> <li>Type of detectors</li> </ul>	Required	Provided	MR		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	Required	Provided	MR		
	<ul> <li>Location of Repeater Funds</li> <li>Alternate source of power</li> </ul>	_	Provided	MR		
	<ul><li>Alternate source of power</li><li>Hooters' Location</li></ul>	Required				
	MOEFA	Required	Provided	MR		
	Public Address System	NA	NA	NA		
)	Automatic Sprinkler System	NA	NA	NA		
	Basements	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	Required				
	Internal Hydrants	100 mm	Provided	MR		
	Size of riser/down- comer	01	Provided	MR		
	<ul> <li>Number of hydrants per floor</li> </ul>	01	Provided	MR		
	Hose Box	UI	Tiovided	1711		
	Yard Hydrants					
	<ul> <li>Total number of hydrants</li> </ul>	NA	NA	NA		
	Hose Box	NA	NA	NA		
3	Pumping Arrangements					
	Ground Level					
	<ul> <li>Discharge of main pump</li> </ul>	NA	NA	NA		
	Head of main pump	NA	NA	NA		
	Number of main pumps	NA	NA	NA		
	Jockey pump out put	NA	NA	NA		
	Jockey pump head	NA	NA	NA		
	Standby Pump out put	NA NA	NA	NA		
	> Standby Pump Head			NA NA		
	Auto Staring/Manual stopping	NA	NA			
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>	NA	NA	NA NA		
	<ul><li>Perrace level</li><li>Discharge of pump</li></ul>	NA	NA	NA		
	Head of the pump	450 LPM	Provided	MR		
	> Power supply	40 m	Provided	MR		
	Auto starting of pump	Required	Provided	MR		
		Required	Provided	MR		
14	Captive water Storage for fire fighting					
	Underground tank capacity	NA	NA	NA		
	> Draw of connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA	NA		
	Overhead Tank capacity	20,000 Ltrs	Provided	MR		
	Exit Signage	Required	Provided	MR		
6	Provision of Lifts					
		NA	NA	NA		
	Pressurization of Lift Shaft	NA NA	NA NA	NA		
	<ul> <li>Pressurization of lift lobby</li> </ul>	NA NA	NA NA	NA		
	Communication in lift Car	I INA	144 F	1 2.22		

(A)	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>	NA	NA	NA
7				
17	Standby power supply	NA	NA	NA
18	Refuge Area			
	➤ Total area	NA	NA	NA
	> Location	NA	NA	NA
19	Fire control room			
	Detector system panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	<ul> <li>Building Floor Plans</li> </ul>	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were test checked at the time of inspection and found functional.

Note:- The P.P.Tower building have no valid fire safety certificate. The Restaurant management has provided separate fire fighting system required as per Law.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name: M.K. Chattopadhyay

Designation: DO (West Division)

Deto (wr)

26 2 20n

Director MADIOL

ETPS

Mml signatur 61.

red