

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE : NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/SZ/2023/ O2

Dated: 03 / 0 / /2023

FIRE SAFETY CERTIFICATE

Certified that Motel Building Block No. 1, FAH located at Khasra Nos. 372, 374 & 375 Village Mailkpur, Kohi Alias, Rangpuri, New Delhi-110038 comprised of Basement (storage) and Ground floor (Hall) owned/occupied by A Unit of Food Art Hospitality Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 26/12/2022 in the presence of Mr. Anil Kumar Verma and that the premise is fit for occupancy class Group-A Residential Building (Motel) with effect from 62/01/2023 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03 / 0) /2023 at New Delhi by

(ATUL GARG)
DIRECTOR

Copy to: -

1. The Addl. Commissioner of Police (Lic/Branch) First Floor, PS Defence Colony, New Delhi- 110049 (Ref. MHA Portal ID 2022071114416 dated 22/07/2022)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



INSPECTION REPORT Name & address of the building

: Motel Building Block No. 1, FAH (Unit of Food Art Hospitality

Pvt Ltd) Khasra Nos. 372, 374 & 375 Village Mailkpur, Kohi Alias,

Rangpuri, New Delhi-110038

2. Type of Occupancy Type of Case 3.

: Group A "Residential" (Motel Building) [Basement + G. Floor]

: New Case

4. Details of Previous NOC : Nil

5. Fire Safety directives letter No : F6/DFS/GH/2000/1445 Dated 22/08/2000

6. Date of inspection 7. Name of Inspecting Officer

: 26/12/2022

8. Name and designation of officers

: DO (South) & ADO (BCP)

From the building side

: Mr. Anil Kumar Verma


Year of Construct

). 0. 7	Year of Construction : 2010 Applicant's letter No : MHA Portal						
S.	Minimum Standards - S		6 dated 22/07/2022				
No.	Minimum Standards on fire prevention and fire safety U/R 33	Directive Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building	Requirement		WIR/NWIR			
	• Road width	12m	Provided	MR			
	Gate width	5m	Provided	MR			
	Width of internal road	NA	NA	NA			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	• Upper Floors	-NA-	-NA-	-NA-			
	Basements	03 Nos	Provided	MR			
	b. Width of staircases						
	Upper Floor	-NA-	-NA-	-NA-			
	Basements	1.50m/2m	02 mtr each	MR			
	c. Protection of exits						
	Fire check door	-NA-	-NA-	-NA-			
	Pressurization	-NA-	-NA-	-NA-			
	d. No. of continuous staircases to terrace	Required	One	MR			
	e. Width of Corridor	-NA-	-NA-	-NA-			
	f. Door Size	2m	2m (Final Exit)	MR			
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Provided	MR			
	Fire Rating of shaft door	-NA-	-NA-	-NA-			
	Water Curtain	-NA-					
	Fire Dampers	-NA-	-NA- -NA-	-NA-			
1.	Smoke Management System	-147-	-INA-	-NA-			
•.	Basements	30 ACPH	Exhaust Fans	MR			
	Upper floors	12 ACPH	-NA-	-NA-			
	Fire Extinguishers			-14/1-			
5	• Total numbers	26	Provided	MR			
	Types	ABC/W.Co ₂ /Co ₂	10/10/06 Nos	MR			
	IS marking	ISI	Yes				
	First-Aid Hose Reels		1 08	MR			
6.	Total numbers on each floor	Required	2 Nos	MR			
	Length of hose reel hose	30m	Provided	MR			
	Nozzle diameter	5mm	Provided	MR			
_	Automatic fire detection and alarming system	<u> </u>	TTOVIGOU	IVIK			
7.	Type of detectors	Smoke & Heat	Provided	MR			
	Location of Main Panel	Required	Ground Floor	MR			
	Location of Repeater Panel	-NA-					
	Alternate source of power		-NA-	MR			
		Required	Provided	MR			

अमृत्यादीः साजादीः

			-31	मृत् गहोल
3.		Required	All Floors	MR
		Required	Provided	MR
0.	Automotic Serial I	Required	Provided	MR
10.				
		Required	Provided	MR
	Basement Upper Floors Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer Number of hydrants per floor Hose Box Total number of hydrants Hose Box Pumping Arrangements Ground Level Discharge of main Pump Head of Main pump Number of main pump Nu	Required	Provided	MR
1.	Internal Hydronts	-NA-	-NA-	-NA-
-				1
	Number of hydroxic	150mm	Provided	MR
	Hose Box	Required	2 Nos	MR
2.		Required	2 Nos	MR
	Hose Description	Required	4 Nos	MR
3.		Required	4 Nos	MR
_				-
	Discharge of main Pump	2280 LPM	2280 LPM	MR
		70m	70m	MR
	Number of main pumps	One	One	MR
		180 LPM	PM 180 LPM	MR
		70m	70m	MR
	Standby Pump out put	2280 LPM	2280 LPM	MR
		70m	70m	
		Required		MR
	Pump House Access	-	Provided	MR
	A Terrage level	Required	Provided	MR
		900 LPM	000 1 DM	
		35m	900 LPM 35m	MR MR
	➢ Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
		1,00,000 Lts	Provided	MD
		Required	Provided	MR
	Draw-off connection	Required	Provided	MR
		Required		MR
	I	25,000 Lts	Provided 25,000 Lts	MR MR
15				
		Required	Provided	MR
10.		,		
		Required	Provided	MR
		Required	Provided	MR
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	- Ditt Digitage	-NA-	-NA-	-NA-
17.	Standby power supply	Required	Provided	MR
18.				
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
19.	Fire Control Room		The second secon	
	Detector System Panel	-NA-	-NA-	-NA-
	Flow Switch Panel	-NA-	-NA-	-NA-
	PA System Panel	-NA-	-NA-	-NA-
		1111		-





			. To allow
Battery backup	-NA-	-NA-	-NA-
Building Floor Plans	-NA-	-NA-	-NA-
Special Fire Protection System for Protection of special Risks, if any:			-NA-

Motel Building Block No. 1, FAH (Unit of Food Art Hospitality Pvt Ltd) Khasra Nos. 372, 374 & 375 Village Mailkpur, Kohi Alias, Rangpuri, New Delhi-110038

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

mello

Signature of the Inspection Officer

Name: Sh. Manoj Sharma Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

Dy. CFO (SZ)

Anu DOP