## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/EH/WZ/ 03

Dated: 03 / 01 / 2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s Spice Era (A unit of Yadav Enterprises) Unit No.GA- 4 & 5 ground floor, Metro Walk Mall, Sector-10, Rohini, Delhi-85, is running at ground floor in a mall building comprised of AB & C blocks, Basement + Ground + one upper floor & D Block Basement + ground floor has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/2013/275 dated 20.02.2013. The premises was re-inspected by the officer concerned of this department on 08.12.2022 in the presence of Mr. Deepak Kumar and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group D "Assembly"(Eating House) for Unit No.GA- 4 & 5 ground floor with effect from  $D \le \sqrt{91}/2 \le 23$  for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

1/2023

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

olc

## Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- The owner/ occupier shall submit a declaration every year in Form 'K'[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms">http://delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms</a>
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

|              |   | 1  |                |             |  |  |  |
|--------------|---|--|----------------|-------------|--|--|--|
|              | ~   |  |                |             |  |  |  |
|              |   |  |                |             |  |  |  |
|              | Name & address of the building Misser   | ON REPORT                                    |                |             |  |  |  |
|              | Name & address of the building : M/s Spice E  | Era (A unit of Yadav Enterp                  | rises) Unit No | .GA-4&5     |  |  |  |
| 2            | Type of Occupancy Assembly  | or, Metro Walk Mall, Sector<br>Eating House) | -10, Rohini, D | elhi-85.    |  |  |  |
| 3.           | Datails of Brazila NOG  |  |                |             |  |  |  |
| 4.           | Fire Safety dimention 1 1.0/DFS/M   | S/EH/2013/725 dated 20.02                    | .2013.         |             |  |  |  |
| 6.           | Data af incentives letter No : NBC Part IV  | 1  |                |             |  |  |  |
| 7.           | Name of Inspecting Officer  |  |                |             |  |  |  |
| 8.           | Name and designation of officers  | ADO(Konini)                                  |                |             |  |  |  |
| 0            | From the building side : Ms. Deepak   | Kumar  |                |             |  |  |  |
| - 9.<br>- 10 | real of Construction .  |  |                |             |  |  |  |
| . No.        | Applicant's letter No. : Online application no.2022111620287 dated 21.11.2022.            |  |                |             |  |  |  |
|              | Minimum Standards on fire prevention<br>and fire safety U/R 33                            | NBC Requirement                              | Provided       | Remarks     |  |  |  |
|              |   | Rule 35 (6)                                  | at site        | MR/NMR      |  |  |  |
| •            | Access to building [Amusement Park Ad   | lventure island metro wa                     | lk issued FS   | C vide lett |  |  |  |
|              | No.F.6/DFS/MS/WZ/2022/427 dated 22.11.2<br>• Road width                                   | 2020]  |                |             |  |  |  |
|              | <ul> <li>Gate width</li> </ul>  |  |                |             |  |  |  |
|              | <ul><li>Width of internal road</li></ul>  | Restaurant within Mall                       | As Above       | MR          |  |  |  |
|              |   |  | 115 110010     |             |  |  |  |
| •            | Number, Width, Type & Arrangement of Exits  |  |                |             |  |  |  |
|              | a. Number of staircases   |  |                |             |  |  |  |
|              | Upper Floors  | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | • Basements   | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | b. Width of staircases  |  |                |             |  |  |  |
|              | • Upper Floor   | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | • Basements   | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | c. Protection of exits  |  |                |             |  |  |  |
|              | Fire check door   | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | Pressurization  | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | <ul><li>d. No. of continuous staircases to terrace</li><li>e. Width of Corridor</li></ul> | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | e. Width of Corridor<br>f. Door Size  | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              |   | Required                                     | Provided       | MR          |  |  |  |
| 3.           | Compartmentation  |  |                |             |  |  |  |
|              | Fire check door   | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | Sealing of electrical shafts  | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | <ul><li>Fire Rating of shaft door</li><li>Water Curtain</li></ul>                         | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | <ul> <li>Fire Dampers</li> </ul>  | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              |   | Restaurant within mall                       | As Above       | MR          |  |  |  |
| 4.           | Smoke Management System   | D  | A _ A 1        |             |  |  |  |
|              | <ul> <li>Basements</li> </ul>   | Restaurant within mall                       | As Above       | MR          |  |  |  |
|              | • Upper floors  | Restaurant within mall                       | As Above       | MR          |  |  |  |
| •            | Fire Extinguishers  |  |                |             |  |  |  |
| •            | Total numbers   | One " 300m2                                  | 08nos.         | MR          |  |  |  |
|              | • Types   | ABC/CO2                                      | ABC/CO2        | MR          |  |  |  |
|              | IS marking  | ISI marked                                   | Yes            | MR          |  |  |  |
| 6.           | First-Aid Hose Reels  |  |                |             |  |  |  |
|              | <ul> <li>Total numbers on each floor</li> </ul>   | 01 near to restaurant                        | As Above       | MR          |  |  |  |
|              | <ul> <li>Length of hose reel hose</li> </ul>  | 30mm   | As Above       | MR          |  |  |  |
|              | <ul> <li>Nozzle diameter</li> </ul>   | 5m   | As Above       | MR          |  |  |  |
| •            | Automatic fire detection and alarming system  | m  |                |             |  |  |  |
| •            | Type of detectors   | Required                                     | Provided       | MR          |  |  |  |
|              | <ul> <li>Location of Main Panel</li> </ul>  | NA   | As Above       | NA          |  |  |  |

|           |  | N/2                      |                      | 27       |  |  |
|-----------|--|--------------------------|----------------------|----------|--|--|
|           | • Logiting (D  | 1                        |                      |          |  |  |
|           | <ul><li>Location of Repeater Panel</li><li>Alternate source of power</li></ul>         | NA                       | As Above             | <u> </u> |  |  |
|           | <ul> <li>Hooters' Location</li> </ul>  | NA                       | As Above             |          |  |  |
| 8.        | MOEFA  | NA                       | As Above             | X        |  |  |
| 8.<br>9.  |  | Required                 | Provided             | N        |  |  |
| 9.<br>10. | Public Address System  | Dami' 1                  |                      | MIQ.     |  |  |
| 10.       | Automatic Sprinkler System[Provided & Mai  | intained by Mall managem | ent]                 | MR       |  |  |
|           | Basement   | NA                       | As Above             | T        |  |  |
|           | Ground & Upper Floors     Sprinklar above 6 1  | NA                       | As Above             | NA       |  |  |
|           | Sprinkler above false ceiling  | NA                       | As Above<br>As Above | NA       |  |  |
| 11.       | Internal Hydrants[Provided & Maintained by   | Mall management]         | AS ADOVE             | NA       |  |  |
|           | <ul> <li>Size of riser/down-comer</li> </ul>   | 100mm                    | 4 41                 |          |  |  |
|           | <ul> <li>Number of hydrants per floor</li> </ul>                                       | One(near to Restaurant)  | As Above             | MR       |  |  |
|           | • Hose Box   | One(near to Postaurout)  | As Above             | MR       |  |  |
| 12.       | Yard Hydrants[Provided & Maintained by Ma  |                          | As Above             | MR       |  |  |
|           | Total number of hydrants   |                          |                      |          |  |  |
|           | <ul> <li>Hose Box</li> </ul>   | Restaurant within mall   | As Above             | MR       |  |  |
| 13.       |  | Restaurant within mall   | As Above             | MR       |  |  |
|           | <ul> <li>Pumping Arrangements[Provided &amp; Maintain</li> <li>Ground Level</li> </ul> | ned by Mall management]  |                      |          |  |  |
|           |  | Restaurant within mall   | As Above             | MR       |  |  |
|           |  | Restaurant within mall   | As Above             | MR       |  |  |
|           | <ul> <li>Head of Main pump</li> <li>Number of main</li> </ul>                          | Restaurant within mall   | As Above             | MR       |  |  |
|           | Number of main pumps   | Restaurant within mall   | As Above             | MR       |  |  |
|           | Jockey Pump out put  | Restaurant within mall   | As Above             | MR       |  |  |
|           | <ul> <li>Jockey pump head</li> <li>Standlar D</li> </ul>                               | Restaurant within mall   | As Above             | MR       |  |  |
|           | Standby Pump out put   | Restaurant within mall   | As Above             | MR       |  |  |
|           | Standby Pump Head  | Restaurant within mall   | As Above             | MR       |  |  |
|           | Auto Starting/Manual Stopping  | Restaurant within mall   | As Above<br>As Above | MR       |  |  |
|           | Pump House Access  | Restaurant within mall   | As Above<br>As Above |          |  |  |
|           | T I I  |                          |                      | MR       |  |  |
|           | <ul> <li>Terrace level</li> <li>Discharge of pump</li> </ul>                           | [Provided & Maintaine    |                      | _        |  |  |
|           | <ul> <li>Discharge of pump</li> <li>Head of the pump</li> </ul>                        | NA                       | As Above             | MR       |  |  |
|           | <ul> <li>Power Supply</li> </ul>   | NA                       | As Above             | MR       |  |  |
|           | <ul> <li>Auto Starting of pump</li> </ul>  | Required                 | As Above             | MR       |  |  |
| 14.       |  | Required                 | As Above             | MR       |  |  |
| 14.       | Captive Water Storage for fire fighting [Prov  |                          |                      |          |  |  |
|           | Underground tank capacity  | Restaurant within mall   | As Above             | MR       |  |  |
|           | <ul> <li>Draw-off connection</li> <li>Fire service inlet</li> </ul>                    | Restaurant within mall   | As Above             | MR       |  |  |
|           | <ul> <li>Fire service inlet</li> <li>Access to tank</li> </ul>                         | Restaurant within mall   | As Above             | MR       |  |  |
|           | <ul> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>                     | Restaurant within mall   | As Above             | MR       |  |  |
|           | • Overhead Fairs capacity  | Restaurant within mall   | As Above             | MR       |  |  |
| 15.       | Exit Signage.  | Required                 | Provided             | MR       |  |  |
| 16.       | Provision of Lifts. [Provided & Maintained by Mall management]                         |                          |                      |          |  |  |
|           | Pressurization of Lift Shaft   | NA                       | NA                   | NIA      |  |  |
|           | <ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> </ul> |                          | NA                   | NA       |  |  |
|           | Communication In lift Car  | NA                       | NA                   | NA       |  |  |
|           | <ul> <li>Fireman's Grounding Switch</li> </ul>   | NA                       | NA                   | NA       |  |  |
|           | <ul> <li>Lift Signage</li> </ul>   | NA                       | NA                   | NA       |  |  |
|           |  | NA                       | NA                   | NA       |  |  |
| 17.       | Standby power supply   | NA                       | NA                   | NA       |  |  |
| 18.       | Refuge Area. [Provided & Maintained by Mall  | management]              |                      |          |  |  |
|           | Total Area   | NA                       | NA                   | NA       |  |  |
|           | Location   | NA                       | NA                   | NA       |  |  |
| 19.       | Fire Control Room[Provided & Maintained by   |                          |                      |          |  |  |
|           | Detector System Panel  | NA NA                    | NA                   | NA       |  |  |
|           | <ul> <li>Flow Switch Panel</li> </ul>  | NA                       | NA                   | NA       |  |  |
|           |  | INA                      |                      |          |  |  |

|  | 4/3 |    |    |
|--|-----|----|----|
| PA System Panel  | NA  | NA | NA |
| <ul> <li>Battery backup</li> </ul>   | NA  | NΛ | NA |
| <ul> <li>Building Floor Plans</li> </ul>                                   | NA  | NA | NA |
| Special Fire Protection System for<br>Protection of special Risks, if any: | NA  | NA | NA |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. **F.6/DFS/MS/EH/2013/725 dated 20.02.2013** is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

12mm

Signature of the Inspecting Officer Name Ajay Kumar Sharma Designation ADO(Rohini)

27/12/7 DO (NW) ردس م Aver Rohini Fi letter is put up for kind perual and Synchrighte DEFOILM, Mist leg upload a