

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

No.F.6/DFS/MS/School/2023/SZ

FIRE SAFETY CERTIFICATE

Certified that the S.D.M.C Primary Pratibha Vidyalaya, Kanganheri, New Delhi-110071, comprised of two blocks namely Old Block having Ground floor plus one upper floor & New Block having ground floor only, owned/occupied by S.D.M.C was issued FSC by this department vide letter no. F.6/DFS/MS/School/2020/SZ/39 dated 31/01/2020. The school building was re-inspected by the officer concerned of this department on 06/03/2023 in the presence of Sh. Neeraj Yadav (Incharge) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions, printed as under.

Issued on 17/03/2023 at New Delhi.

DIRECTOR **DELHI FIRE SERVICE**

Copy to:-

- The Principal, 1. S.D.M.C Primary Pratibha Vidyalaya, Kanganheri, New Delhi-110071
- 2. Director of Education, S.D.M.C, Civic Centre, Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

INSPECTION REPORT 1. Name & address of the building: S.D.M.C Primary Pratibha Vidyalaya, Kanganheri, New Delhi-110071 Building comprised of Two Blocks namely Old Blk (G+1) & New Blk (Ground floor only) 2. 3. Type of Occupancy Educational Type of Case Renewal 5. Details of Previous NOC F.6/DFS/MS/School/2020/SZ/39 dated 31/01/2020 6. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 7. Date of inspection 06/03/2023 8. Name of Inspecting Officer A.D.O. R.K. Yadav 9. Name and designation of officers From the building side Sh. Neeraj Yadav (Incharge) 10. Year of Construction 2010 (Old Block) & 2019 (New Block) 11. Applicant's letter No. Nil dated 24/02/2023 Minimum Standards on fire prevention and Dir. Of Edu. S. No. Provided at Remarks Circular dt. fire safety U/R 33 site MR/NMR 01.03.2011 Requirement Access to building Accessible 06 m Road width Provided MR Gate width N/A N/A N/A Width of internal road N/A N/A N/A Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 No.'s in OB Provided MR Basements N/A N/A N/A b. Width of staircases Upper Floor 1.50 & .75 m 1.50 & 1.18 m MR Basements N/A N/A N/A c. Protection of exits Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace Width of Corridor N/A N/A N/A 1.0 m 1.18 m (double doors) in MR Class room Door Size OB & 1.14m (double doors) in NB 3. Compartmentation N/A Fire check door N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System Basements N/A N/A N/A Upper floors Required Natural ventilation M/R provided 5. Fire Extinguishers Total numbers 06 no's Provided M/R ABC/CO₂ type Types Provided M/R IS marking Provided M/R ISI marked First-Aid Hose Reels Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter N/A

1.

2.

N/A

N/A

	Automatic fire detection and alarming system	N/A	N/A	N/A	
1	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel SP Panel Panel	N/A		N/A	
	Location of Repeater Panel	N/A	N/A N/A	N/A	
	Alternate source of powerHooters' Location	N/A	N/A N/A	N/A	
× 7		N/A	N/A N/A	N/A	
7	MOEFA	N/A N/A	N/A	N/A	
	Public Address System	IV/A	14/11	1,711	
).	Automatic Sprinkler System	N/A	N/A	N/A	
	BasementGround Floor	N/A	N/A	N/A	
	 Ground Floor Sprinkler above false ceiling 	N/A	N/A	N/A	
	Internal Hydrants				
1	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
2.	Yard Hydrants				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
3.	Pumping Arrangements				
	Ground Level		2000		
	Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A	
	Jockey Pump out putJockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/Manual Stopping	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
	> Pump House Access	370092			
	 Terrace level Discharge of pump 	N/A	N/A	N/A	
	> Head of the pump	N/A	N/A	N/A	
	> Power Supply	N/A	N/A	N/A	
	➤ Auto Starting of pump	N/A	N/A	N/A	
14.	Captive Water Storage for fire fighting				
14.	Underground tank capacity	N/A	N/A	N/A	
	> Draw-off connection	N/A	N/A	N/A	
	> Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	N/A	N/A	N/A	
15.	Exit Signage.	N/A	N/A	N/A	
16.			No Li	No Lift	
10.	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	 Communication In lift Car 	N/A	N/A	N/A	
	 Fireman's Grounding Switch 	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
		N/A	N/A	N/A	
17.	Standby power supply	14/74			
18.	Refuge Area.	21/4	N/A	N/A	
10.	> Total Area	N/A	1. 3		
	> Location	27/4	N/A	N/A	
	> Location	N/A	IN/A	1,1,1	

	,	
N/A	N/A	N/A
	N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A N/A N/A N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2020/SZ/39 dated 31/01/2020 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer Divisional Officer (South West)